STANDARD BOLT FOR AUTOMATIC TRANSAXLE REPAIR MANUAL

HOW TO DETERMINE NUT STRENGTH

		Nut	Туре				
Present Standard Old Standard Hexagon Nut						Class	
Hexagon Nut		Cold Forging Nut		Cutting Processed Nut			
No Mark						4N	
No Mark (w/ Washer)		No Mark (w/ Washer)		No Mark		5N (4T)	
						6N	
				*		7N (5T)	
(SN)						8N	
(10N)				No Mark		10N (7T)	
(11N)						11N	
						12N	

^{*:} Nut with 1 or more marks on one side surface of the nut.

HINT:

B06432

Use the nut with the same number of the nut strength classification or the greater than the bolt strength classification number when tightening parts with a bolt and nut.

Example: Bolt = 4T

Nut = 4N or more

U140E,U140F A/T REPAIR MANUAL (RM836U)

0103G-01