055VB-03

PROBLEM SYMPTOMS TABLE

NOTICE:

Confirm the problem symptom and make an inspection depending on the applicable flowchart.

Problem Symptom	Suspected Area	See Page
69 (No communication from theft deterrent ECU	Theft warning ECU (theft deterrent ECU)	05–2157
more than 10 seconds.)	2. Wire harness	05–2157