
## ROCKER PANEL MOULDING LH REPLACEMENT

760BW-03



## 1. REMOVE ROCKER PANEL MOULDING LH

- (a) Remove the 6 screws.
- (b) Using a screwdriver, remove the rocker panel moulding. HINT:

Tape the screwdriver tip before use.