

RightShip Ship Inspection Program

List of Findings

RightShip Ship Inspection Report - 71449

A general cargo ship that is carrying general cargo and/or container cargo

Vessel Name:	MANTA MERVE
IMO Number:	9597678
DOC Company:	Manta Denizcilik Nakliyat ve Ticaret Ltd Sti
Place of Inspection:	Bahrain, Khalifa Bin Salman
Name of Inspector:	Altaf Kapdi
Inspection Completion Date:	2/25/2026 12:00:00 AM
Operational Variant:	

This is a list of Findings made during my inspection of your vessel, completed today. As the scope and scale of the inspection has been limited by time and operational constraints, this does not necessarily constitute a comprehensive list of all Findings on board.

A copy of this list together with a detailed inspection report will be submitted to RightShip, who will liaise directly with your owners / managers in due course. The following Findings should not be considered as a final or comprehensive list and RightShip reserves the right to add to or amend these Findings. If RightShip adds to or amends the list of Findings, they will advise the owner/ship's manager.

When RightShip reviews the inspection report, the vessel's manager and Master will be given the opportunity to provide comments and response to each Finding on the list.

This list of Findings does not constitute any warranty of the fitness or suitability of the vessel. Thank you for the cooperation and hospitality accorded to me by yourself and your crew.

DISCLAIMER

THIS DOCUMENT AND THE CONTENTS HEREOF ARE PREPARED SOLELY FOR RIGHTSHIP'S CUSTOMER IN RESPECT OF THE VESSEL(S) NAMED FOR RIGHTSHIP INSPECTION AND ARE NOT INTENDED FOR ANY THIRD PARTY TO ACCESS, USE, RELY ON OR DISTRIBUTE WITHOUT RIGHTSHIP'S EXPLICIT WRITTEN CONSENT. NOTWITHSTANDING ANY CONSENT THAT MAY HAVE BEEN GIVEN BY RIGHTSHIP AS AFOREMENTIONED, RIGHTSHIP SHALL HAVE NO LIABILITY WHATSOEVER AND HOWSOEVER ARISING TO ANY SUCH PERSON OR ENTITY, OR THIRD PARTY RECIPIENT, WHETHER IN CONTRACT, TORT OR OTHERWISE.

IF, IN RELIANCE OF THIS DOCUMENT, YOU ELECT TO CHARTER ANY VESSEL OR MAKE ANY COMMERCIAL OR OTHER DELIBERATIONS IN CONNECTION WITH IT, YOU DO SO AT YOUR OWN RISK AND YOU MUST MAKE YOUR OWN ASSESSMENT AND SATISFY YOURSELF AS TO THE ACCURACY AND COMPLETENESS OF THE INFORMATION CONTAINED IN THIS DOCUMENT. RIGHTSHIP PROVIDE NO WARRANTY AS TO THE SAFETY OR QUALITY OF THAT VESSEL, ITS FITNESS FOR ANY PURPOSE, OR ANY OTHER FINDINGS ABOUT IT AND RIGHTSHIP DO NOT ACCEPT RESPONSIBILITY OR LIABILITY FOR ANY INCOMPLETENESS OR INACCURACIES IN THE INFORMATION CONTAINED IN THIS DOCUMENT THAT MAY INCLUDE UNVERIFIABLE INFORMATION OF CUSTOMER AND/OR THIRD PARTIES.

THIS DOCUMENT CONTAINS CONFIDENTIAL AND/OR LEGALLY PRIVILEGED INFORMATION AND IS SUBJECT TO THE INTELLECTUAL PROPERTY RIGHTS AND OTHER PROPRIETARY RIGHTS OF RIGHTSHIP AND/OR ITS LICENSORS. UNAUTHORISED ACCESS, USE OR DISTRIBUTION OF THIS DOCUMENT OR ANY CONTENTS HEREOF CONSTITUTES BREACH OF OBLIGATION OF CONFIDENCE TO AND/OR INFRINGEMENT OF INTELLECTUAL PROPERTY AND OTHER PROPRIETARY RIGHTS OF RIGHTSHIP AND/OR ITS LICENSORS, WHICH MAY RESULT IN LEGAL ACTION TAKEN AGAINST YOU. FOR MORE INFORMATION ABOUT THE RIGHTS AND OBLIGATIONS OF RIGHTSHIP'S INSPECTION CUSTOMERS, PLEASE REFER TO TERMS AND CONDITIONS GOVERNING RIGHTSTORE, COPY OF WHICH MAY BE ACCESSED ON RIGHTSTORE OR SUCH OTHER PORTAL ON WHICH RIGHTSHIP MAY CHOOSE TO PUBLISH.

Number of Findings: 5

Section 2: Certification and Personal Management

2.13 Is the officer matrix accurately completed and does it reflect the information on officers and engineers on board the vessel at the time of inspection?

Findings: The updated crew matrix uploaded to the RightShip portal contained the following discrepancies:

1) The Master and Chief Engineer were not in a position to present up-to-date authenticated supporting documents of their rank experiences to verify against the data contained in the matrix posted in the RightShip Portal. 2) The Chief Officer's Sea service in rank was recorded as 1 years, whereas actual sea service in his rank was 9 months.

Attachments:

[Q213_76bd47ba-9626-4caa-b016-4349ba8708f5.pdf](#)

Section 3: Navigation

3.19 Is the ECDIS of an approved type and does it meet the SOLAS requirement?

Findings: The officer on watch on the bridge was interviewed to assess his familiarity with ECDIS operations; however, he was unable to demonstrate or confirm the version of the presentation library currently in use in the ECDIS on board.

Section 4: ISM System

4.32 Are records available to show that Emergency Escape Breathing Devices (EEBDs) in the accommodation and engine room are being inspected, in good condition and are available for instant use?

Findings: One EEBD unit located at the upper deck fire station, as indicated in the LSA/FFA plan, was found with a pressure reading of 0 bar against the required full-charge pressure of 200 bar. It was reported that the unit was subsequently recharged to the required pressure in accordance with the manufacturer's guidelines during the inspection.

Section 7A: Fuel Management (Oil)

7A.7 Are bunkering and oil fuel transfer procedures carefully planned and executed in accordance with industry standards, are the details of the last operation in accordance with industry standards, is the vessel equipped with a procedure for sampling the oil fuel used on board, and are bunker samples stored in a sheltered location?

Findings: The company policy stipulates that bunker samples were to be disposed of after a one-year retention period. However, during a random check, a bunker sample dated March 17, 2024 was observed in the designated storage area, indicating that samples exceeding the prescribed retention period were still being retained on board.

Section 14: General Appearance - Hull and Superstructure

14.10 Are portable and fixed cargo lights used for illumination of cargo holds inspected regularly and maintained in good condition? (V)

Findings: Six cargo lights on board were observed without protective glass covers and conductive drip shields.

Vessel's Master Name


ATIL ALPAN

Vessel's Master Email Address

mantamerve@fleetmail.inmarsat.com

- ☒ By signing the list of Findings, I confirm a closing meeting has taken place and the inspector has informed me that, where not already transmitted, the list of Findings will be sent via internet email once connectivity is restored.

Vessel's Master Signature:

A handwritten signature in black ink, consisting of a large loop followed by a series of smaller, connected loops and a final upward stroke, written over a horizontal line.

Inspector Name

Altat Kapdi

Inspector's Signature:

A handwritten signature in black ink, featuring a dense, scribbled pattern of loops and lines, written over a horizontal line.

CONTACT US

If you're interested and would like to know more, get in touch with our team today.

 www.rightship.com

 dryinspections@rightship.com

 RightShip

MELBOURNE

 Level 8/ 550 Bourke Street,
Melbourne VIC 3000,
Australia

 +61 3 8686 5750

LONDON

 4th Floor, 6 Dowgate Hill,
London EC4R 2SU, United
Kingdom

 +44 203 872 5900

SINGAPORE

 20 Cecil Street, PLUS,
#13-06
Singapore 049705

 +65 3138 3855

HOUSTON

 Suite 140 14141
Southwest Freeway,
Sugar Land TX 77478,
United States of America

 +1 832 770 8200

MALTA

 The Tower, 3rd Floor,
Fortunato Mizzi Street,
Ir-Rabat Għawdex
VCT 2517, Malta