

Property Inspection Report

Claim Number	CLM-2026-08421
Inspection Date	August 14, 2026
Inspector	Maria Lopez - Field Property Inspector
Property	1847 Willow Bend Drive, Austin, TX 78745

Areas Inspected

Kitchen sink base cabinet, adjacent lower cabinets, visible kitchen flooring near the sink, and accessible lower drywall at the cabinet perimeter.

Observed Conditions

Visible water-related damage was present in the sink base cabinet and adjacent finish materials. Portions of the cabinet base showed swelling and discoloration. Flooring near the sink showed localized edge swelling. Lower drywall adjacent to the cabinet area showed staining.

Some discoloration and material deterioration appeared more developed than would typically be expected from a very recent brief wetting event; however, visual inspection alone cannot establish the exact age or duration of moisture exposure.

Source / Cause

No active leak was observed during the inspection because the affected under-sink water supply had been shut off. Based on the available conditions, the exact failed component and the relationship, if any, between the current damage and prior plumbing activity could not be confirmed.

Recommended Follow-Up

Obtain prior plumbing service records, mitigation documentation, photographs taken at discovery, and any plumber findings identifying the component associated with the August event.