

Property Repair History - Plumbing Work Order

Service Provider	Lone Star Residential Plumbing
Customer	Daniel Carter
Service Address	1847 Willow Bend Drive, Austin, TX 78745
Service Date	June 3, 2026
Work Order	LSRP-60326-118

Customer Complaint

Customer reported moisture and intermittent dripping inside the cabinet beneath the kitchen sink. Customer requested inspection of plumbing connections in the sink base cabinet.

Technician Observations

Technician observed active moisture beneath the kitchen sink and evidence of leakage near the cold-water supply connection. The cabinet base was damp at the time of service. No wall cavity inspection or flooring removal was performed.

Work Performed

Technician tightened the affected connection and replaced a worn sealing component. Water was run at the fixture after the repair and no active dripping was observed during the service visit.

Service Notes

Customer was advised to monitor the area for additional moisture and to contact the company if leakage returned. This work order does not establish whether later water damage, if any, arose from the same source.