# TRAXNYC box · artwork · top · tooling + gold foil

full size.  magenta cuts, grey is tooling, gold is foil




*magenta solid = trim.  magenta dashed = 3 mm bleed on the wrap.*
*grey = blind deboss and cap: line 7 in, stopping 20.9 from each corner where the R22 cap meets it; stud ø3.5 at 9, 9.*
*the line never crosses the cap and the cap never crosses the line.*
*nothing grey is printed or foiled; it is tooling only.*

# TRAXNYC box · artwork · front · tooling

full size.  magenta cuts, grey is tooling, gold is foil




*magenta solid = trim.  magenta dashed = 3 mm bleed on the wrap.*
*grey = blind deboss and cap: line 7 in, stopping 20.9 from each corner where the R22 cap meets it; stud ø3.5 at 9, 9.*
*the line never crosses the cap and the cap never crosses the line.*
*nothing grey is printed or foiled; it is tooling only.*

# TRAXNYC box · artwork · end · tooling

full size.  magenta cuts, grey is tooling, gold is foil




*magenta solid = trim.  magenta dashed = 3 mm bleed on the wrap.*
*grey = blind deboss and cap: line 7 in, stopping 20.9 from each corner where the R22 cap meets it; stud ø3.5 at 9, 9.*
*the line never crosses the cap and the cap never crosses the line.*
*nothing grey is printed or foiled; it is tooling only.*