PT DAIKIN APPLIED SOLUTIONS INDONESIA

EPL CONNECT
VALUE ENGINEERING SERVICES

CORRECTIVE MAINTENANCE REPORT

CR-undefined

01 - UNIT & PERSONNEL INFORMATION

Customer / Project	-	**Service Date**	29/3/2026
Unit Model	HCCA 18	**SO / WO Number**	-
Unit Tag Number	DKN-850237	**Location Area**	-
Technician / Engineer	-	**Visit Count**	1

02 - CUSTOMER REPRESENTATIVE (PIC)

PIC Name	-	**Department**	-
Phone / WA	-	**Email**	-

03 - ANALYSIS & CORRECTIVE ACTION

CASE / COMPLAINT

-

ROOT CAUSE ANALYSIS

Hasil pengecekan kebocoran berasal dari condensasi pipa chiller

TEMPORARY ACTION

Sudah di keringkan dan di lakukan pemakuman

PERMANENT ACTION

-

RECOMMENDATION

Perbaikan isolasi pipa chiller

04 - ADDITIONAL ENGINEER NOTES

-

SERVICE ENGINEER	ACKNOWLEDGED BY (PIC)	APPROVED BY (MANAGER)
Name: -	Name: -	Name: _____
Date: 29/3/2026	Date: _____	Date: _____

EPL CONNECT VERIFIED DIGITAL RECORD 2026