
Sensors: Accuracy
Very dissatisfied
Dissatisfied
Neutral
Satisfied
Very satisfied
Europe
Asia
N America
Africa
Oceania
L Amer & Carib
20
10
0
10
20
30
40
Number of Respondents