
PN_IDLE
PNC_ENABLE_CHECK
Request Activation of PN Rx PDU group
SUM_PNC_PASSIVE_SYNCH_TIME == ON
(Activation Criterion == FALSE &&
PN State Transition != PNC_NO_COMM) &&
DIAG_DisableNormalComm == <ENABLE_NORMAL_COMM>
PNC_TX_ENABLE
Request activation of Tx PDU
Notify SUSD
SUM_PNC_PASSIVE_SYNCH_TIME == EXPIRED
PN_ACTIVE
PNC_REMOTELY_ACTIVE
Bus communication == Full Comm
PN state Transition != PNC_NO_COMM
SUM_PNC_PASSIVE_SYNCH_TIME == ON