
PN_IDLE
PNC_ENABLE_CHECK
Activation Criteria is FALSE
PN state != PNC_NO_COMM
DIAG_DisableNormalComm is <ENABLE_NORMAL_COMM>
Request activation of PN RX Pdu Group
SUM_PNC_PASSIVE-SYNCH_TIME is ON
PNC_TX_ENABLE
Request Tx PDU activation
Notify SUSD
PN_ACTIVATE
PNC_REMOTELY_ACTIVE
Bus communication is Full Comm
PN state transition != PNC_NO_COMM
SUM_PNC_PASSIVE_SYNCH_TIME is ON