
PN_ACTIVE
PNC_PREPARE_SLEEP
Activation Criteria == FALSE &&
Deactivation Criteria == TRUE
PN_IDLE
PNC_ENABLE_CHECK
Request BswM to deactivate PN’s Tx and Rx Pdu group
Notify SUM modules