
Shutdown detection sequence diagram
SOH
PNC
SUSD
Time Manager Runnable
Shutdown Delay Detector
SUSD_SOH_PermitExecution port value
alt
[WakeupBit in SUSD_SOH_PermitExecution is ACTIVE]
SUM_SOH_ShutDown_Timer = 0
Reset SUM_SOH_ShutDown_Timer’s flag
[ShutdownTargetBit in SUSD_SOH_PermitExecution is OFF]
PNC_SUSD_ShutdownPermission port value
alt
[PNC_SUSD_ShutdownPermission==0xFF]
Set SUM_SOH_ShutDown_Timer’s flag