

High Draw Sensors



RTC (ALWAYS POWERED)



Battery (2 POS CONN)

This suitch is located off-board on connector in the suitch is connected in t

Main Power Suitch Circuit

