

Registration No.: R20231016105838

Date: 2023-10-16

CERTIFICATE OF REGISTRATION

Client Information

Name: Tyler M. Henderson Jr.

Address: Arroyo Orchard, Maraska, Roxas, Oriental Mindoro, REGION IV-B

(MIMAROPA), Philippines

Meter No.: W-49290 Property Type: Commercial

Pre-Installation Charges	Description	Amount (PHP)
Application Fee	Covers the inspection related costs.	50 PHP
Inspection Fee	Covers the administrative processing and setup costs associated with new service requests.	250 PHP
Registration Fee	Bookkeeping and Setting of new accounts.	100 PHP
Connection Fee	Includes the cost of meter and ball valve.	4100 PHP
Installation Fee	Cover the labor for installation of connection	400 PHP

Total Assessment Amount PHP 4,900.00

Cashier	•	Administrator