

مقررہ سہ ماہی کے لئے سہ ماہی

404201984 - ()

$$d = \tan^{-1}(-0.411) = -22.378^\circ, (x_c, y_c) = (18, 17) \text{ mm}, d = -22.378^\circ$$

$$\sigma_{\text{max}} = 146.59 \text{ N/mm}^2, \sigma_{\text{min}} = -100.61 \frac{\text{N}}{\text{mm}^2}$$

$$(\bar{x}, \bar{y}) = (8, 17) \text{ mm}, \alpha = -22.378^\circ \quad \underline{\text{الف}}$$

$$\sigma_{\max_{z=0}} = 146.59 \text{ N/mm}^2, \sigma_{\min_{z=0}} = -100.61 \text{ N/mm}^2 \quad \underline{\text{ب}}$$

$$u_{z=500} = -1587 \text{ mm}, v_{z=500} = -10.229 \text{ mm} \quad \underline{\text{ج}}$$

Rouzbeh Pourjafarian

$$I_{xx} = 4032 \text{ mm}^2, I_{yy} = 10692 \text{ mm}^2, I_{xy} = -3888 \text{ mm}^2 \quad \underline{\text{الف}}$$

$$\sigma_{z_{fp}} = 0.612 \text{ N/mm}^2 \quad \underline{\text{ب}} \quad \sigma_{z_{mid}} = 0.46x - 0.80y \quad \underline{\text{ج}}$$

$$\sigma_{z_t} = -0.876 \text{ N/mm}^2, \sigma_{z_m} = -1.128 \text{ N/mm}^2 \quad \underline{\text{د}}$$

نیمه مربع

404201984 (نیمه مربع)

Rouzbeh Pourjafarian

$$I_{xx} = 2ta^3, I_{yy} = \frac{1}{3}ta^3, I_{xy} = \frac{\sqrt{3}}{6}ta^3$$

404201984 - (76219412312

404201984 - (76219412312

$$I_{xx} = 3\pi r^4, I_{yy} = \pi r^4, I_{xy} = -4\pi r^4$$

Rouzbah Pourjafarian

$$e = 30.77 \text{ mm}$$

10 20 30 40 50 60 70 80 90 100

$C = 28.58 \text{ mm}$

Rouzbah Pourjafarian

$$q_1 = 0 = q_7$$

$$\bullet \langle S_1 \rangle h/2, \quad q_{12} = \frac{tS_x}{I_{yy}} \left(\frac{3}{2} h S_1 - \frac{S_1^2}{2} \right), \quad q_2 = q_6 = \frac{tS_x}{I_{yy}} \left(\frac{5}{8} h^2 \right)$$

$$\bullet \langle S_2 \rangle h, \quad q_{23} = \frac{tS_x}{I_{yy}} \left(h S_2 + \frac{5}{8} h^2 \right), \quad q_3 = q_5 = \frac{tS_x}{I_{yy}} \left(\frac{13}{8} h^2 \right)$$

$$\bullet \langle \theta \rangle \pi/2, \quad q_{34} = \frac{tS_x}{I_{yy}} \left(S_m \theta h + \frac{13}{8} h^2 \right), \quad q_4 = \frac{tS_x}{I_{yy}} \left(\frac{21}{8} h^2 \right)$$

$$\bullet \langle \theta \rangle \pi/2, \quad q_{45} = \frac{tS_x}{I_{yy}} \left(\frac{21}{8} h^2 - S_m \theta h^2 \right)$$

$$\bullet \langle S_3 \rangle h, \quad q_{56} = \frac{tS_x}{I_{yy}} \left(\frac{13}{8} h^2 - h S_3 \right)$$

$$\bullet \langle S_4 \rangle h/2, \quad q_{67} = \frac{tS_x}{I_{yy}} \left(\frac{5}{8} h^2 - \frac{3}{2} h S_4 + \frac{S_4^2}{2} \right)$$

مجلس شورای اسلامی ایران

شماره 404201084 - (تاریخ: 1395/05/05)

Rouzbeh Pourjafarian

$$I_{xx} = 5 \times 10^6 \text{ mm}^4, t = 4 \text{ mm}$$

$$q_{01} = \frac{-s_y t}{I_{xx}} (0.5 s_1^2 - 5327.35), 0 \leq s_1 \leq 55$$

$$q_{12} = \frac{-s_y t}{I_{xx}} (0.35 s_2^2 + 55 s_2 - 3814.85), 0 \leq s_2 \leq 25\sqrt{2}$$

$$q_{23} = \frac{-s_y t}{I_{xx}} (80 s_3 - 1428.37), 0 \leq s_3 \leq 50$$

$$q_{34} = \frac{-s_y t}{I_{xx}} (80 s_4 - 0.5 s_4^2 + 2571.63), 0 \leq s_4 \leq 80$$

$$q_{11}' = -2.057 \times 10^{-3} s_y, q_{11}'' = 3.0518 \times 10^{-3} s_y$$

$$q_{45} = \frac{-s_y t}{I_{xx}} (5771.63 - 80 s_5 + \frac{1}{2} s_5^2), 0 \leq s_5 \leq 80, q_{56} = \frac{-s_y t}{I_{xx}} (2571.63 - 80 s_6), 0 \leq s_6 \leq 50$$

$$q_{67} = \frac{-s_y t}{I_{xx}} (-1428.37 - \frac{\sqrt{2}}{4} s_7^2 - 55 s_7), 0 \leq s_7 \leq 25\sqrt{2}, q_{78} = \frac{-s_y t}{I_{xx}} (3814.85 - \frac{1}{2} s_8^2), 0 \leq s_8 \leq 55$$