

## C28/C28FDSOI/C32 Stacked vias design rule

Applicable to 6U1x\_2U2x\_2T8x metallization option only


**Design Foundation** 



## Design rule description

Stacked vias from Via2 to YZ are forbidden under Copper Pillar pads.
This rule is applicable to 10ML option only.

Additional De	esign Rules in STMicroelectronics technology		
STK.R.1	Stacked_YZ_V2 on M3_B2_Pillar is not allowed under Bump <sup>a</sup> .		:





- Mechanical stress is propagated from the bump to the bottom metallization, through stacked vias.
- Mechanical stress propagation is enhanced as stacked vias are placed on small metal pillar (small stacked metal shapes)


 To stop mechanical stress propagation through stacked vias, via stacks must be broken at the uppest via level.



## How to fix ? (1/2)









## How to fix ? (2/2)

- For stacked via fix, the reference position is YZ.
  - W0 or W1 should be shifted by at least **0.360um** from YZ for a mechanically efficient solution

