

4-Point Inspection Report

Insured / Applicant Robert and Ana Kim

Application / Policy # H03-4481207

Address Inspected 902 Palmetto Way


Tampa, FL 33606

Actual Year Built 1986

Date Inspected 09/29/2026

Name of Inspector Jeremy Heath

License # UT-12345



Electrical System

Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.

Main Panel

Type: ☒ Circuit breaker ☐ Fuse

Total amps: 200

Is amperage sufficient for current usage? ☒ Yes ☐ No (explain)

Second Panel

Type: ☐ Circuit breaker ☐ Fuse

Total amps:

Is amperage sufficient for current usage? ☐ Yes ☐ No (explain)

Indicate presence of any of the following

Present: ☐ Cloth wiring ☐ Active knob and tube ☐ Branch circuit aluminum wiring

If aluminum wiring is present, describe the usage of all aluminum wiring:

Single strand (aluminum branch) wiring remediation: ☐ Connections repaired via COPALUM crimp ☐ Connections repaired via AlumiConn

Hazards Present

Hazards: ☐ Blowing fuses ☐ Tripping breakers ☐ Empty sockets ☐ Loose wiring ☐ Improper grounding ☐ Corrosion ☐ Over fusing

☒ Double taps ☐ Exposed wiring ☐ Unsafe wiring ☐ Improper breaker size ☐ Scorching ☐ Other (explain)

General condition of the electrical system: ☐ Satisfactory ☒ Unsatisfactory (explain)

Supplemental Information

Main panel — panel age: 12 yrs

Main panel — year last updated: 2014

Main panel — brand / model: Square D QO

Second panel — panel age:

Second panel — year last updated:

Second panel — brand / model:

Wiring type: ☒ Copper ☒ NM, BX or Conduit

HVAC System

Central AC: ☒ Yes ☐ No

Central heat: ☒ Yes ☐ No

If not central heat, indicate primary heat source and fuel type:

Are the heating, ventilation and air conditioning systems in good working order? ☒ Yes ☐ No (explain)

Date of last HVAC servicing / inspection: 04/12/2026

Hazards Present

Wood-burning stove or central gas fireplace not professionally installed? ☐ Yes ☒ No

Space heater used as primary heat source? ☐ Yes ☒ No

Is the source portable? ☐ Yes ☐ No

Does the air handler / condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? ☐ Yes

☐ No

HVAC System (continued)

Supplemental Information

Age of system: 9 yrs

Year last updated:

Plumbing System

Is there a temperature pressure relief valve on the water heater? ☒ Yes ☐ No

Is there any indication of an active leak? ☐ Yes ☒ No

Is there any indication of a prior leak? ☐ Yes ☐ No

Water heater location: Garage

General condition of plumbing fixtures and connections to appliances

Dishwasher: ☒ Satisfactory ☐ Unsatisfactory ☐ N/A

Refrigerator: ☐ Satisfactory ☐ Unsatisfactory ☐ N/A

Washing machine: ☐ Satisfactory ☐ Unsatisfactory ☐ N/A

Water heater: ☐ Satisfactory ☐ Unsatisfactory ☐ N/A

Showers / Tubs: ☐ Satisfactory ☐ Unsatisfactory ☐ N/A

Toilets: ☐ Satisfactory ☐ Unsatisfactory ☐ N/A

Sinks: ☐ Satisfactory ☐ Unsatisfactory ☐ N/A

Sump pump: ☐ Satisfactory ☐ Unsatisfactory ☒ N/A

Main shut off valve: ☐ Satisfactory ☐ Unsatisfactory ☐ N/A

All other visible: ☐ Satisfactory ☐ Unsatisfactory ☐ N/A

If unsatisfactory, provide comments / details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.):

Supplemental Information

Age of piping system: ☐ Original to home ☒ Completely re-piped ☐ Partially re-piped

Year and extent of renovation: 2015 – full re-pipe

Type of pipes (check all that apply): ☐ Copper ☐ PVC/CPVC ☐ Galvanized ☒ PEX ☐ Polybutylene ☐ Other (specify)

Roof

Predominant Roof

 Covering material: Asphalt shingle

 Roof age (years): 8

 Remaining useful life (years): 14

 Date of last roofing permit: 06/2018

Date of last update:

 If updated: ☒ Full replacement ☐ Partial replacement

% of replacement:

 Overall condition: ☒ Satisfactory ☐ Unsatisfactory (explain below)

 Any visible signs of damage / deterioration? ☐ Cracking ☐ Cupping/
 curling ☐ Excessive granule loss ☐ Exposed asphalt

☐ Exposed felt ☐ Missing/loose/cracked tabs or tiles

☐ Soft spots in decking ☐ Visible hail damage

 Any visible signs of leaks? ☐ Yes ☒ No

 Attic / underside of decking: ☐ Yes ☐ No

 Interior ceilings: ☐ Yes ☒ No

Secondary Roof

Covering material:

Roof age (years):

Remaining useful life (years):

Date of last roofing permit:

Date of last update:

 If updated: ☐ Full replacement ☐ Partial replacement

% of replacement:

 Overall condition: ☐ Satisfactory ☐ Unsatisfactory (explain below)

 Any visible signs of damage / deterioration? ☐ Cracking ☐ Cupping/
 curling ☐ Excessive granule loss ☐ Exposed asphalt

☐ Exposed felt ☐ Missing/loose/cracked tabs or tiles

☐ Soft spots in decking ☐ Visible hail damage

 Any visible signs of leaks? ☐ Yes ☐ No

 Attic / underside of decking: ☐ Yes ☐ No

 Interior ceilings: ☐ Yes ☐ No

Additional Comments / Observations

Double-tapped breaker at slot 14 should be corrected by a licensed electrician. Water heater replaced 2021.

I certify that the above statements are true and correct.

Jeremy Heath

Inspector Signature

Home Inspector

Title

UT-12345

License Number

09/29/2026

Date

Vision Property Inspections

Company Name

Home Inspector

License Type

(801) 555-0134

Work Phone



Pictures



Dwelling — front