

## Inspection Report

**Client Name** Tysen and Chantel Gough

**Address of Inspection** 1428 Ridgeline Dr


Ogden, UT 84403

**Date of Inspection** 09/29/2026

**Real Estate Agent** Cyndi Farrais

**Name of Inspector** Jeremy K. Heath

**License #** UT-12345



## Property Information

Inspection details & property description

|                      |                          |                      |                     |
|----------------------|--------------------------|----------------------|---------------------|
| Type of inspection   | <b>Real Estate Sale</b>  | Type of loan         | <b>Conventional</b> |
| Property type        | <b>Single Family</b>     | Construction style   | <b>Ranch</b>        |
| Year of construction | <b>1998</b>              | Total square footage | <b>2,400 sq ft</b>  |
| Valuation            | <b>\$450,000</b>         | Lot size             | <b>0.25 acres</b>   |
| Stories              | <b>1.5</b>               | Basement             | <b>Unfinished</b>   |
| Garage               | <b>Attached · 2 cars</b> | Car port             | <b>None</b>         |
| Bedrooms             | <b>4</b>                 | Bathrooms            | <b>3</b>            |
| Hallways             | <b>2</b>                 | Checklist depth      | <b>Standard</b>     |

### ADDITIONAL INSPECTION SERVICES

Radon · Thermal Audit · Termite

## Beginning Notes

Conditions at the time of inspection

|                 |                       |             |              |
|-----------------|-----------------------|-------------|--------------|
| Property status | <b>Owner Occupied</b> | Weather     | <b>Sunny</b> |
| Temperature     | <b>72°F</b>           | Power is on | <b>Yes</b>   |
| Gas is on       | <b>Yes</b>            | Water is on | <b>Yes</b>   |

### BUYER'S AREAS OF CONCERN

Buyer asked us to pay particular attention to the roof, the electrical panel, and any signs of water intrusion in the basement.

### APPARENT HAZARDS OBSERVED BEFORE INSPECTION

Tree branches in contact with the structure on the north side. Section of front walkway concrete lifting — trip hazard.



## 02 Landscaping

|                             |          |
|-----------------------------|----------|
| Fence Type                  | Reviewed |
| Front Gate                  | Reviewed |
| Other Gate                  | Reviewed |
| Grading                     | Reviewed |
| Landscaping                 | Concerns |
| Vegetation                  | Reviewed |
| Water Feature               | Reviewed |
| Brush Fire Defensible Space | Reviewed |
| Surface Drainage            | Reviewed |
| Wall                        | Reviewed |
| Retaining Wall              | Reviewed |
| Driveway                    | Reviewed |
| Walk Ways                   | Reviewed |
| Bushes                      | Concerns |
| Trees                       | Reviewed |
| Electrical Receptacles      | Reviewed |
| Sprinkler System            | Reviewed |

Overall condition

**Good**

### COMMENTS

Vegetation is well kept. Recommend trimming tree branches back from the roof line.

### FINDINGS

**Cat 1** No power to exterior receptacle — wiring damaged at housing (back of property).

**Cat 1** Tree branches in contact with the structure.

## 10 Exterior Walls

|                        |          |
|------------------------|----------|
| Siding Material        | Reviewed |
| Soffits                | Reviewed |
| Trim                   | Reviewed |
| Rain Gutters           | Concerns |
| Water Down Spouts      | Reviewed |
| Windows                | Reviewed |
| Lintels                | Reviewed |
| Concrete Sidewalk      | Reviewed |
| Front Steps            | Reviewed |
| Front Porch            | Reviewed |
| Doorbell               | Reviewed |
| Exterior Doors         | Reviewed |
| Chimney                | Concerns |
| Foundation Type        | Reviewed |
| Exterior Foundation    | Reviewed |
| Dryer Exhaust Vent     | Reviewed |
| Hose Bib(s)            | Reviewed |
| Lighting               | Reviewed |
| Electrical Receptacles | Reviewed |
| Mail Box               | Reviewed |

Overall condition

**Good**

### FINDINGS

**Cat 1** Rail required for stairs down to basement back door.

**Cat 2** Section of concrete is lifting — trip hazard.

**Cat 3** Residue of ivy on the front of the house.

**14 Garage**

|                        |          |
|------------------------|----------|
| Garage type            | None     |
| Foundation Type        | Reviewed |
| Roof Type              | Concerns |
| Exterior Walls         | Reviewed |
| Electrical             | Reviewed |
| Hose Bib(s)            | Reviewed |
| Door(s)                | Reviewed |
| Floor Surfacing        | Reviewed |
| Visible Foundation     | Reviewed |
| Trusses                | Reviewed |
| Connector Plates       | Reviewed |
| Ceiling                | Concerns |
| Attic (secondary)      | Reviewed |
| Windows                | Reviewed |
| Thermal Imaging        | Reviewed |
| Garage Door(s)         | Reviewed |
| Lintels                | Reviewed |
| Interior Walls         | Reviewed |
| Lighting               | Reviewed |
| Wiring Type            | Reviewed |
| Electrical Receptacles | Concerns |
| EV Charging            | Reviewed |
| Mold                   | Reviewed |
| Heated                 | Reviewed |

Overall condition

**Good**



## 17 Bedroom 1

|                        |            |
|------------------------|------------|
| Type                   | Master Bed |
| Level                  | Main Floor |
| Door(s)                | Reviewed   |
| Ceiling                | Reviewed   |
| Floor                  | Reviewed   |
| Sub Floor              | Reviewed   |
| Interior Walls         | Reviewed   |
| Windows                | Reviewed   |
| Thermal Anomalies      | Concerns   |
| Closet                 | Reviewed   |
| Lighting               | Reviewed   |
| Shelves                | Reviewed   |
| Electrical Receptacles | Reviewed   |
| Ceiling Fan            | Reviewed   |
| HVAC                   | Reviewed   |
| Thermostat             | Reviewed   |
| Alarms                 | Reviewed   |

Overall condition

**Good**

**19 Living Room**

|                        |                 |
|------------------------|-----------------|
| Door(s)                | <b>Reviewed</b> |
| Ceiling                | <b>Concerns</b> |
| Floor                  | <b>Reviewed</b> |
| Sub Floor              | <b>Reviewed</b> |
| Stairways              | <b>Reviewed</b> |
| Railing                | <b>Reviewed</b> |
| Interior Walls         | <b>Reviewed</b> |
| Windows                | <b>Reviewed</b> |
| Thermal Anomalies      | <b>Reviewed</b> |
| Lighting               | <b>Reviewed</b> |
| Electrical Receptacles | <b>Concerns</b> |
| Ceiling Fans           | <b>Reviewed</b> |
| Fireplace              | <b>Reviewed</b> |
| HVAC                   | <b>Reviewed</b> |
| Alarms                 | <b>Reviewed</b> |

Overall condition

**Good**


**23 Kitchen**

| Remodel                | Concerns |
|------------------------|----------|
| Door(s)                | Reviewed |
| Ceiling                | Reviewed |
| Floor                  | Reviewed |
| Sub Floor              | Reviewed |
| Interior Walls         | Reviewed |
| Windows                | Reviewed |
| Thermal Anomalies      | Reviewed |
| Counters               | Reviewed |
| Cupboards              | Concerns |
| Cabinets               | Reviewed |
| Island                 | Reviewed |
| Pantry                 | Reviewed |
| Sink                   | Reviewed |
| Plumbing               | Reviewed |
| Dishwasher             | Reviewed |
| Stove & Oven           | Reviewed |
| Exhaust Hood           | Reviewed |
| Refrigerator           | Concerns |
| Lighting               | Reviewed |
| Electrical Receptacles | Reviewed |
| HVAC                   | Reviewed |


Overall condition

**Good**


02 Landscaping · Photos




Front Yard



Front Yard



Back Yard 1



Concerns

Cat 1


**10 Exterior Walls · Photos**



Front



Left Side



Concerns

Cat 2

## Summary of Findings

Findings grouped by category, in the order they appear in the report

**1****Category 1 · Safety**

Address before closing

**3**

- 1 No power to exterior receptacle — wiring damaged at housing (back of property). (Landscaping)
- 2 Tree branches in contact with the structure. (Landscaping)
- 3 Rail required for stairs down to basement back door. (Exterior Walls)

**2****Category 2 · Functional**

Address in the first few months after closing

**2**

- 1 Section of concrete is lifting — trip hazard. (Exterior Walls)
- 2 No diverter; water going into foundation causing settling. (Roof)

**3****Category 3 · Items to monitor**

Monitor and address over time

**1**

- 1 Residue of ivy on the front of the house. (Exterior Walls)