# **Cavity Pressure Sensor** 2000 bar **DPPC DS04.0**

#### **Features**

- · For direct measuring
- Measuring range 0...2000 bar
- Connector thread M4 x 0,35
- Sensor diameter 4 mm




<b>Technical Data</b>	
Method	Piezo electric; quartz
Range	02000 bar
Overload	2500 bar
Nom. sensitivity DPPC DS04.0-5.0 DPPC DS04.0-9.4 DPPC DS04.0-9.4/CS	-5,0 pC/bar ± 2% -9,4 pC/bar ± 2% -9,4 pC/bar ± 1%
Linearity	< 1% FS
Natural frequency	> 100 kHz
Insulation resistance at 20°C	>10 <sup>12</sup> Ω
Insulation resistance	>10 <sup>11</sup> Ω

Method	Piezo electric; quartz
Range	02000 bar
Overload	2500 bar
Nom. sensitivity DPPC DS04.0-5.0 DPPC DS04.0-9.4 DPPC DS04.0-9.4/CS	-5,0 pC/bar ± 2% -9,4 pC/bar ± 2% -9,4 pC/bar ± 1%
Linearity	< 1% FS
Natural frequency	> 100 kHz
Insulation resistance at 20°C	>10 <sup>12</sup> Ω
Insulation resistance at 200 °C	>10 <sup>11</sup> Ω

Mechanical Data	
Connector thread	M4 x 0,35
Material enclosure	Stainless steel

Environmental Conditions				
Operating temp. range	0+200 °C			
Storage temperature	-40+200 °C			
Melt temperature (at sensor front side)	< +400 °C			
Protection incl. connector IP 65				


#### **Dimensions (mm)**



### **Delivery Contents**

- Special nut DZPC MN04
- Calibration sheet


# **Order Code**



www.baumer.com 10.12



# **Mounting Dimensions**



Accessories		
Sensor Cable	<b>Mounting Accessories</b>	Description
DZCC xxxx-ST-MF DZCC xxxx-HT-MF	DZPC MN04 DZPC MWPT DZPC MT04	Special nut Mounting wrench Spacer tube

www.baumer.com 10.13