
Display box, 4-channel DDBF 4-SC

Features

Battery

USB connection

- 4-channel display box for strain rings DSRC and strain clamps DSRV
- Contemporaneous measurement and display of 4 channels
- A/C or Battery operation
- Display in με, kN, t
- 2 analog outputs
- Reset with keypad or InspectMaster



Mechanical Data	
Sensor connection	4 pin Binder (series 712)
Enclosure	Aluminum, lacquered

USB 2.0, type B

Maintenance-free Li-Ion battery

Environmental Conditions		
Operating temp. range	+5+50 °C	
Storage temperature	-20+60 °C	
Protection class	IP 40	



Order Code

DDBF 4-SC


Delivery Contents

- Display box
- Power adapter (100 240 VAC)
- Software *InspectMaster*
- USB connecting cable
- Ground connection cable with clip


9.6 www.baumer.com




Dimensions (mm)



View Connector Side



View Bottom Side, under the top cover




Electrical Connections

Sensor connection




Pin	Signal	
1	S/G 1	EXC,+
2	S/G 1	SIG
3	S/G 2	SIG.+
4	S/G 2	EXC

Bridge configuration per connector



Analysis Software InspectMaster



Functions:

- Display in με, N, kN, t
- Display of deviation of tie bar load distribution in $\,\%\,$
- Cycle function with auto reset mode
- Display of graphs
- Saving of measured data
- Export function (Text file may be exported and processed in Excel)

Requirements:

- PC with Windows, 2000, NT, XP minimum 500 MHz and USB interface required

www.baumer.com