

## **Features**


- Ultra sensitive piezo electric surface strain sensor
- Sensitivity 900 pC/με
- To measure very small mechanical strains
- · Ideally suited for mold protection
- Very simple installation




Technical Data	
Method	Piezo electric; ceramic
Recommended Measuring range	0+500 με
Typical Sensitivity	900 pC/με
Linearity	< 1% FS
Capacitance	8000 pF
Insulation resistance at 20°C	> 10 <sup>10</sup> \Omega

Mechanical Data	
Connector	BNC (50Ω)
Weight incl. cable	170 g
Material - Sensor housing - Cable	Stainless steel RGT 404 triax, FEP
Clamping torque	5 Nm


<b>Environmental Conditions</b>			
Operating temp. range	0+50 °C		
Storage temperature	0+50 °C		
Protection class	IP 65		



## **Dimensions (mm)**



## **Typical Measuring Chain**



Pos.	Qty	Туре	Description
1	1	DSPN	High resolution surface strain sensor
2	1	DACU	Charge amplifier

## **Delivery Contents**

- Screws 2 pcs. M4 x 20 (12.9)
- Calibration sheet

www.baumer.com