## TI-30X IIS and TI-30X IIB

**2-Line Display**: The first line displays an entry of up to 88 digits. Scroll the line with ① and ①. The second line displays the result after you press [ENTER].

**Previous Entries**: After an expression is evaluated, press ⊚ and ⊙ to scroll previous entries.

**Menus:** Some keys access menus. Press  $\textcircled{\bullet}$  and  $\textcircled{\bullet}$  to underline a menu item; press ENZER to select it.

12345[PIX]		<u>F</u> 0123456789
2 ENTER	12345	12345.00
2nd [FIX] ⋅	12345	12345.

Last Answer (Ans): Stores the last calculated result.

2 + 2 ENTER	2+2	4.
2nd [ANS] $x^2$ ENTER	Ans <sup>2</sup>	16.

## Clearing and Editing:

CLEAR	Clears entry line or error message.
DEL	Deletes the character at the cursor.
[2nd] [INS]	Inserts a character at the cursor.
[2nd] [RESET]	Displays menu to reset the unit.
ON & CLEAR	Resets unit without displaying a menu.
[2nd] [STAT]	Clears all data points without exiting STAT
CLRDATA	mode.
2nd [EXIT STAT] Y	Clears all data points and exits STAT mode.

Note: Resetting the unit clears all settings and memory.

Trigonometry		
TAN 45) ENTER	tan(45)	1.
Memory		
25STO→ ENTER	25→A	25.
Fractions		
3 Ab/c 1 Ab/c 2 + 3 Ab/c 4 ENTER	3_1_2+3_4	4_1/4
2nd [Ab/c ◆ d/e] ENTER	Ans ▶ Ab/c ←	d/e 17/4
2nd [F↔D] ENTER	Ans≯F∢≯D	4.25
Rectangular-Polar Conversions		
2nd [R↔P] 5 2nd [,] 3 ) ENTER	R▶Pr(5,3)	5.830951895
Probability (Combinations)		
52 PRB () 5 ENTER	52 nCr 5	2598960.
Statistics		
[2nd] [STAT]	1-VAR 2-VAR	
ENTER DATA 45 ENTER	x <sub>1</sub> =45	45.
<b>⊙</b> EN <u>T</u> ER	FRQ=1	1.
⊕55 ENTER	X <sub>2</sub> =55	55.
→ 3 ENTER	FRQ=3	3.
STATVAR () () ()	n ⊼ Sx <u>σx</u>	4.330127019
ENTER X 2 ENTER	σx * 2	8.660254038
2nd [EXIT STAT]	EXIT STAT: Y N	
<u>ENTER</u>		
Notation		
1234 2nd [SCI/ENG] ( ENTER ENTER	1234 1.234 x10 <sup>03</sup>	
Printed in China	30XII/RC/1L1/A	