

Re: Truck Struts Out of Spec Query

From Okky Rizki Rohayat <okky.rrohayat@bukittechnology.com>
Date Thu 8/6/2026 10:36 PM
To benedict.panizza <benedict.panizza@buma.com.au>; Bukit Technology Support <support@bukittechnology.com>
Cc Bradley Carlson <Bradley.Carlson@buma.com.au>; Brendon Porter <brendon.porter@buma.com.au>; Angus Wilson <angus.wilson@buma.com.au>; Pradya Mutiarahma <pradya.mutiarahma@bukittechnology.com>

1 attachment (1 MB)
BAA-2306.pdf;

Hi Benedict,

Sorry for the delayed response.

We have traced back the initial requirement for the suspension cylinder height adjustment, which was created on 16 March 2023. We found the corresponding ticket in Jira (please see the attached file). However, we couldn't find any information explaining why this logic was implemented as described in Pradya's explanation.

According to the ticket, this requirement originally came from Ben. Could you please reach out to him to clarify the reasoning behind this logic?

Thank you.

Regards,
Okky

From: Benedict Panizza <benedict.panizza@buma.com.au>
Sent: Friday, July 17, 2026 5:05 AM
To: Bukit Technology Support <support@bukittechnology.com>; Okky Rizki Rohayat <okky.rrohayat@bukittechnology.com>
Cc: Bradley Carlson <Bradley.Carlson@buma.com.au>; Brendon Porter <brendon.porter@buma.com.au>; Angus Wilson <angus.wilson@buma.com.au>
Subject: RE: Truck Struts Out of Spec Query

Hi Pradya

The issue is when the prompt prior to adjustment is inputted with a “no”. If the answer is no to an adjustment and the struts are out of spec, then they are still out of spec. Thus, a defect should appear in the Identified Defects page to be acknowledged by the Supervisor themselves.

Regards,



Benedict Panizza
Asset Engineer
Lvl 11 199 Grey Street
South Brisbane QLD 4101

Email benedict.panizza@buma.com.au
Website buma.com.au


BUMA-OFFICIAL

From: Bukit Technology Support <support@bukittechnology.com>
Sent: Thursday, 16 July 2026 7:10 PM
To: Benedict Panizza <benedict.panizza@buma.com.au>; Okky Rizki Rohayat <okky.rrohayat@bukittechnology.com>
Cc: Bradley Carlson <Bradley.Carlson@buma.com.au>; Brendon Porter <brendon.porter@buma.com.au>; Angus Wilson <angus.wilson@buma.com.au>
Subject: Re: Truck Struts Out of Spec Query

Hi Benedict,

Current logic is designed to create an **Identified Defect** only if the status remains **Out of Spec after the adjustment** has been applied.

In other words, if the adjustment brings the value back within the acceptable range, no Identified Defect record will be generated.



Please let us know if you need any further clarification.

Regards,
Pradya

From: Benedict Panizza <benedict.panizza@buma.com.au>
Sent: Tuesday, July 14, 2026 4:55 PM
To: Bukit Technology Support <support@bukittechnology.com>; Okky Rizki Rohayat <okky.rrohayat@bukittechnology.com>
Cc: Bradley Carlson <Bradley.Carlson@buma.com.au>; Brendon Porter <brendon.porter@buma.com.au>; Angus Wilson <angus.wilson@buma.com.au>
Subject: RE: Truck Struts Out of Spec Query

Hi Okky

The question was more surrounding why “*out of spec*” struts do not show up in the identified defects page the same way an X rating would for supervisors to acknowledge?

Where does the logic for this live?

Regards,



Benedict Panizza
Asset Engineer
Lvl 11 199 Grey Street
South Brisbane QLD 4101

Email benedict.panizza@buma.com.au
Website buma.com.au

BUMA-OFFICIAL

From: Bukit Technology Support <support@bukittechnology.com>
Sent: Tuesday, 14 July 2026 7:41 PM
To: Benedict Panizza <benedict.panizza@buma.com.au>; Okky Rizki Rohayat <okky.rrohayat@bukittechnology.com>
Cc: Bradley Carlson <Bradley.Carlson@buma.com.au>; Brendon Porter <brendon.porter@buma.com.au>; Angus Wilson <angus.wilson@buma.com.au>
Subject: Re: Truck Struts Out of Spec Query

Hi Benedict,

The out-of-spec logic is available in the UAT SQL database with the following details:

- **Database:** sqldb-ae-nonprod-astadm-001
- **Table:** md_parameter_ehms

The relevant configuration is maintained in this table. I've also attached an example of the configuration data for your reference.

component_id	type_parameter_id	cbm_group_id	cbm_area_id	parameter_ehms_id	model_id	ps_type_id	task_number	detail_number	cbm_parameter_id
413	7	5	5	54143	15	3	146	a	101
413	7	5	5	54144	15	3	146	a	101
414	7	5	5	54145	15	3	146	b	101
414	7	5	5	54146	15	3	146	b	101
415	7	5	5	54147	15	3	146	c	101
415	7	5	5	54148	15	3	146	c	101
416	7	5	5	54149	15	3	146	d	101
416	7	5	5	54150	15	3	146	d	101

Please let me know if you have any questions.

Thank you.

Regards,
Pradya

From: Bukit Technology Support <support@bukittechnology.com>
Sent: Tuesday, July 14, 2026 8:35 AM
To: benedict.panizza <benedict.panizza@buma.com.au>; Okky Rizki Rohayat <okky.rrohayat@bukittechnology.com>
Cc: Bradley Carlson <Bradley.Carlson@buma.com.au>; Brendon Porter <brendon.porter@buma.com.au>; Angus Wilson <angus.wilson@buma.com.au>
Subject: Re: Truck Struts Out of Spec Query

Hi Benedict,

Sorry for the late response.

We're currently checking this with our backend team to validate the implemented logic. We'll get back to you with our findings as soon as we have an update.

Thank you.

Regards,
Pradya

From: Benedict Panizza <benedict.panizza@buma.com.au>
Sent: Monday, July 13, 2026 10:25 AM
To: Okky Rizki Rohayat <okky.rrohayat@bukittechnology.com>; Bukit Technology Support <support@bukittechnology.com>
Cc: Bradley Carlson <Bradley.Carlson@buma.com.au>; Brendon Porter <brendon.porter@buma.com.au>; Angus Wilson <angus.wilson@buma.com.au>
Subject: Truck Struts Out of Spec Query

Hi Okky

Why do truck struts being out of spec (even if readjusted) do not show up in the defects / review page for the services? See example filled out task from the UAT below. This seems like an important piece of information for supervisors to acknowledge prior to releasing the machine. Where does the logic for this live in the IronForms backend?

FRONT SUSPENSION

REAR SUSPENSION

Item	Measurement Location	Comment	Measurement Value	UoM	Status
a	Front left suspension cylinder.	Additional Information (if required)	250	mm	Out of spec Aaron Gross, 13/07/26 13:03:38 (AEST)
b	Front right suspension cylinder.	Additional Information (if required)	250	mm	Out of spec Aaron Gross, 13/07/26 13:06:18 (AEST)
c	Rear left suspension cylinder.	Additional Information (if required)	250	mm	Out of spec Aaron Gross, 13/07/26 13:06:36 (AEST)
d	Rear right suspension cylinder.	Additional Information (if required)	250	mm	Out of spec Aaron Gross, 13/07/26 13:07:12 (AEST)

Does the supervisor want a cylinder height adjustment performed?

Choose One

If you want to change the value, please select "Yes"

Regards,



Benedict Panizza

Asset Engineer

Lvl 11 199 Grey Street
South Brisbane QLD 4101

Email benedict.panizza@buma.com.au
Website buma.com.au

NOTICE:This message is for the named person's use only. It may contain confidential, proprietary or legally privileged information. BUMA Australia does not waive any confidentiality, copyright or legally privileged information by any transmission. If you receive this message in error, please immediately delete it and all copies of it from your system, destroy any hard copies of it and notify the sender. You must not, directly or indirectly, use, disclose, distribute, print, or copy any part of this message if you are not the intended recipient. BUMA Australia reserves the right to monitor all e-mail communications through its networks. Any views expressed in this message are those of the individual sender, except where the message states otherwise and the sender is authorized to state them to be the views of any such entity.

BUMA-OFFICIAL

NOTICE:This message is for the named person's use only. It may contain confidential, proprietary or legally privileged information. BUMA Australia does not waive any confidentiality, copyright or legally privileged information by any transmission. If you receive this message in error, please immediately delete it and all copies of it from your system, destroy any hard copies of it and notify the sender. You must not, directly or indirectly, use, disclose, distribute, print, or copy any part of this message if you are not the intended recipient. BUMA Australia reserves the right to monitor all e-mail communications through its networks. Any views expressed in this message are those of the individual sender, except where the message states otherwise and the sender is authorized to state them to be the views of any such entity.

NOTICE:This message is for the named person's use only. It may contain confidential, proprietary or legally privileged information. BUMA Australia does not waive any confidentiality, copyright or legally privileged information by any transmission. If you receive this message in error, please immediately delete it and all copies of it from your system, destroy any hard copies of it and notify the sender. You must not, directly or indirectly, use, disclose, distribute, print, or copy any part of this message if you are not the intended recipient. BUMA Australia reserves the right to monitor all e-mail communications through its networks. Any views expressed in this message are those of the individual sender, except where the message states otherwise and the sender is authorized to state them to be the views of any such entity.