



Fehlerverlauf L2



Standardabweichung L2



- Celsa ALO_8030_K_8R1 | Pruefling —○— MBS ASK101.4_8R1 | PAC2 —●— MBS ASK101.4_8R1 | Pruefling —●— Redur 13A1030.3ffp_0R0 | Pruefling
- Celsa ALO_8030_K_8R1 | Pruefling —●— Redur 13A1030.3ffp_0R0 | Pruefling
- Redur 13A1030.3ffp_8R1 | Pruefling
- Redur 13A1030.3ffp_8R1 | Pruefling