$x_5 = 0$ 

 $\rightarrow x_5 \oplus x_6 = 0 \longrightarrow x_6 = 0$ 

 $x_2 \oplus x_6 = 1 \longrightarrow x_2 = 1$