

Label 2 – False injection of HPE. Power Consumption pattern changed

