THE PARTY OF THE P

MAHARASHTRA STATE BOARD OF TECHNICAL EDUCATION

(Autonomous) (ISO/IEC - 27001 - 2005 Certified)

SUMMER – 13 EXAMINATION

Subject Code: 12042 <u>Model Answer</u>

Important Instructions to examiners:

- 1) The answers should be examined by key words and not as word-to-word as given in the model answer scheme.
- 2) The model answer and the answer written by candidate may vary but the examiner may try to assess the understanding level of the candidate.
- 3) The language errors such as grammatical, spelling errors should not be given more Importance (Not applicable for subject English and Communication Skills).
- 4) While assessing figures, examiner may give credit for principal components indicated in the figure. The figures drawn by candidate and model answer may vary. The examiner may give credit for any equivalent figure drawn.
- 5) Credits may be given step wise for numerical problems. In some cases, the assumed constant
- values may vary and there may be some difference in the candidate's answers and model answer.
- 6) In case of some questions credit may be given by judgement on part of examiner of relevant answer based on candidate's understanding.
- 7) For programming language papers, credit may be given to any other program based on equivalent concept.



(Autonomous) (ISO/IEC - 27001 - 2005 Certified)

SUMMER – 13 EXAMINATION <u>Model Answer</u>


Subject Code: 12042

Que 1. A) Conventional symbols (2 marks each)


a) External screw thread




b) Asbestos



c) Rack & Pinion



d) Gate valve







(Autonomous) (ISO/IEC - 27001 - 2005 Certified)

SUMMER – 13 EXAMINATION <u>Model Answer</u>


Subject Code: 12042

e) Splined shaft





f) Sq. section on shaft



Q1 B) Any three

(4 Marks each)

a) Meanings of symbols





The basic symbol used for indication of surface roughness consists of two legs of unequal length inclined at 60° to the line representing the surface under consideration.



(Autonomous) (ISO/IEC - 27001 - 2005 Certified)

SUMMER – 13 EXAMINATION

Subject Code: 12042

Model Answer

This current symbol is used whenever the removal of material is **not permitted**. The circle is added to the basic symbol.

Roughness value in µm		Roughness Grade no.	Symbol
;;)	0.8	N6	
11)	0.4	N5	
	0.2	N4 - 1	* * *

- b) Symbols for
 - i) Cylindricity



ii) Angularity



c) Two plates of 10 mm thick welded with V-butt joint Sketch & Symbol

10 mm Thick plates



symbol





(Autonomous) (ISO/IEC - 27001 - 2005 Certified)


SUMMER – 13 EXAMINATION

Subject Code: 12042

Model Answer

d) Transition fit:

A transition fit is one having limits of size so prescribed that either a clearance or an interference may always result when mating parts are assembled. It means in a batch of jobs given for assembly some pairs may result in <u>Clearance fit</u> and remaining may have <u>Interference fit</u>. Following figure shows transition fit.






(Autonomous) (ISO/IEC - 27001 - 2005 Certified)

SUMMER – 13 EXAMINATION <u>Model Answer</u>

Subject Code: 12042 <u>Model Answ</u>

Q2 A) A problem on Auxiliary Views

For FV: 4 Marks For AV: 2 Marks For SV: 6 Marks





Subject Code: 12042


MAHARASHTRA STATE BOARD OF TECHNICAL EDUCATION

(Autonomous) (ISO/IEC - 27001 - 2005 Certified)

SUMMER – 13 EXAMINATION <u>Model Answer</u>

Q 2 B) A problem on line

For FV: 3 Marks For TV: 3 Marks For SV: 2 Marks






(Autonomous) (ISO/IEC - 27001 - 2005 Certified)

SUMMER – 13 EXAMINATION Model Answer

Subject Code: 12042 <u>Model Answer</u>

Q 2 B) A Problem on Plane


For Stage I: 2 Marks For stage II: 3 Marks For final stage: 3 Marks



SUMMER – 13 EXAMINATION

Subject Code: 12042 **Model Answer**

Q3 a) Problem on Prism Inserted into Vertical Prism




F.V.- 04 MARKS T.V.- 04 MARKS S.V.-02 MARKS

(Autonomous) (ISO/IEC - 27001 - 2005 Certified)

SUMMER – 13 EXAMINATION

Subject Code: **12042** <u>Model Answer</u>

Q3 b) Prob- Cylinder Inserted in to Vertical prism



F.V.- 04 MARKS

T.V.- 04 MARKS

S.V.-02 MARKS


(Autonomous) (ISO/IEC - 27001 - 2005 Certified)

,

SUMMER – 13 EXAMINATION

Subject Code: **12042** <u>Model Answer</u>

Q3 C) Connecting Rod Problem



F.V.- 05 MARKS

T.V.- 05 MARKS




(Autonomous)

(ISO/IEC - 27001 - 2005 Certified)

SUMMER – 13 EXAMINATION Model Answer

Subject Code: 12042 Q4 a) Universal Coupling



SECTIONAL F.V.- 10 MARKS


T.V.- 08 MARKS

Bill of Material .-02 MARKS

SUMMER – 13 EXAMINATION Model Answer

Q4 b) ASSEMBLY OF PEDESTAL BEARING

Subject Code: 12042



SECTIONAL F.V.- 10 MARKS

T.V.- 08 MARKS

Bill of Material .-02 MARKS




Subject Code: 12042

(ISO/IEC - 27001 - 2005 Certified)

SUMMER – 13 EXAMINATION Model Answer

Q5 a) DETAILS OF FOOT STEP BEARING



- 1. **BODY -- 07 MARKS**
- 2. BUSH—05 MARKS
- 3. DISC-02 MARKS
- 4. SHAFT—02MARKS
- 5. **PIN—02 MARKS**
- 6. DIM.TOLE.&TOLE GRD—02MARKS




(Autonomous) (ISO/IEC - 27001 - 2005 Certified)

SUMMER – 13 EXAMINATION

Subject Code: 12042 <u>Model Answer</u>

Q5 b) DETAILS OF STUFFING BOX.



- 1. BODY & BUSH -- 09 MARKS
- 2. GLAND—05 MARKS
- 3. STUD—02 MARKS
- 4. SHAFT—02MARKS 5. Nut —02 MARKS



Subject Code: 12042

MAHARASHTRA STATE BOARD OF TECHNICAL EDUCATION (Autonomous) (ISO/IEC - 27001 - 2005 Certified)

SUMMER – 13 EXAMINATION Model Answer