(Autonomous) (ISO/IEC - 27001 - 2005 Certified)

#### **SUMMER - 13 EXAMINATION**

Subject Code: 12243 <u>Model Answer</u>

#### **Important Instructions to examiners:**

- 1) The answers should be examined by key words and not as word-to-word as given in the model answer scheme.
- 2) The model answer and the answer written by candidate may vary but the examiner may try to assess the understanding level of the candidate.
- 3) The language errors such as grammatical, spelling errors should not be given more Importance (Not applicable for subject English and Communication Skills).
- 4) While assessing figures, examiner may give credit for principal components indicated in the figure. The figures drawn by candidate and model answer may vary. The examiner may give credit for any equivalent figure drawn.
- 5) Credits may be given step wise for numerical problems. In some cases, the assumed constant values may vary and there may be some difference in the candidate's answers and model answer.
- 6) In case of some questions credit may be given by judgement on part of examiner of relevant answer based on candidate's understanding.
- 7) For programming language papers, credit may be given to any other program based on equivalent concept.

#### Q1. Attempt any <u>THREE</u> of the following:

#### i) 1.Job Production:

A Production system which manufactures one or few numbers of single products as per the customer specifications within the fixed time period is known as job production system. **1M** 

**Examples:** special car manufacturers, special machine tool products, computer assembly section, etc. 1M

#### 2.Batch Production:

When a firm manufactures limited number of products in terms of lots or batch either at regular intervals or according to customer order, it is termed as batch production. **1M** 

Examples: chemical plants, pharmaceuticals, paints, electric motors, heavy vehicles, etc. 1M

#### ii) Factors Influencing Selection of Site -:

- 1) Availability of raw materials
- 2) Proximity to the market

(Autonomous) (ISO/IEC - 27001 - 2005 Certified)

- 3) Labor supply
- 4) Transport and communication facilities
- 5) Fuel and power
- 6) Climatic considerations
- 7) Momentum of an early start
- 8) Personal preferences
- 9) Government Policy (any 4 points 1 mark each with explanation)

#### iii) Steps involved in Process Planning -:

- 1) Study of part drawings and its specifications. (part print analysis)
- 2) To decide about make or buy about the part under planning. This decision is called make or buy decision.
- 3) Selection of most appropriate process which is competitive and economical.
- 4) Deciding the sequence of operations which comprises the selected process. Operations are combined wherever possible.
- 5) Determination of blank size of raw material and list of material is prepared.
- 6) As per the capacity and capability, the suitable machines with accessories are selected.
- 7) Determination of inspection points or stages on product manufacturing line.
- 8) Selection of labour, tools, measuring and inspection devices.
- 9) Estimation of process and manufacturing cost of product.
- 10) Preparation of route and operation sheet which is also called as process sheet.

(8 steps for 4 marks)

#### iv) 1.Routing:

Routing is the selection of route or path over which each part is to travel during the process of transformation from raw material to finished product.

#### 2. Sequencing:

The selection of the appropriate order in which waiting customers may be served is called sequencing.

It is deals with the situations in which the effectiveness measure (time, cost, distance etc) is a function of the order or sequence of performing a series of jobs (tasks).

#### 3. Scheduling:

(Autonomous) (ISO/IEC - 27001 - 2005 Certified)

Scheduling may be defined as the fixation of time and date for each operation as well as it determines the sequence of operations to be followed.

### 4. Dispatching:


Dispatching is defined as the physical release of work authorization to the operating facilities in accordance of planned routing and schedule. (1mark each)

### Q1 b. Attempt any **ONE** of the following:

- i) Break even point can be lowered by,
  - 1. By decrease in fixed cost.
  - 2. By decrease in variable cost.
  - 3. By increase in selling price.

Effect of Break-Even Point shifting:

- i. If BEP <u>lowered</u> then <u>Profit Increases</u>
- ii. if BEP Rising then Profit Decreases.



#### (2+2+2 marks)

- ii) Principle Objectives of production planning and control: (4 marks)
  - 1. To plan the production activities in a systematic way to fulfill the production demands.
  - 2. To provide the men, machines, materials and tooling at the right time in the required quantity and quality.

### MAHARASH

#### MAHARASHTRA STATE BOARD OF TECHNICAL EDUCATION

(Autonomous) (ISO/IEC - 27001 - 2005 Certified)

- 3. To select the path that should be followed by the material.
- 4. To determine the sequence of operations to be performed.
- 5. To co-ordinate the workings of different departments.
- 6. To ensure that the finished product is delivered as per the commitment.

They are achieved by doing or controlling the following parameters. (2 marks)

Materials, Methods, Machines and Equipments, Routing, Estimating, Loading and Scheduling Dispatching, Expediting, Inspection, Evaluating.

#### Q2. Attempt any <u>TWO</u> of the following:


#### a) Product Layout -:

This layout is also called flow-line layout, line layout or production line layout. In this layout, the machines, equipment and work centers are arranged in a straight or curved line, in the order in which they have to be used, that is, according to the sequence of operations needed to manufacture a product. To justify the product layout, the product must be standardized and manufactured in large quantities. Hence, this system is best suited for mass production.

Examples are: automobile assembly lines, bottling plant and so on.

The raw material enters at one end of the line and moves from one machine to another in the line without back-tracking or cross-movements and finally the end product leaves from the other end of the line. (2 marks)

#### Schematic diagram: (2 marks)



#### **Advantages -:**

(Autonomous) (ISO/IEC - 27001 - 2005 Certified)

- 1. Reduced total production time.
- 2. Minimum of handling and transportation resulting in lower total material handling cost.
- 3. Less floor area needed per unit of production.
- 4. There in less work-in-process (WIP), that is, lower stocks.
- 5. Reduced delays due to the flow of work in the forward direction.
- 6. Higher productivity.
- 7. Easy supervision, easy inspection and easier co-ordination.
- 8. Better utilization of machines and workers.
- **9.** Greater simplicity of production control leading to lower accounting cost and need for fewer controls and records. **(2 marks)**

#### **Disadvantages:**

- 1. The layout is fixed, that is, if the product changes, the whole line will have to be rearranged, that is, lower flexibility.
- 2. The break down of a single machine in the line leads to shut-down of the whole production line.
- 3. The manufacturing cost rises if the volume of production falls.
- 4. If one or more lines are running light, there is considerable machine idleness.
- 5. Line balancing is important, so that the material being processed, does not have to wait for the next operation.
- 6. High capital investment.
- 7. Expansion is difficult. (2 marks)

#### b) EOQ:

The Economic Order Quantity (EOQ) is the number of units that a company should add to inventory with each order to minimize the total costs of inventory such as holding costs, order costs, and shortage costs.


#### 2marks

#### **EOQ** model:

i)Economic order quantity (EOQ) with constant demand and instantaneous supply.



(Autonomous) (ISO/IEC - 27001 - 2005 Certified)



3 Marks explanation 1 Mark for diagram.

### **Concept of discounts: (2Marks)**

Quantity discounts are price reduction for large orders offered to customers to include them to buy in large quantities.

If quantity discounts are offered, the buyer must weight the potential benefits of reduced purchase price and fewer orders that will result from buying in large quantities against the increase in carrying costs caused by higher average inventories. The buyer's goal with quantity discounts is to select the order quantity that will minimize total cost, where total cost is the sum of carrying cost, ordering cost, and purchasing cost:

Tc = carrying cost + ordering cost + purchasing cost

Total cost = 
$$\frac{A \times Co}{Q} + \frac{Q \times Cu i}{2} + Cp \times A$$

Where  $C_p$  = purchase price of material per unit.



(Autonomous) (ISO/IEC - 27001 - 2005 Certified)

iii)

Element	Average time	Rating	Basic time = Average time X Rating/100
1	1.44	120	1.728
2	2.61	120	3.132
3	3.35	120	4.02
4	1.21	120	1.452
5	0.53	120	0.636
Total Time			10.968

### (calculating Average time 2 marks)

\* Basic time per piece= 10.968 minutes -----1 (2marks)

\*Relaxation allowance =  $5/100 \times 10.968$ 

= 0.5484 minutes -----2 (1 mark)

\*Contingency allowance = 3/100 X 10.968

= 0.3290 minutes -----3 (1 mark)

\*Special and other allowances =  $8/100 \times 10.968$ 

= 0.8774 minutes----4 (1 mark)

\*Standard time of operation = 1+2+3+4

=10.968+0.5484+0.3290+0.8774

Standard time of operation =12.72 minutes (1 mark)

### Q3. Attempt any **FOUR** of the following.

a.

1. The general level of education is an important factor in national productivity. The use of computers and other sophisticated equipment and system requires better educated employees.

Government can help by sponsoring more education, especially in fields that directly affect productivity.

### MAHARASHTRA STATE BOARD OF TECHNICAL EDUCATION (Autonomous)



(ISO/IEC - 27001 - 2005 Certified)

2. Employees need to be motivated to be productive. Pay is not enough; they need to have good, safe, working conditions and to be recognized as the most vital part of the enterprise.

3. Labour unions and management may be adversaries in negotiating pay and benefits but can cooperate in seeking productivity improvements, to the benefit of all.

4. An excessive amount of government regulation may have a detrimental effect on productivity.

5 Government can do much to eliminate unneeded regulations and to make cost-benefit analysis to determine the necessary regulations such as those on health and safety.

(4 Marks)

#### b. Group Technology -

Processes are grouped into cells using a technique known as group technology (GT).

Group technology involves identifying parts with similar design characteristics (size, shape, and function) and similar process characteristics (type of processing required, available machinery that performs this type of process, and processing sequence).

Group technology is a manufacturing philosophy or principle with far reaching implications.

#### (2Marks)

#### **Differing points of cellular layout:**

- 1. Reduced material handling and transit time
- 2. Reduced setup time
- 3. Reduced work-in-process inventory
- 4. Better use of human resources
- 5. Easier to control
- 6. Easier to automate (Any 4 points 2 marks)

### c. Design Principles of Jigs and Fixtures:

- 1. The jig and fixture should be as open as possible to minimize chip or burr accumulation and to enable the operator to remove the chips easily with a brush or an air jet.
- 2. Fool Proofing
- 3. Clearance
- 4. Rigidity
- 5. Trunnions
- 6. Burr grooves

## MAHARASHTRA STATE BOARD OF TECHNICAL EDUCATION (Autonomous)

THE PARTY IN COLUMN TO SERVICE AND ADDRESS OF THE PARTY ADDRESS OF T

(ISO/IEC - 27001 - 2005 Certified)

- 7. Ejectors
- 8. Inserts
- 9. Design for safety
- 10. Sighting surfaces
- 11. Simplicity in Design
- 12. Economical (any 4 points 1 mark each)

#### d. Selection of Machine -

- 1. Initial, running and maintenance cost of machine. A machine which results in lower total cost should be selected.
- 2. Volume of production rate of production and unit cost of production.
- 3. Type of product to be manufactured and the frequency of production cycle.
- 4. The degree of flexibility desired in production.
- 5. Durability and dependability i.e. quality and reliability aspect of machine and its output.
- 6. Minimum setup, put-away and operation time.
- 7. Longer productive life of machines or equipment.
- 8. Functional versatility i.e. ability of machine to perform more than one function.

(any four 1 mark each)

#### e. 5 'S' as Waste Reduction Techniques -

Seiri is the first step of the 5S method. It means "to sort" or organize.

Seiri has two main goals:

1.Remove unnecessary objects 2.Reduce waste

What does it means to "reduce waste" to us. This goes beyond simply "reducing waste material" by identifying all hindrances and generating ideas for improvements. Are work instructions available, accurate, and used Work instructions can help improve quality, reduce reject rates and increase productivity.

What safety hazards exist? Cluttered floors; missing safety guards on machinery; electrical faults; broken steps on ladders.



(Autonomous) (ISO/IEC - 27001 - 2005 Certified)

- 1. Are materials being waster?
- 2. Will employees become ill?
- 3.Do we have the right tools, in the right places, in good condition?

Waste reduction techniques should be key components of any cost-effective, comprehensive waste management program. They do not have to be based on complex technology or require large capital expenditures. (4 marks)

Que.4	Attempt any <u>THREE</u> of the Following (3*3=9)	Marks		
<b>a.</b> (i)	Name the material handling devices suitable for process layout and explain any one.	04		
	List of material handling devices suitable for process layout any 4 type. (2 M)			
Ans:	i) Trucks			
	a) Power lift			
	- fork lift truck			
	- elevating platform truck			
	b) Hand lift truck			
	c) porters trolley			
	ii) Tractors and trailers.			
	iii) Hoist and cranes			
	iv) Conveyor  Explanation of above any one –(2 M)			
	Trucks:			
	- Manually operated trucks are most commonly used for movement of material			
	over short distance where the load are not heavy.			
	- Most commonly used trucks are fork lift truck.			
	- Heavy duty machines having diesel or petrol engine with large wheel are used			
	for stockyard work.  - Trucks with smaller wheels are used for both operations inside & outside.			
ii)	What are the different types of assembly? Explain any one.	04		
Ans:	Types of assembly (2 M)			
	i) Unit assembly/ fixed assembly/ stationary assembly			



	ii)Progressive assembly				
	Explanation of any one type (2 M)				
	i) Unit assembly/ fixed assembly/ stationary assembly				
	In unit assembly the complete joining of two or more part is carried out at a				
	single place				
	- The complete product is assembled at a single assembly work station.				
	ii) Progressive assembly				
	- In progressive assembly the components moves along the assembly line and at				
	each work station few components are joined to the parts or sub assembly.				
iii)	Explain plant capacity and plant efficiency factor.	04			
Ans:	Plant capacity (2 M)				
	- Plant capacity is the amount of finished product or find product produced per				
	hour				
	- Generally plant capacity is expressed as amount of final product produced per				
	annum				
	Plant efficiency factor (2 M)				
	- It is the ratio of the working hours utilized by the plant per day or per shift or				
	per week or per year to the working hours of the plant for the same period				
	- Plant efficiency factor = actual work hour in sp. Period / available work hour				
	for sp. Period				
iv)	What is the LOB? With suitable example	04			
Ans:	LOB (line balancing)-Concept (2M)				
	- Line balancing means assigning the equal work content to each work station in				
	the assembly line.				
	- The main objective of line balancing is to minimize idle time of man and				
	machine				
	Proper Explanation with example (2M)				
	- If a product is completed by using three different machines – A,B & C in				
	sequence.				
	- If 'A' can process 10 pieces / unit time,				
	- If 'b' can process 15 pieces / unit time &				
	- If 'C' can process 30 pieces / unit time.				
	- Then for line balancing, 3 machines of type A, 2 machines of type B with every				



	machine of type C. So that constant output of 30 pieces / unit time at each work	
	station can be achieved.	
Que.4	Define machine capacity. Explain the factor affecting the machine selection.	06
b	Machine capacity: Definition-(2M)	
i)	- It is production rate of machine per hour	
Ans:	- Capacity is expressed in terms of unit produced per hour or tones per annum.	
	Factors affecting machine selection (any 4 point- 4 M)	
	- Types of product.	
	- Types of plant layout.(Space requirement)	
	- Running and maintenance cost.	
	- Quantity to be produced.	
	- Durability & Reliability.	
	- Flexibility.	
	- Minimum setup & operation time.	
	- Ease in operation.	
ii)	Explain the principle of material handling.	06
Ans:	A) Related to planning (any 2 point- 2M)	00
Alls.	- All activity should be planned.	
	- Plan a system which include all the handling activities & co-coordinating the	
	operations.	
	- Simplification principle.	
	- Gravity principle.	
	- Space utilization.	
	- Space utilization Safety principle.	
	B) Related to equipment (any 2 point- 2M)  - Mechanization/ automation principle.	
	- Equipment selection according to movement & method of material handling.  Standardization principle	
	- Standardization principle.	
	- Flexibility principle.	
	- Maintenance principle.	
	- Idle time principle- reduced idle time.	



(Autonomous) (ISO/IEC - 27001 - 2005 Certified)

	C) Related to Operation ( any 2 point- 2M)	
	- Control principle- Use material handling equipment to improve production	
	control, inventory control etc.	
	- Capacity principle- to achieve full production capacity.	
	- Performance efficiency principle.	
Que.5	Attempt any <u>FOUR</u> of the Following (4*4=16)	
<b>a</b> )	State the advantages and limitations of rapid prototyping.	04
Ans:	Advantages: (Any 4 point – 2M)	
	1. The Prototype gives the user a fair idea about the final look of the product.	
	2. Rapid prototyping can enhance the early visibility.	
	3. It is easier to find the design flaws in the early developmental stages.	
	4. Active participation among the users and producer is encouraged by rapid prototyping.	
	5. As the development costs are reduced, Rapid prototyping proves to be cost effective.	
	6. The user can get a higher output.	
	7. The deficiencies in the earlier prototypes can be detected and rectified in time.	
	8. The speed of system development is increased. It is possible to get immediate feedback from the user.	
	9. There is better communication between the user and designer as the requirements and expectations are expressed in the beginning itself.	
	10. High quality product is easily delivered by way of Rapid prototyping.	
	Disadvantages: (Any 4 point – 2M)	
	1. Some people are of the opinion that rapid prototyping is not effective because,	
	in actual, it fails in replication of the real product or system.	
	2. It could so happen that some important developmental steps could be omitted to	
	get a quick and cheap working model. This can be one of the greatest	
	disadvantages of rapid prototyping.	
	3. Another disadvantage of rapid prototyping is one in which many problems are	
	overlooked resulting in endless rectifications and revisions.	
	4. One more disadvantage of rapid prototyping is that it may not be suitable for large sized applications.	
	5. The user may have very high expectations about the prototype's performance	
	, , , , , , , , , , , , , , , , , , , ,	1



	and the designer is unable to deliver these.	
	6. The system could be left unfinished due to various reasons or the system may	
	be implemented before it is completely ready.	
	7. The producer may produce an inadequate system that is unable to meet the	
	overall demands of the organization.	
	8. Too much involvement of the user might hamper the optimization of the	
	program.	
<b>b</b> )	Define Method Study. State its objectives.	04
Ans:	Definition:2 M	
	Method study: Method study may be defined as the systematic investigation of the	
	existing method of doing a job in order to develop and install an easy, rapid, effective	
	and efficient procedure for doing the same job and at lower costs.	
	Objectives : (any 4 points- 2 M )	
	1. Improvement in process and procedure.	
	2. Improvement of factory shop and work place layout.	
	3. Improvement of the design of plant and equipment.	
	4. Reduction of unnecessary fatigue and economy in human effort.	
	5. Improvement in the use of materials, machines and manpower	
	6. The development of better working environment.	
<b>c</b> )	"Critical examination forms the basis for the method improvement." Justify.	04
Ans:	Critical examination is a questioning technique having a set of questions to find out the	
	facts and reasons, six types of question are framed- what, why, how, when, where and	
	who. The questioning process is considered under five major heads namely- place,	
	purpose, sequence, person and means. These five aspects are considered as governing	
	factor in critical examination.	
	All the questions are divided into three categories :	
	(a) Primary questions: deals with facts and reasons.	
	(b) Secondary questions: deals with finding out the alternatives.	
	(c) Final questions: select few alternatives for development.	
	(c) Final questions: select few alternatives for development.  Thus, it is clear that solution to above questions will definitely give an idea for	



Ans:	What are the different types of jigs and fixtures? Draw a neat sketch of any one jig and					
4 1113 •	label it.					
	Types of jigs: (1 M)					
	a) Drill jigs:					
	i) Template jig.	ii) Plate jig.				
	iii) Diameter jig.	iv) Leaf jig.				
	v) Channel type jig.					
	b) Boring jig.					
	Types of fixture: (1M)					
	i) Milling fixture. ii) Turning fixture.					
	iii) Grinding fixture. iv) Broaching fixture.					
	v) Boring fixture. vi) Indexing fixture.					
	vii) Welding fixture. viii) Assembly fixture.					
	ix) Tapping fixture. x) Duplex fixture.					
	Neat sketch of any one type of jig with lable: 2 M					
		Template Jig				
		Drill				
		Work				
e)	Explain two bin system.		04			
		as of inventory control is the two- bin system.	04			
,	- One of the oldest system	as of inventory control is the two- bin system.  sock of each item is separated into two bins.	04			
	- One of the oldest system - In the two bin system, st	·	04			
	- One of the oldest system - In the two bin system, st	ock of each item is separated into two bins. just enough to last from the date of new order is placed until	04			
	<ul> <li>One of the oldest system</li> <li>In the two bin system, st</li> <li>One bin contains stock;</li> <li>it is received in inventory.</li> </ul>	ock of each item is separated into two bins. just enough to last from the date of new order is placed until	04			
	<ul> <li>One of the oldest system</li> <li>In the two bin system, st</li> <li>One bin contains stock;</li> <li>it is received in inventory.</li> </ul>	cock of each item is separated into two bins.  just enough to last from the date of new order is placed until  quantity of stock, enough to satisfy probable demand during	04			
e) Ans:	- One of the oldest system - In the two bin system, st - One bin contains stock; it is received in inventory - The other bin contains a the period of replenishmen	cock of each item is separated into two bins.  just enough to last from the date of new order is placed until  quantity of stock, enough to satisfy probable demand during	04			
	- One of the oldest system - In the two bin system, st - One bin contains stock; it is received in inventory - The other bin contains a the period of replenishme - To start with, the stock i	cock of each item is separated into two bins.  just enough to last from the date of new order is placed until  quantity of stock, enough to satisfy probable demand during int.	04			
,	- One of the oldest system - In the two bin system, st - One bin contains stock; it is received in inventory - The other bin contains a the period of replenishme - To start with, the stock i	cock of each item is separated into two bins.  just enough to last from the date of new order is placed until  quantity of stock, enough to satisfy probable demand during  nt.  s issued from first bin. When the first bin is empty, an order	04			




Ans:	(any 4 point- 4 M)	
	Necessity of MRP:	
	I. It helps to procure the material or components as and when needed and thus	
	excessive inventory levels.	
	II. To ensure availabilities and procurement of materials as well as action required	
	to meet delivery deadlines.	
	III. Using MRP, it is possible to give timely information about likely delivery times	
	to prospective customers.	
	<b>IV.</b> It helps to increase the efficiency of production system.	
Que.6	Why power devices are used in clamping? What are the disadvantages in hand	04
a)	clamping?	
Ans:	Reasons (any 4 point- 2 M)	
	Power devices are used in clamping because of following reasons:	
	- It holds the work piece rigidly.	
	- The work piece not be damaged due to application of clamping pressure by the	
	clamping unit.	
	- It is capable to be unaffected by the vibrations generated during an operation.	
	- It is user friendly, like it's clamping and releasing is easy and less time consuming.	
	- It is quick acting & easily controllable.	
	- Reliable & high accuracy.	
	Disadvantages of hand clamping. ( any 4 points- 2 M)	
	- Variable pressure damages the work piece.	
	- More time required for clamping.	
	- Due to repetitive effort of operator, operator's fatigue comes into play.	
	- Uniform clamping pressure for similar type of element is difficult to achieve.	
	- Less accuracy due to improper clamping.	
b)	Define single piece production system. State its correlation with JIT.	
Ans:	Definition of single piece production system. (2M)	
	Single piece production system describes the sequence of product or of transactional	
	activities through a process one unit at a time.	
	In single piece production system, focus is on the product or on the transactional	
	process, rather than on the waiting, transporting and storage.	
	Correlation with JIT: (Proper explanation: 2 M)	
	Achieving single piece production system helps manufacturers achieve the just –in –	



	time manufacturing.	
	That is right parts can be made available when they are needed in the quantity they are	
	needed.	
	Single piece production means parts are moved through operations from step to step	
	with no Work-in-Process (WIP) in between, either one piece at a time or a small batch	
	at a time. That satisfies the JIT requirement.	
<b>c</b> )	What are the general steps for conducting the time study?	04
Ans:	The various steps involved in time study procedure are as follows:	
	1. Select the task to be timed.	
	2. Standardized the method of working.	
	3. Select the operator to be studied.	
	4. Record necessary details of job and condition of work.	
	5. Break the task into elements.	
	6. Measure the duration of each element and check the pace of working.	
	7. Extend the observed time into normal/ basic time.	
	8. Calculate the standard time after adding the various allowances with normal time.	
<b>d</b> )	What is ABC analysis? Explain with neat sketch.	04
Ans:	(Concept- 1M, sketch 1M, Explanation-2M)	
	<b>ABC analysis:</b> ABC analysis is segregating the items from one another and tells how	
	much valued the items is and controlling it to what extent is in the interest of	
	organization.	

(Autonomous) (ISO/IEC - 27001 - 2005 Certified)





Move to take pen			Remain idle.	(any 6)
Bring the pen to	<b>1</b>	<b>—</b>	Remain idle.	
central position.			Removing the	
Holding the pen			cap & putting it	
			at convenient	
			place.	
Holding the pen	•		Returning to	
Holding the pen			central position.	
	\\	<del>\</del>		
	1		Unscrewing the	
Taking the pen-		<u> </u>	barrel of pen.	
top near to ink		$\overline{}$		
bottle.	<b>1</b>	1	Holding the non	
Sucking the ink			Holding the pen	
from bottle to	<del>\</del>	•	Holding the pen	
pen pump.				
			Taking the barrel	
			near the pen -	
Holding the pen			top.	
top.			Sarayying the	
Holding the pen			Screwing the barrel to the pen-	
top.			top.	
			Cop.	
Summorve				1 M
Summary:				1 1/1



		<b>\</b>			
Left hand	1	3	5	-	
Right hand	3	3	2	2	