1:	5110		
3	Ho	urs / 100 Marks Seat No.	
	Instru	ctions – (1) All Questions are Compulsory.	
		(2) Answer each next main Question on a new page.	
		(3) Illustrate your answers with neat sketches whereve necessary.	er
		(4) Figures to the right indicate full marks.	
		(5) Assume suitable data, if necessary.	
		M	arks
1.		Attempt any FIVE of the following:	20
	a)	Enumerate the meaning of 'Reaching', 'Drawing-In' and 'denting'.	
	b)	Mention any four types of ingredients and their functions in sizing.	
	c)	How size paste level in the size box is maintained?	
	d)	What is the use of 'Wet-splitting' and 'Teflon coating'?	
	e)	State the measuring method of stretch percentage in sizing.	
	f)	Sketch and label Auto loom Shuttle alonge with pirn.	
	g)	Enumerate merit and demerits of side and centre weft fork motion.	
2.		Attempt any TWO of the following:	16
	a)	Sketch and label pressure cooker used in size cooking.	
	b)	Describe the congealing and keeping properties of a starch paste & its application.	
	c)	Explain the selection criterias of Maize starch and PVA.	

		Ma	ırks
3.		Attempt any TWO of the following:	16
	a)	Give the functions of reed and healdwire. Draw its figures.	
	b)	(i) Compare two cylinder and multi cylinder drying methods of sizing.	
		(ii) Draw the diagram of size box and label its parts.	
	c)	Sketch and label multi cylinder sizing machine.	
4.		Attempt any <u>TWO</u> of the following:	16
	a)	Describe the importance and working of 'Measuring and Marking motion.'	
	b)	Enumerate factors affecting size pick up %.	
	c)	How to calculate Dead Loss % and count of sized warp ?	
5.		Attempt any <u>TWO</u> of the following:	16
	a)	Define migration and mention procedure of migration measurement.	
	b)	Compare Ordinary power loom and Automatic loom for 16 points.	
	c)	Sketch and Label any one warp stop motion.	
6.		Attempt any <u>TWO</u> of the following:	16
	a)	(i) Pirn changing motion is preferred to shuttle changing motion. Comment.	
		(ii) State the importance of weft feeler on automatic loom.	
	(b)	Sketch and label cimmco semi positive let-off mechanisum.	
	(c)	Mention eight important points of special warp preparation, with proper reasons, required for Automatic weaving.	