




1. UNIVERSAL M.2 B–KEY WWAN SOCKET




2. USB ESD AND MODEM BULK CAPACITANCE



3. FSA2567 DUAL–SIM MUX



4. TWO FIELD–ACCESSIBLE NANO–SIM HOLDERS




Insert power pin into the slot opposite 2.2 V source but are intentionally not from MODM2M.

Insert power pin into the slot opposite 2.2 V source but are intentionally not from MODM2M.



Power-Regulator (1189-1192) provide 1.2V of low-ESR bulk inside the socket. CTR5/CTR6 are local RF bypass.

6. MODEM CONTROL CONTRACT



Control output sequence in the system GPIO register: FULL_CARD_POWER_OFF and RESET require that modem-specific timing validation.

TP7201-TP7208 are support factory problem. USB 2/3 has no branch or grounds that happen.



5. RF BULKHEAD HARNESS CONTRACT



Four left-based EXT R048333M uses RF 10-to-10M bulkhead pigtail. Their cable length measures a model sample gain.