Corrected Siemens Valve & Repair-Set Supplier Research

12 third-party sourcing routes for the nine earlier valve lines (ten units) and a **separate, newly supplied repair-set identifier**. No direct purchase from Siemens Energy, Hartmann, SOMAS or another original manufacturer is proposed.

What changed: The previous brief mixed manufacturers with resellers. The manufacturer product literature remains useful for technical identification, but those companies are not purchasing contacts here.

What has not been proved: No seller has confirmed in writing that an exact requested reference is available factory-new. None of these third parties has been independently established as an authorized Siemens Energy seller for the specific turbine/parts. A published turbine application is not an assembly cross-reference.

Part identity: distinguish documented text from AI inference

A2A50182217: The user-provided eTenders search screenshot reads **"0613656 KIT,VLV RPR:A2A50182217;CONTROL. 3575ST31"**. The abbreviation suggests a **valve-repair-kit lead**, not a whole valve or proven new stock. The meaning of 0613656 and 3575ST31, the source document and full line context are not confirmed.

PB0000135690: supplied as an alleged associated item code. Its pairing with A2A50182217 and its exact meaning are not established by that screenshot. Do not represent it as a verified Siemens part or plant-block identifier.

Unverified AI additions: the pressure-filter assembly 74605.0002.1010.0031, SGT5-2000E/V94.2 fit, the kit's seal/filter contents, and A2A50179079 / PB0000119810 as a compatible filter element. Do not purchase a substitute based on these assertions.

The earlier **nine complete-valve references** remain separate inquiry lines. No public evidence connects this extra repair-set code to any one of them. Obtain the turbine model/serial, original valve and actuator nameplates, and the relevant parts-list/drawing before asking a reseller to certify a match.

Original nine-line valve schedule

#	Function	Siemens order / reference	Siemens item reference	Qty
1	Fuel-gas pilot control valve	MBMBP1J000-E13	404050912140	1
2	Fuel-gas premix control valve	MBMBP1H000-E13	404050912147	1
3	Fuel-gas stop valve	MBMBP1F000-E13	404050912154	1
4	Certified cooling-air butterfly	MBMBH1A000-E04/0003	405211540032	2
5	Certified cooling-air butterfly	MBMBH1A000-E04/0002	405211540033	1
6	Certified cooling-air butterfly	MBMBH1A000-E04/0001	405211540034	1
7	Complete purge-air ball valve	MBMBH4B000-E05/0004	405211311668	1
8	Complete purge-air ball valve	MBMBH4B000-E05/0003	405211311669	1
9	Complete purge-air ball valve	MBMBH4B000-E05/0002	405211311670	1

Item 4 is the only two-unit line. The repair-set quantity was not supplied.

Third-party sourcing shortlist

How to read this list: Each entry was screened against a published offering and an additional product, company or industry source where available. This checks whether it is a plausible RFQ recipient, not whether it has new stock or is OEM-authorized. The caveat under every entry is a mandatory check. **Overall fit: 3/10 as a ready-to-buy list.** Individual scores measure evidence for the requested parts, turbine family, new condition and supply chain, not company reputation. Tap underlined teal text to open sources and contacts.

01 Score Group / Score Energy | FIT 5/10

UK / international | Independent turbine-parts supplier
Route: Fuel/auxiliary valves; kit inquiry

Basis: Publishes Siemens gas-turbine OEM parts supply and examples including actuators and bleed valves. Its turbine materials distinguish new OEM stock from overhauled stock. (Product evidence; Second check).

Before relying on it: Published Siemens examples center on the TB5000 line, not these exact references; request model coverage and only factory-new complete assemblies.
Contact: energycustomersupport@score-group.com | +44 1779 482300 | Official contact page.

02 AP4 Group / AP+M | FIT 4/10

USA / international | Independent parts distributor
Route: Fuel-system and auxiliary spares; kit inquiry

Basis: Publishes a gas-turbine auxiliary/fuel-system parts search. First Reserve's acquisition announcement independently confirms the established AP4 business. (Product evidence; Second check).

Before relying on it: Generic fuel-system coverage does not establish Siemens SGT5 capability, OEM authorization, exact valve stock or new-only condition.
Contact: +1 561 732 6000 | Official contact page.

03 EthosEnergy | FIT 5/10

Global | Independent heavy-duty turbine parts provider
Route: All lines as a sourcing request

Basis: Heavy-duty turbine business includes a new-parts offering and Siemens support; an independent industry report corroborates its substantial parts operation. (Product evidence; Second check).

Before relying on it: No public proof for the precise Siemens valve/kit references or V94.2 model; parts business also offers refurbished/used material.
Contact: Contact via company inquiry page | Official contact page.

04 European Power Systems | FIT 3/10

UK / Spain | Independent Siemens spare-parts trader
Route: Siemens original-valve and kit RFQ

Basis: Its Siemens spares page describes genuine new parts sourced from Siemens or original component makers. UK Companies House identifies European Power Systems Limited (04359653). (Product evidence; Second check).

Before relying on it: Published Siemens stock focuses on SGT100-400/legacy engines; no exact heavy-frame or valve-kit match, and overhauled inventory must be excluded.
Contact: info@europeanpowersystems.eu.com | +44 1509 610770 | Official contact page.

05 CEDCO GmbH | FIT 3/10

Germany / international | Independent industrial-turbine spares supplier
Route: Siemens platform spares; conditional valve/kit RFQ

Basis: Publishes a gas-turbine spare-parts offering; independent German business directories identify the company. (Product evidence; Second check).

Before relying on it: Its public materials do not establish inventory of these exact new valves or the repair set. Confirm model, manufacturer and original part lineage.
Contact: Contact via company inquiry page | Official contact page.

06 TTPS International | FIT 2/10

USA / international | Independent Siemens turbine-parts inquiry
Route: All Siemens references; especially repair-set inquiry

Basis: Maintains a Siemens gas-turbine-parts page and a company contact route. (Product evidence; Second check).

Before relying on it: An independent legal/authorization confirmation, original-component chain and exact new-condition stock were not established in public evidence. Screen before payment.
Contact: sales@ttpsintl.com | +1 732 343 5113 (recheck on official site) | Official contact page.

07 Gas Turbine Services | FIT 2/10

UK / Denmark | Independent Siemens Lincoln/Ruston spares supplier
Route: All lines only if the unit is SGT100-400

Basis: Publishes strategic OEM stock and quality certificates for Siemens Lincoln/Ruston turbines. (Product evidence; Second check).

Before relying on it: Its historical Siemens-approved service-center status does not establish current authorization. No documented V94.2/SGT5-2000E coverage.
Contact: gts@gasturbineservices.com | +44 1522 842700 | Official contact page.

08 Armour Valve | FIT 3/10

Canada | Third-party SOMAS valve distributor
Route: Cooling-air butterfly valves, items 4-6

Basis: Lists SOMAS as a supplier and markets SOMAS butterfly valves; a Canadian trade directory independently lists Armour Valve. (Product evidence; Second check).

Before relying on it: SOMAS turbine-cooling application exists, but no cross-reference proves the requested Siemens assemblies are SOMAS; require original valve and actuator nameplates.
Contact: sales@armourvalve.com | +1 416 299 0780 | Official contact page.

09 KLINGER Baltic | FIT 2/10

Estonia / Baltic region | Third-party SOMAS valve seller
Route: Cooling-air butterfly valves, items 4-6

Basis: Publishes a SOMAS butterfly-valve product page; Estonian business register lists Klinger Baltic OÜ (11492319). (Product evidence; Second check).

Before relying on it: Product-line evidence is not a Siemens OEM cross-reference. Seek a complete, newly manufactured certified assembly with actuator compatibility.
Contact: info@klinger.ee | +372 670 3002 | Official contact page.

10 Zuercher Technik | FIT 2/10

Switzerland | Third-party SOMAS valve supplier
Route: Cooling-air butterfly valves, items 4-6

Basis: Catalogs SOMAS MTV/MTVF butterfly valves; a Swiss business directory separately identifies the company. (Product evidence; Second check).

Before relying on it: Cataloging SOMAS components does not prove a certified, identical Siemens cooling-air assembly or current new stock.
Contact: +41 61 975 10 10 (recheck on official site) | Official contact page.

11 VBR Turbine Partners | FIT 3/10

Netherlands / Europe | Parker Meggitt valve distributor (company-stated)
Route: Fuel-gas valve assemblies if Meggitt original

Basis: Publishes an OEM distributorship for Parker Meggitt turbine valves and a new-valve sales route. (Product evidence; Second check).

Before relying on it: Public fit is chiefly Rolls-Royce-derived Siemens turbines, not proven for the requested machine; maker-endorsed authorization and exact cross-reference require written proof.
Contact: sales@vbr-turbinepartners.com | +31 88 010 9030 | Official contact page.

12 TransCanada Turbines | FIT 1/10

Canada / worldwide | Independent aero-derivative turbine parts provider
Route: Only if the turbine is Avon/RB211-derived

Basis: Company and independent power-industry profiles document turbine OEM-parts/service supply for Siemens/Rolls-Royce Avon and RB211 engines. (Product evidence; Second check).

Before relying on it: Aero-derivative engines differ from SGT5-2000E/V94.2. Do not send an RFQ for a heavy-frame unit without platform confirmation.
Contact: info@tcturbines.com | +1 403 219 6600 (recheck on official site) | Official contact page.

Mandatory RFQ and buying gate

Send the schedule and the **separate** A2A50182217 / PB0000135690 identity query to relevant sellers. For each offered line demand: (1) an exact manufacturer and revision cross-reference for both Siemens references; (2) documented factory-new, unused, never installed condition (exclude refurbished, repaired, exchange and undisclosed old stock); (3) original-manufacturer traceability, certificate of conformity and manufacturer date; (4) complete valve/actuator or kit contents and applicable tests, pressure and service ratings; (5) turbine-model/serial compatibility and written permission for any substitution; (6) lead time, warranty, country of origin, delivery terms and legal seller details. Verify any claimed OEM authorization directly through the original manufacturer's published partner channel before paying.

Safety boundary: The suggestion to copy worn seals or substitute a filter element is not a verified spare-part cross-reference. Do not install locally reverse-engineered fuel-gas-valve internals without the required engineering approval, test and certification evidence.

Ready-to-send inquiry

Subject: Factory-new turbine valves (9 lines / 10 units) + separate A2A50182217 repair-set identification. Please quote only new, unused, never-installed original-manufacturer parts for the attached nine-line schedule; no refurbished, repaired, exchange or undisclosed old-stock units. For each line identify the original valve/actuator manufacturer, both Siemens references, revision, assembly scope, turbine-model fit, traceability, CoC, production date, lead time and warranty. Separately, can you identify A2A50182217 and PB0000135690 from a manufacturer parts list, confirm whether they identify the same repair set, provide kit contents and quote it new? No substitution without written engineering approval.

Not counted as qualified resellers: Direct makers (Siemens Energy, Hartmann Valves and SOMAS); Pietro Fiorentini, whose external gas-line equipment is not a verified valve-kit substitute; and highly promoted stock claims from businesses whose independent registration or claimed certification could not be substantiated. Hartmann turbine-valve application; SOMAS turbine-cooling product.

An Ankerlig Majors pricing schedule (unverified portal lead) appeared in a search index but could not be opened here. Even if this tender belongs to Ankerlig, its plant-level SGT5-2000E association does not establish that A2A50182217 fits this turbine or any valve above.

Research limitation: public/indexed product pages and company/industry records were available for screening, but supplier sites could not be loaded directly from this session for live stock checks. The user-provided procurement snippet was not an original manufacturer's parts list. Reconfirm published contact details on each official company page before sending an inquiry. No supplier was contacted, and no availability, price or lead time is confirmed.

Direct contact URLs

If your phone's PDF viewer does not open the underlined links, select or copy these printed addresses instead.

Score Group / Score Energy: https://score-group.com/contact/

AP4 Group / AP+M: https://ap4.com/contact/

EthosEnergy: https://ethosenergy.com/contact

European Power Systems: https://europeanpowersystems.eu.com/contact/

CEDCO GmbH: https://www.cedco.de/contact.html

TTPS International: https://ttpsintl.com/contact-us/

Gas Turbine Services: https://gasturbineservices.com/contact-us/

Armour Valve: https://armourvalve.com/contact/

KLINGER Baltic: https://klinger.ee/en/

Zuercher Technik: https://zuercher.com/en/

VBR Turbine Partners: https://vbr-turbinepartners.com/contact/

TransCanada Turbines: https://www.tcturbines.com/