

RVSP

Dr. G.
Omprakash

Motivation

Power Density
Spectrum

Random Process: Spectral Characteristics



Dr. G. Omprakash

Assistant Professor, ECE, KLEF



Table of Contents

RVSP

Dr. G.
Omprakash

Motivation

Power Density
Spectrum

1 Motivation

2 Power Density Spectrum



RVSP

Dr. G.
Omprakash

Motivation

Power Density
Spectrum

Motivation



Spectral characteristics: Why do we need them?

RVSP

Dr. G.
Omprakash

Motivation

Power Density
Spectrum

- **Biomedical Signals:** They are random but have clear frequency content.
 - Take ECG data → show PSD → most energy lies below 40 Hz
 - Helps in designing filters (e.g., removing high-frequency noise or 50 Hz powerline interference).
- **Music vs Noise:** Why does music sound “structured” but noise sounds “random”?
 - Plot PSD of music vs white noise.
 - Music has spectral peaks (harmonics), noise has a flat spectrum.
- **Stock Market Returns:** Finance also treats returns as random processes.
 - Spectral analysis helps identify these dominant frequencies, which correspond to economic cycles or investor behaviors.
 - Time-domain analysis (like simple trend analysis) often misses these periodic components.



RVSP

Dr. G.
Omprakash

Motivation

Power Density
Spectrum

Power Density Spectrum



Why Power Density? Why not the Fourier transform?

RVSP

Dr. G.
Omprakash

Motivation

Power Density
Spectrum

- The spectral properties of a *deterministic* signal $x(t)$ are contained in its *Fourier transform*:
$$X(\omega) = \int_{-\infty}^{\infty} x(t)e^{-j\omega t} dt$$
- For a Fourier transform to exist: *deterministic* signal $x(t)$ must satisfy Dirichlet's conditions: **Absolutely integrable, Finite number of discontinuities, Finite number of maxima/minima**
- We cannot apply Fourier transform to *random process* $x(t)$
 - Dirichlet condition: **Absolute Integrability (Finite Energy) is not satisfied for random process $x(t)$**
- A stationary random process (like white noise, financial returns, etc.) is defined over all time and **never decays**.
 - Even if you take the Fourier Transform of one realization, that transform will differ for every realization — completely random and not useful.



Power Spectral Density (PSD)

RVSP

Dr. G.
Omprakash

Motivation

Power Density
Spectrum

- What we actually care about is the average frequency content of the process across all realizations — its *spectral characteristics*.
- Instead of taking the FT of the random process itself, we take the FT of its autocorrelation function $R_X(\tau) = E[X(t)X(t + \tau)]$.

$$S_{XX}(\omega) = \int_{-\infty}^{\infty} R_{XX}(\tau) e^{-j\omega\tau} d\tau$$

- $R_{XX}(\tau)$ is deterministic and integrable



Power Density spectrum: Derivation

RVSP

Dr. G.
Omprakash

Motivation

Power Density
Spectrum

Consider a random process $X(t)$. Let us take one sample function $x(t)$. Let $x_T(t)$ be portion of sample function that exists between $-T$ and T

$$x_T(t) = \begin{cases} x(t) & -T < t < T \\ 0 & \text{otherwise} \end{cases} \quad (1)$$

Since $x_T(t)$ is finite duration, it is absolutely integrable and the Fourier transform can be defined

$$X_T(\omega) = \int_{-T}^T x_T(t) e^{-j\omega t} dt = \int_{-T}^T x(t) e^{-j\omega t} dt \quad (2)$$



Power Density spectrum: Derivation

RVSP

Dr. G.
Omprakash

Motivation

Power Density
Spectrum

We are interested in Power..First calculate energy and divide it by time duration to get power. The energy contained in $x(t)$ in the interval $(-T, T)$ is

$$E(T) = \int_{-T}^{T} x^2(t) dt \quad (3)$$

Using Parseval's theorem, the relation between $x(t)$ and its Fourier transform $X_T(\omega)$ is given by

$$E(T) = \int_{-T}^{T} x^2(t) dt = \frac{1}{2\pi} \int_{-\infty}^{\infty} |X_T(\omega)|^2 d\omega \quad (4)$$



RVSP

Dr. G.
Omprakash

Motivation

Power Density
Spectrum

The average power $P(T)$ is given by

$$P(T) = \frac{1}{2T} \int_{-T}^T x^2(t) dt = \frac{1}{2\pi} \int_{-\infty}^{\infty} \frac{|X_T(\omega)|^2}{2T} d\omega \quad (5)$$

$\frac{|X_T(\omega)|^2}{2T}$ is the power density spectrum for a finite duration sample function $x(t)$. It varies for different sample functions of $X(t)$. So $P(T)$ is a random quantity. Take the expected value of $P(T)$ (with $T \rightarrow \infty$) to get the average power of the random process

$$P_{XX} = \lim_{T \rightarrow \infty} \frac{1}{2T} \int_{-T}^T E[X^2(t)] dt = \frac{1}{2\pi} \int_{-\infty}^{\infty} \lim_{T \rightarrow \infty} \frac{E|X_T(\omega)|^2}{2T} d\omega \quad (6)$$



RVSP

Dr. G.
Omprakash

Motivation

Power Density
Spectrum

Two observations from the previous equation:
(1). Average power of the random process $X(t)$ is given by the time average of its second moment

$$P_{XX} = \lim_{T \rightarrow \infty} \frac{1}{2T} \int_{-T}^T E[X^2(t)] = A[E[X^2(t)]]$$

P_{XX} can also be obtained from the frequency domain using the equation

$$P_{XX} = \frac{1}{2\pi} \int_{-\infty}^{\infty} S_{XX}(\omega) d\omega = \int_{-\infty}^{\infty} S_{XX}(f) df \quad (7)$$

where $S_{XX}(\omega)$ is the PSD given by

$$S_{XX}(\omega) = \lim_{T \rightarrow \infty} \frac{E[|X_T(\omega)|^2]}{2T} \quad (8)$$



Power Density Spectrum

RVSP

Dr. G.
Omprakash

Motivation

Power Density
Spectrum

The power density spectrum for the random process is given by

$$S_{XX}(\omega) = \lim_{T \rightarrow \infty} \frac{E[|X_T(\omega)|^2]}{2T}$$



Properties of PSD

RVSP

Dr. G.
Omprakash

Motivation

Power Density
Spectrum

- The power density spectrum $S_{XX}(\omega)$ is a real value and non-negative function:
 $S_{XX}(\omega) \geq 0$
- The power density spectrum is an even function in ω : $S_{XX}(\omega) = S_{XX}(-\omega)$

$$S_{XX}(\omega) = \int_{-\infty}^{\infty} R_{XX}(\tau) e^{-j\omega\tau} d\tau \implies S_{XX}(-\omega) = \int_{-\infty}^{\infty} R_{XX}(\tau) e^{j\omega\tau} d\tau$$

Replace τ by $-\tau$

$$S_{XX}(-\omega) = \int_{\infty}^{-\infty} R_{XX}(-\tau) e^{-j\omega\tau} (-d\tau) = \int_{-\infty}^{\infty} R_{XX}(-\tau) e^{-j\omega\tau} d\tau$$

Since $R_{XX}(-\tau) = R_{XX}(\tau)$

$$S_{XX}(-\omega) = \int_{-\infty}^{\infty} R_{XX}(\tau) e^{-j\omega\tau} d\tau = S_{XX}(\omega)$$



Properties of PSD

RVSP

Dr. G.
Omprakash

Motivation

Power Density
Spectrum

- The power density spectrum is a real function
 - From the definition of PSD eqn (8) $|X_T(\omega)|^2$ is real so PSD is also real
- Average power is equal to the integral of $S_{XX}(\omega)$

$$P_{XX} = \frac{1}{2\pi} \int_{-\infty}^{\infty} S_{XX}(\omega) d\omega$$

- $S_{\dot{X}\dot{X}}(\omega) = \omega^2 S_{XX}(\omega)$
 - The power density spectrum of the derivative $\dot{X} = dX(t)/dt$ is ω^2 times the power spectrum of $X(t)$
- Power spectrum and the autocorrelation function form a Fourier transform pair

$$S_{XX}(\omega) = \int_{-\infty}^{\infty} R_{XX}(\tau) e^{-j\omega\tau} d\tau; \quad R_{XX}(\tau) = \frac{1}{2\pi} \int_{-\infty}^{\infty} S_{XX}(\omega) e^{j\omega\tau} d\omega;$$



Relationship b/w power spectrum and autocorrelation

RVSP

Dr. G.
Omprakash

Motivation

Power Density
Spectrum

Q: Derive the relationship between the power density spectrum and the autocorrelation function

We know that

$$S_{XX}(\omega) = \lim_{T \rightarrow \infty} \frac{E[|X_T(\omega)|]^2}{2T}; \text{ where } X_T(\omega) = \int_{-T}^T x_T(t)e^{-j\omega t} dt$$

Substitute $|X_T(\omega)|^2 = X_T^*(\omega)X_T(\omega)$ in the power density equation

$$\begin{aligned} S_{XX}(\omega) &= \lim_{T \rightarrow \infty} E \left[\frac{1}{2T} \int_{-T}^T X(t_1)e^{j\omega t_1} dt_1 \int_{-T}^T X(t_2)e^{-j\omega t_2} dt_2 \right] \\ &= \lim_{T \rightarrow \infty} \frac{1}{2T} \int_{-T}^T \int_{-T}^T E[X(t_1)X(t_2)] e^{-j\omega(t_2-t_1)} dt_2 dt_1 \end{aligned}$$



Relationship b/w power spectrum and autocorrelation

RVSP

Dr. G.
Omprakash

Motivation

Power Density
Spectrum

We know that $E[X(t_1)X(t_2)] = R_{XX}(t_1, t_2)$. The PSD becomes

$$S_{XX}(\omega) = \lim_{T \rightarrow \infty} \frac{1}{2T} \int_{-T}^T \int_{-T}^T R_{XX}(t_1, t_2) e^{-j\omega(t_2-t_1)} dt_2 dt_1 \quad (9)$$

Take the inverse Fourier transform of $S_{XX}(\omega)$

$$\mathcal{F}^{-1}[S_{XX}(\omega)] = \frac{1}{2\pi} \int_{-\infty}^{\infty} S_{XX}(\omega) e^{j\omega\tau} d\omega \quad (10)$$

$$= \frac{1}{2\pi} \int_{-\infty}^{\infty} \lim_{T \rightarrow \infty} \frac{1}{2T} \int_{-T}^T \int_{-T}^T R_{XX}(t_1, t_2) e^{-j\omega(t_2-t_1-\tau)} dt_2 dt_1 d\omega \quad (11)$$



Relationship b/w power spectrum and autocorrelation

RVSP

Dr. G.
Omprakash

Motivation
Power Density
Spectrum

$$\begin{aligned} F^{-1}[S_{XX}(\omega)] &= \lim_{T \rightarrow \infty} \frac{1}{2T} \int_{-T}^T \int_{-T}^T R_{XX}(t_1, t_2) \frac{1}{2\pi} \left[\int_{-\infty}^{\infty} e^{-j\omega(t_2 - t_1 - \tau)} d\omega \right] dt_2 dt_1 \\ &= \lim_{T \rightarrow \infty} \frac{1}{2T} \int_{-T}^T \int_{-T}^T R_{XX}(t_1, t_2) \frac{1}{2\pi} [2\pi\delta(t_2 - t_1 - \tau)] dt_2 dt_1 \\ &= \lim_{T \rightarrow \infty} \frac{1}{2T} \int_{-T}^T R_{XX}(t_1, t_1 + \tau) dt_1 = A[R_{XX}(t, t + \tau)] \end{aligned}$$

For a wide-sense stationary process $A[R_{XX}(t, t + \tau)] = R_{XX}(\tau)$.



RVSP

Dr. G.
Omprakash

Motivation

Power Density
Spectrum

Relationship b/w power spectrum and autocorrelation

Therefore

$$F^{-1}[S_{XX}(\omega)] = R_{XX}(\tau) \implies S_{XX}(\omega) = F[R_{XX}(\tau)] \quad (12)$$

The power spectral density is Fourier transform of autocorrelation function

$$S_{XX}(\omega) = \int_{-\infty}^{\infty} R_{XX}(\tau) e^{-j\omega\tau} d\tau; \quad (13)$$

$$R_{XX}(\tau) = \frac{1}{2\pi} \int_{-\infty}^{\infty} S_{XX}(\omega) e^{j\omega\tau} d\omega; \quad (14)$$

The above two equations are called the *Weiner-Khintchine relations*



Problems

RVSP

Dr. G.
Omprakash

Motivation

Power Density
Spectrum

If $R_{XX}(\tau) = ae^{-b|\tau|}$, find the spectral density function, where a and b are constants



Problems

RVSP

Dr. G.
Omprakash

Motivation

Power Density
Spectrum

If $R_{XX}(\tau) = ae^{-b|\tau|}$, find the spectral density function, where a and b are constants

$$S_{XX}(\omega) = F[R_{XX}(\tau)] = a \left[\int_{-\infty}^0 e^{(b-j\omega)\tau} d\tau + \int_0^{\infty} e^{-(b+j\omega)\tau} d\tau \right] \quad (15)$$

$$= \frac{2ab}{b^2 + \omega^2} \quad (16)$$



Problems

RVSP

Dr. G.
Omprakash

Motivation

Power Density
Spectrum

If $R_{XX}(\tau) = (A^2/2)\cos(\omega_0\tau)$, find the spectral density, where A and ω_0 are constants



Problems

RVSP

Dr. G.
Omprakash

Motivation

Power Density
Spectrum

If $R_{XX}(\tau) = (A^2/2)\cos(\omega_0\tau)$, find the spectral density, where A and ω_0 are constants

$$S_{XX}(\omega) = \frac{A^2\pi}{2} [\delta(\omega - \omega_0) + \delta(\omega + \omega_0)] \quad (17)$$



RVSP

Dr. G.
Omprakash

Motivation

Power Density
Spectrum

Acknowledge various sources for the images.
Thankyou