








test and programming steps:
 1. detect badge
 2. detect battery
 3. check RESET pull-up
 4. check capsense resistor
 5. check capsense capacitance
 6. check MCU pins
 7. check JTAG connectivity
 8. program
 9. verify
 10. run





top PCB

back PCB



This header allows connection of a GoodFET instead of a GreatFET.

With a GoodFET connected, tests and test indicator LEDs are inactive, but the GoodFET can be used to communicate with and program the badge microcontroller.



License: BSD-3-Clause
 Copyright 2018 Great Scott Gadgets

Sheet: /
 File: working.kicad_sch

Title: ToorCamp 2018 Badge Test Jig

Size: A4 Date: 2018-06-10
 KiCad E.D.A. eeschema 7.0.6

Rev:
 Id: 1/1