







1. DC Out is not for input!
2. Use 5-12V DC 2.1mm or 5V DC from USB port to charge 4.2v LiIon
3. Use 9-12V DC 2.1mm to charge 8.4v LiIon
4. CHG LED will slowly blink when charging is done!
5. Chip will auto. slow down when too hot
6. Adj. RProg = $\frac{13.2 - 11.5 \cdot I_{reg}}{1.2 \cdot I_{reg} - 1.2}$
7. 10K NTC can be used for 10K NTC


Sheet: Bottom copper File: working.kicad_pcb		
Title:		
Size: A4	Date: 2023-08-03_17-21-23	Rev:
KiCad E.D.A. 7.0.6-7.0.6-ubuntu22.04.1 + KiBot v1.6.3		Id: 2/6





Sheet: Front courtyard area		
File: working.kicad_pcb		
Title:		
Size: A4	Date: 2023-08-03_17-21-23	Rev:
KiCad E.D.A. 7.0.6-7.0.6-ubuntu22.04.1 + KiBot v1.6.3		Id: 4/6





Sheet: Front documentation
File: working.kicad_pcb

Title:

Size: A4	Date: 2023-08-03_17-21-23
KiCad E.D.A. 7.0.6-7.0.6-ubuntu22.04.1 + KiBot v1.6.3	

Rev:
Id: 6/6