



NOTE: FXOS8700CQ only supports a point-to-point SPI protocol, with only one master and one slave device present on the bus. As such, only I2C is broken out here.


3-Axis Gyroscope




5V/3V Level Shifting




3-Axis Accelerometer/Magnetometer




Header Pins




3.3V VREG



Accel RST Inverter



Shared Reset Line



ISSUE	#{COMPANY}		© 2015
DRAWN	#{DRAWN}		REV
CHECKED	#{CHECKED}		#{REV}
DATE	#{CURRENT_DATE}		DRG No
DATE	#{DATE}		#{DRGNO}
FILE:	#{PROJECTNAME}		PAGE: #{#}/#{##}

Title:		Size: User		Date:		Rev:	
KiCad E.D.A.		kicad-cli		7.0.6-7.0.6-ubuntu22.04.1		Id: 1/1	