


Haptic Motor Driver and LRA Vibration Motor




JUMPER-SMT_2-NC_TRACE_SILK

Cut trace to remove LED.




Jumpers




Cut traces to remove pull up resistors.

Decoupling Caps Near P4 (VDD)



Qwiic Connectors and Header

Qwiic Bus Isolate - cut this trace to separate the qwiic bus power (3.3V) from the board. Note: I2C is still pulled up to 3.3V.



Released under the Creative Commons Attribution Share-Alike 4.0 License
<https://creativecommons.org/licenses/by-sa/4.0/>

TITLE: \${PROJECTNAME}		Special Instructions
Design by: \${DESIGNER}		REV: \${REV}
Date: \${CURRENT-DATE}		Sheet: \${#}/\${##}

Size: User Date: KiCad E.D.A. eeschema 7.0.6 Rev: Id: 1/1