Type 2 – (Supply, Measure->GND)
Type 3 – (Supply, Measure->GND, GND)
Type 4 – (Supply, Measure 1, Measure 2, GND), not supported



DRILL DRILL

DRILL DRILL

Copyright Tinkerforge GmbH 2013.
This documentation describes Open Hardware and is licensed under the CERN OHL v. 1.1.
You may redistribute and modify this documentation under the terms of the CERN OHL v.1.1. (http://ohwr.org/cernohl). This documentation is distributed WITHOUT ANY EXPRESS OR IMPLIED WARRANTY, INCLUDING OF MERCHANTABILITY, SATISFACTORY QUALITY AND FITNESS FOR A PARTICULAR PURPOSE. Please see the CERN OHL v.1.1 for applicable conditions

Copyright (©) 2013, B.Nordmeyer <bastian@tinkerforge.com>
Licensed under CERN OHL v.1.1

Tinkerforge GmbH

Sheet: /
File: working.kicad_sch

Title: Industrial Dual 0–20mA Bricklet

Size: A4	Date: 25 jun 2013	**Rev: 1.0**
KiCad E.D.A. eeschema 7.0.6		Id: 1/1