
Half Bridge Drivers
Feedback Current Amplifiers
For more information about JP2-4, refer to the hookup guide.
Power Supply
NOTE: For VCC of 5V, close JP5 to bypass the DC/DC converter
Note: For inductive loads, such as motors, a capacitor >100uF (2.5mm pin pitch) may need to be installed at C15.
Protection Diodes
Connectors
VCC : 5-28VDC
MC33926
U1
U2
U3
U4
R-78E5.0-1.0
JP1
JUMPER-SMT_3_1-NC_TRACE_SILK
JP2
JP3
JP4
JP5
JUMPER-SMT_2_NC_PASTE_NO-SILK
JUMPER-SMT_2_NO_SILK
OPAMP-DUALU
IC1C
IC2C
J1
J3
Slew Rate:
GND - SLOW - 3 us
3.3V - FAST - 1.45 us
open hardware
sparkfun
Released under the Creative Commons Attribution Share-Alike 4.0 License
https://creativecommons.org/licenses/by-sa/4.0/
TITLE: ${PROJECTNAME}
Design by: Alex Wende
REV: v10
Sheet: /
File: working.kicad_sch
Date: ${CURRENT_DATE}
Sheet: ${#}/${##}
Title:
Size: User
Date:
Rev:
KiCad E.D.A. kicad-cli 7.0.6-7.0.6-ubuntu22.04.1
Id: 1/1