

Vehicle Damage Assessment Report

Report Date: 2025-08-21 16:38:25


Make	kia
Model	sportage
Year	2017
VIN	UNKNOWN

AI-Generated Detailed Report:

Vehicle Damage Assessment Report Report Date: 2025-08-21 Vehicle Information: - Make: Kia - Model: Sportage - Year: 2017 - VIN: UNKNOWN Detected Damages: - Broken headlight assembly with hood damage. Detection confidence: 92%. Localization accuracy: 10%. Estimated repair cost: \$450-850 USD. See attached image. Summary of Estimated Repair Costs: - Headlight assembly and hood: \$450-850 USD

Annotated Images:





hif

Inspector Signature