

Vehicle Damage Assessment Report

Report Date: 2025-08-23 14:45:19

Name	kia_name
Surname	kia_surname
Make	kia
Model	rio
Year	2021
VIN	KIA_VIN

AI-Generated Detailed Report:

Vehicle Damage Assessment Report Report Date: 2025-08-23 Prepared for: kia_name kia_surname

Vehicle Information: - Make: Kia - Model: Rio - Year: 2021 - VIN: KIA_VIN

Detected Damages: - Dent in front door (conf=0.94, IoU=0.40) — Estimated Cost: \$427.58 (See attached image) - Scratch in front door (conf=0.48, IoU=0.09) — Estimated Cost: \$428.62 (See attached image)

Summary of Estimated Repair Costs: - Front door dent repair and refinishing: \$427.58 - Front door scratch repair and refinishing: \$428.62 Total Estimated Repair Cost: \$856.20

Annotated Images:






YOLO Predictions



YOLO Predictions + Masks



huf

Inspector Signature