- CONNECT USB MINI-B TO HOST PC -VIRTUAL COM PORT SHOULD BE PECOGNIZED - Ub pin 3 = 5.0V ± 5% = 4.75V to 5.25V - Ub pm 7 or 4 = 33V ± 1% = 3.26V to 3.34V

-LOAD PROPELLISE TOOL & "IDENTIFY PROCESSOR=

- PROBRAM EEPPON W JABULATOR GODE

-ON PESET, LED = ORANGE THEN LED : GREEN

- OPEN CON PORT VIA PARALLAX SEPIAL TERMINAL OR OTHER TERMINAL PROGRAM (115.2 Klops, 8NI)

- "ENTER" KEY WILL PETURN A ": " PROMPT

-"V" COMMAND - VERIFY VADJ MATCHES ENTERED VOLTAGE

-"W" GOMMAND - VERIFY CHJ3... CHD CAN BE SET TO 0x000000 AND 0xFFFFFF

-"R= COMMAND - CA123... CAID = D×FFFFFF WHEN NOTHING CONNECTED

- PUL EACH CHANNEL TO GND & VERIFY "CASCADING ZERO=

- DONE }