## **FLYSKY**

## Release Notes for FS-G11P Transmitter Firmware/ FS-G11P 软件版本更新记录

新增功能: 无

修改功能: 1. 修复了编程混控的 BUG。

2. 修复了智能车控无法正常使用的问题。

3. 修复了其他已知问题。

▶ 特殊变化: • 无

## 注意事项

• 发射机固件更新完成后,模型数据会被复位。在固件更新之前,可通过遥控管家进行数据备份,然后导入该版本使用。

- 使用遥控管家备份数据时,需注意以下版本兼容性问题: 遥控管家 3.0.4 版本和 3.3.5 版本目前互不兼容。因此,导出和导入模型数据时,必须使用相同版本的遥控管家进行操作。
- 发射机固件更新完成后,需完成摇杆校准。
- 发射机和接收机更新完成后需要重新对码。

-----

New functions: • None

Modified functions:

Fixed the bug in Programming Mix.

2. Fixed the issue where the SVC was not functioning properly.

3. Fixed other known issues.

Special changes: • None

## Notes

- After the transmitter firmware update is finished, the model data will be reset. It is recommended to back up data through the FlySkyAssistant, and then import the data after the update is finished.
- When using FlySkyAssistant to back up data, please note the following version compatibility issues: FlySkyAssistant versions 3.0.4 and 3.3.5 are currently incompatible with each other. Therefore, when exporting and importing model data, you must use the same version of FlySkyAssistant for the operation.
- Done the **Stick Calibration** function after the transmitter firmware update is finished.
- The transmitter and the receiver need to be rebound after the update is finished.