Phase rotation by medium and instrument

All symbols are centred on the measured overtone order · error bars: standard deviation of three sweeps