MATCHRITE 552 SPECTROPHOTOMETER

Proprietary Notice

The information contained in this manual is derived from patent and proprietary data of X-Rite, Incorporated. The contents of this manual are the property of X-Rite, Incorporated and are copyrighted. Any reproduction in whole or part is strictly prohibited. Publication of this information does not imply any rights to reproduce or use this manual for any purpose other than installing, operating, or maintaining this

Getting StartedThis document is designed to get you familiarized with your


Charge the Battery Pack

Only use the AC Adapter supplied or the optional battery charger (X-Rite P/N 500CHG). The battery pack must remain in the instrument at all times to operate.

Before initial "remote" use of the instrument, charge the battery pack for approximately three hours. However, if immediate use is required, the instrument can be operated "tethered" to the AC adapter during battery charging.

MATCHRITE 552 SPECTROPHOTOMETER

GETTING STARTED



MATCHRITE 552 SPECTROPHOTOMETER

NOTE: