# Release Notes

 $Version\ 1.5.0$ 

# Revision History

Revision	Description of Change	Date
v1.0.1	Initial creation	5/2016
v1.1.0	Updates for 1.1 release	3/2017
v1.2.0	Updates for 1.2 release	8/2017
v1.3.0	Updates for 1.3 release	1/2018
v1.3.1	Updates for 1.3.1 release	3/2018
v1.4.0	Updates for 1.4.0 release and moved previous to appendices	10/2018
v1.5.0	Updates for 1.5.0 release	4/2019

# Table of Contents

Ι	Enhancements	1					
	-1 New Digital Radio Controller Front-End Control Paradigm	1					
	New Time-Based Protocol ("ComplexShortWithMetadata-prot") (Technology Preview)						
	-3 New Time-Based Assets Project ("assets_ts") (Technology Preview)						
	-4 New HDL Worker Port Interfaces						
	-5 ocpidev Improvements						
	-6 New "Zed" RCC Platform: xilinx13_4						
	-7 gdb and rsync Provided on xilinx13_3 and xilinx13_4 RCC Platforms	2					
	N1 137 /						
П	Changes and Notes	2					
	I-1 Deprecation of the "Readable" Attribute						
	I-2 Deprecation of Zipper RF Interface Board						
	I-3 E3xx PPS Discipline						
	I-4 "new_project_source" script removed						
	I-5 RCC Worker Parameter Macros Stricter						
	I-6 ocpidev Changes						
	I-7 "myClock" HDL Code Deprecated / Removed						
	I-8 Initrastructure Owds Moved						
	I-10 HDL Wrapper Changes						
	1-10 HDL Wrapper Changes	0					
$\mathbf{II}$	Major Known Deficiencies	3					
	II-1 "udev" Radio Rules Sometimes Does Not Work						
	II-2 Emulators Not Constrained To Specific Containers In Unit Tests	3					
	II-3 Provided LiquidDSP Build May Link Incorrectly						
	II-4 Previously Documented Deficiencies	4					
A	pendices	5					
Δ							
	Release 1.4.0	5					
<b>.</b> .	Release 1.4.0	<b>5</b> 5					
<b>11</b>	A-I Enhancements	5					
<b>.</b>	A-I Enhancements	5 5					
<b>11</b>	A-I. Enhancements	5 5 5					
11	A-I. Enhancements	5 5 5					
11	A-I.1 Support for Ettus E310 Platform  A-I.2 Component Unit Test Enhancements  A-I.3 Multi-Slave Proxy Support  A-I.4 Transmit Blanking / Powerdown for DACs	5 5 5 5					
11	A-I.1 Support for Ettus E310 Platform  A-I.2 Component Unit Test Enhancements  A-I.3 Multi-Slave Proxy Support  A-I.4 Transmit Blanking / Powerdown for DACs  A-I.5 ocpidev Improvements	5 5 5 5 5					
11	A-I.1 Support for Ettus E310 Platform  A-I.2 Component Unit Test Enhancements  A-I.3 Multi-Slave Proxy Support  A-I.4 Transmit Blanking / Powerdown for DACs  A-I.5 ocpidev Improvements  A-I.6 VHDL-Native Pattern and Capture HDL Workers	5 5 5 5 5					
71	A-I.1 Support for Ettus E310 Platform  A-I.2 Component Unit Test Enhancements  A-I.3 Multi-Slave Proxy Support  A-I.4 Transmit Blanking / Powerdown for DACs  A-I.5 ocpidev Improvements  A-I.6 VHDL-Native Pattern and Capture HDL Workers  A-I.7 New Documentation RPM	5 5 5 5 5					
71	A-I.1 Support for Ettus E310 Platform  A-I.2 Component Unit Test Enhancements  A-I.3 Multi-Slave Proxy Support  A-I.4 Transmit Blanking / Powerdown for DACs  A-I.5 ocpidev Improvements  A-I.6 VHDL-Native Pattern and Capture HDL Workers	5 5 5 5 5 6 6					
	A-I.1 Support for Ettus E310 Platform  A-I.2 Component Unit Test Enhancements  A-I.3 Multi-Slave Proxy Support  A-I.4 Transmit Blanking / Powerdown for DACs  A-I.5 ocpidev Improvements  A-I.6 VHDL-Native Pattern and Capture HDL Workers  A-I.7 New Documentation RPM  A-I.8 Zynq Parts Defined	5 5 5 5 5 6 6					
	A-I.1 Support for Ettus E310 Platform  A-I.2 Component Unit Test Enhancements  A-I.3 Multi-Slave Proxy Support  A-I.4 Transmit Blanking / Powerdown for DACs  A-I.5 ocpidev Improvements  A-I.6 VHDL-Native Pattern and Capture HDL Workers  A-I.7 New Documentation RPM  A-I.8 Zynq Parts Defined  A-II Changes and Notes	5 5 5 5 6 6 6					
	A-I.1 Support for Ettus E310 Platform  A-I.2 Component Unit Test Enhancements  A-I.3 Multi-Slave Proxy Support  A-I.4 Transmit Blanking / Powerdown for DACs  A-I.5 ocpidev Improvements  A-I.6 VHDL-Native Pattern and Capture HDL Workers  A-I.7 New Documentation RPM  A-I.8 Zynq Parts Defined  A-II.1 I/Q Data Ordering	5 5 5 5 5 6 6 6 6					
	A-I.1 Support for Ettus E310 Platform  A-I.2 Component Unit Test Enhancements  A-I.3 Multi-Slave Proxy Support  A-I.4 Transmit Blanking / Powerdown for DACs  A-I.5 ocpidev Improvements  A-I.6 VHDL-Native Pattern and Capture HDL Workers  A-I.7 New Documentation RPM  A-I.8 Zynq Parts Defined  A-II Changes and Notes  A-II.1 I/Q Data Ordering  A-II.2 Upgrade Notes	55 55 55 56 66 66 66 67					
	A-I.1 Support for Ettus E310 Platform  A-I.2 Component Unit Test Enhancements  A-I.3 Multi-Slave Proxy Support  A-I.4 Transmit Blanking / Powerdown for DACs  A-I.5 ocpidev Improvements  A-I.6 VHDL-Native Pattern and Capture HDL Workers  A-I.7 New Documentation RPM  A-I.8 Zynq Parts Defined  A-II.1 Changes and Notes  A-II.1 I/Q Data Ordering  A-II.2 Upgrade Notes  A-II.3 Significant SD Card Layout Changes	5 5 5 5 5 6 6 6 6 6 7 7					
	A-I.1 Support for Ettus E310 Platform  A-I.2 Component Unit Test Enhancements  A-I.3 Multi-Slave Proxy Support  A-I.4 Transmit Blanking / Powerdown for DACs  A-I.5 ocpidev Improvements  A-I.6 VHDL-Native Pattern and Capture HDL Workers  A-I.7 New Documentation RPM  A-I.8 Zynq Parts Defined  A-II Changes and Notes  A-II.1 I/Q Data Ordering  A-II.2 Upgrade Notes  A-II.3 Significant SD Card Layout Changes  A-II.4 Intel Quartus and Quartus Pro Version Change	5 5 5 5 5 6 6 6 6 6 7 7					
	A-I.1 Support for Ettus E310 Platform  A-I.2 Component Unit Test Enhancements  A-I.3 Multi-Slave Proxy Support  A-I.4 Transmit Blanking / Powerdown for DACs  A-I.5 ocpidev Improvements  A-I.6 VHDL-Native Pattern and Capture HDL Workers  A-I.7 New Documentation RPM  A-I.8 Zynq Parts Defined  A-II.1 I/Q Data Ordering  A-II.2 Upgrade Notes  A-II.3 Significant SD Card Layout Changes  A-II.4 Intel Quartus and Quartus Pro Version Change  A-II.5 New Input Port ZLM-Handling Primitive	5 5 5 5 5 6 6 6 6 6 7 7 7					
	A-I. Support for Ettus E310 Platform  A-I.2 Component Unit Test Enhancements  A-I.3 Multi-Slave Proxy Support  A-I.4 Transmit Blanking / Powerdown for DACs  A-I.5 ocpidev Improvements  A-I.6 VHDL-Native Pattern and Capture HDL Workers  A-I.7 New Documentation RPM  A-I.8 Zynq Parts Defined  A-II Changes and Notes  A-II.1 I/Q Data Ordering  A-II.2 Upgrade Notes  A-II.3 Significant SD Card Layout Changes  A-II.4 Intel Quartus and Quartus Pro Version Change  A-II.5 New Input Port ZLM-Handling Primitive  A-II.6 Change in QDAC/QDAC_TS Component Spec  A-II.7 Change in ocpidev Default Output and Scope  A-II.8 Rounding and Truncation in qdac-spec Workers	55 55 55 56 66 66 67 77 77 77					
7.	A-II Enhancements A-I.1 Support for Ettus E310 Platform A-I.2 Component Unit Test Enhancements A-I.3 Multi-Slave Proxy Support A-I.4 Transmit Blanking / Powerdown for DACs A-I.5 ocpidev Improvements A-I.6 VHDL-Native Pattern and Capture HDL Workers A-I.7 New Documentation RPM A-I.8 Zynq Parts Defined A-II Changes and Notes A-II.1 I/Q Data Ordering A-II.2 Upgrade Notes A-II.3 Significant SD Card Layout Changes A-II.4 Intel Quartus and Quartus Pro Version Change A-II.5 New Input Port ZLM-Handling Primitive A-II.6 Change in QDAC/QDAC_TS Component Spec A-II.7 Change in ocpidev Default Output and Scope	5 5 5 5 5 6 6 6 6 6 7 7 7 7 7					
	A-I.1 Support for Ettus E310 Platform  A-I.2 Component Unit Test Enhancements  A-I.3 Multi-Slave Proxy Support  A-I.4 Transmit Blanking / Powerdown for DACs  A-I.5 ocpidev Improvements  A-I.6 VHDL-Native Pattern and Capture HDL Workers  A-I.7 New Documentation RPM  A-I.8 Zynq Parts Defined  A-II. Changes and Notes  A-II.1 I/Q Data Ordering  A-II.2 Upgrade Notes  A-II.3 Significant SD Card Layout Changes  A-II.4 Intel Quartus and Quartus Pro Version Change  A-II.5 New Input Port ZLM-Handling Primitive  A-II.6 Change in QDAC/QDAC_TS Component Spec  A-II.7 Change in ocpidev Default Output and Scope  A-II.8 Rounding and Truncation in qdac-spec Workers  A-II.9 HDL Workers Failing Unit Tests That Previously Passed  A-II.10 New Framework Build System	5 5 5 5 5 6 6 6 6 6 7 7 7 7 7 7 7 7 8					
	A-I.1 Support for Ettus E310 Platform A-I.2 Component Unit Test Enhancements A-I.3 Multi-Slave Proxy Support A-I.4 Transmit Blanking / Powerdown for DACs A-I.5 ocpidev Improvements A-I.6 VHDL-Native Pattern and Capture HDL Workers A-I.7 New Documentation RPM A-I.8 Zynq Parts Defined A-II Changes and Notes A-II.1 I/Q Data Ordering A-II.2 Upgrade Notes A-II.3 Significant SD Card Layout Changes A-II.4 Intel Quartus and Quartus Pro Version Change A-II.5 New Input Port ZLM-Handling Primitive A-II.6 Change in QDAC/QDAC_TS Component Spec A-II.7 Change in ocpidev Default Output and Scope A-II.8 Rounding and Truncation in qdac-spec Workers A-II.9 HDL Workers Failing Unit Tests That Previously Passed	5 5 5 5 5 6 6 6 6 6 7 7 7 7 7 7 7 7 8 8 8 8 8 8 8					
2.	A-I.1 Support for Ettus E310 Platform  A-I.2 Component Unit Test Enhancements  A-I.3 Multi-Slave Proxy Support  A-I.4 Transmit Blanking / Powerdown for DACs  A-I.5 ocpidev Improvements  A-I.6 VHDL-Native Pattern and Capture HDL Workers  A-I.7 New Documentation RPM  A-I.8 Zynq Parts Defined  A-II. Changes and Notes  A-II.1 I/Q Data Ordering  A-II.2 Upgrade Notes  A-II.3 Significant SD Card Layout Changes  A-II.4 Intel Quartus and Quartus Pro Version Change  A-II.5 New Input Port ZLM-Handling Primitive  A-II.6 Change in QDAC/QDAC_TS Component Spec  A-II.7 Change in ocpidev Default Output and Scope  A-II.8 Rounding and Truncation in qdac-spec Workers  A-II.9 HDL Workers Failing Unit Tests That Previously Passed  A-II.10 New Framework Build System	55 55 55 56 66 66 66 67 77 77 77 77 77 88 88 88					
2.	A-I.1 Support for Ettus E310 Platform  A-I.2 Component Unit Test Enhancements  A-I.3 Multi-Slave Proxy Support  A-I.4 Transmit Blanking / Powerdown for DACs  A-I.5 ocpidev Improvements  A-I.6 VHDL-Native Pattern and Capture HDL Workers  A-I.7 New Documentation RPM  A-I.8 Zynq Parts Defined  A-II Changes and Notes  A-II.1 I/Q Data Ordering  A-II.2 Upgrade Notes  A-II.3 Significant SD Card Layout Changes  A-II.4 Intel Quartus and Quartus Pro Version Change  A-II.5 New Input Port ZLM-Handling Primitive  A-II.6 Change in QDAC/QDAC_TS Component Spec  A-II.7 Change in ocpidev Default Output and Scope  A-II.8 Rounding and Truncation in qdac-spec Workers  A-II.9 HDL Workers Failing Unit Tests That Previously Passed  A-II.11New RCC Platform Configuration  A-III.11New RCC Platform Configuration  A-III.11 ZedBoard IP Required Even In Standalone Mode	55 55 55 56 66 66 66 67 77 77 77 77 77 88 88 88 88					
	A-I.1 Support for Ettus E310 Platform A-I.2 Component Unit Test Enhancements A-I.3 Multi-Slave Proxy Support A-I.4 Transmit Blanking / Powerdown for DACs A-I.5 ocpidev Improvements A-I.6 VHDL-Native Pattern and Capture HDL Workers A-I.7 New Documentation RPM A-I.8 Zynq Parts Defined A-II Changes and Notes A-II.1 I/Q Data Ordering A-II.2 Upgrade Notes A-II.3 Significant SD Card Layout Changes A-II.4 Intel Quartus and Quartus Pro Version Change A-II.5 New Input Port ZLM-Handling Primitive A-II.6 Change in QDAC/QDAC.TS Component Spec A-II.7 Change in ocpidev Default Output and Scope A-II.8 Rounding and Truncation in qdac-spec Workers A-II.9 HDL Workers Failing Unit Tests That Previously Passed A-II.10New Framework Build System A-II.11New RCC Platform Configuration A-IIIMajor Known Deficiencies A-III.1 ZedBoard IP Required Even In Standalone Mode A-III.2 Connection Direction In GUI Assumes XML order	55 55 55 56 66 66 66 77 77 77 77 77 78 88 88 88 88					
	A-I.1 Support for Ettus E310 Platform  A-I.2 Component Unit Test Enhancements  A-I.3 Multi-Slave Proxy Support  A-I.4 Transmit Blanking / Powerdown for DACs  A-I.5 ocpidev Improvements  A-I.6 VHDL-Native Pattern and Capture HDL Workers  A-I.7 New Documentation RPM  A-I.8 Zynq Parts Defined  A-II Changes and Notes  A-II.1 I/Q Data Ordering  A-II.2 Upgrade Notes  A-II.3 Significant SD Card Layout Changes  A-II.4 Intel Quartus and Quartus Pro Version Change  A-II.5 New Input Port ZLM-Handling Primitive  A-II.6 Change in QDAC/QDAC_TS Component Spec  A-II.7 Change in ocpidev Default Output and Scope  A-II.8 Rounding and Truncation in qdac-spec Workers  A-II.9 HDL Workers Failing Unit Tests That Previously Passed  A-II.11New RCC Platform Configuration  A-III.11New RCC Platform Configuration  A-III.11 ZedBoard IP Required Even In Standalone Mode	55 55 55 56 66 66 67 77 77 77 77 77 77 88 88 88 88 88 88					

	A-III.5 Default python Must Be Python2	9
	A-111.71 Teviously Documented Deficiencies	,
$\mathbf{B}$	Release 1.3.1	
	B-I Enhancements	
	B-II Changes and Notes	
	B-IIIMajor Known Deficiencies	
	B-III.1 PCI Platforms Can Only Transmit Using One Channel	)
$\mathbf{C}$	Release 1.3	1
C	C-I Enhancements	
	C-I.1 OSS Release	
	C-I.2 Python and GNU Radio Integration (Technology Preview)	
	C-I.3 AD9361 Support	
	C-I.4 GUI Improvements	
	C-I.5 Project Registry	
	C-I.6 Project Migration	
	C-I.7 ocpidev Improvements	
	C-I.8 RCC Platforms	
	C-I.9 Remote Containers (Technology Preview)	
	C-I.10 OpenCL Containers (Technology Preview)	
	C-II Changes and Notes	
	C-II.1 Major Project Restructuring	
	C-II.2 Upgrade Notes	
	C-II.3 Prerequisite RPMs Built With Newer Language Standards	
	C-II.4 Legacy Platform Names Continue to be Deprecated	
	C-II.5 OCPI_XILINX_VIVADO_DIR Variable Changed	
	C-II.6 ocpidev and Requesting RCC Platform To Match HDL Platform	
	C-II.7 zero_padding Component in ocpi.assets deprecated	
	C-IIIMajor Known Deficiencies	3
	C-III.1 Previously Documented Deficiencies	3
_		
D	Release 1.2	
	D-I Enhancements	
	D-I.1 Vivado Support for Applicable Xilinx-Based Platforms	
	D-I.2 New command option "ocpidev build"	
	D-I.4 Artifact Version Checking	
	D-I.5 Miscellaneous Improvements	
	D-II Changes and Notes	
	D-II.1 1x-spec and tx-spec Support Froperty Interdependence	
	D-IIIMajor Known Deficiencies	
	D-III.1 Driver Failing to Allocate Memory on Zynq-Based Platforms	
	D-III.2 HDL Workers Cannot Send SOM Without Valid Data	
	D-III.3 SDP Cannot Handle More Than One ZLM Per Application Run	
	D-III.4 File_Read and File_Write Cannot Handle ZLM Mid-file	
	D-III.5 PCI-Based Platforms Not Always Detected in Remote Tests	
	D-III.6 Built Projects Cannot Be Moved	
	D-III.7 Properties Before Raw Properties Cannot Have Parameterized Lengths	
	D-III.8 XML Parser Mixed-Case Issue	
	D-III.9 Simulation of Primitive Cores Needs Makefile Modified	
	D-III.0 Lime RX/TX Proxy Tests on CentOS6	
	D-III.1Previously Documented Deficiencies	
	D-IIV Addenda to Previous Release Notes	
	D 17 Individue to 1 Iorious Indiasc Indiasc	,

${f E}$	Rele	ease 1.1	17
	E-I	Enhancements	17
		E-I.1 Debug Symbols for Framework Now Available	17
		E-I.2 Kernel Driver Memory Arguments	
		E-I.3 HDL File_Read and File_Write CWD	
	E-II	Changes and Notes	17
		E-II.1 Simulators Renamed and Work Out-of-the-Box	18
		E-II.2 HDL Width Adapters Not Required	
		E-II.3 Platform Name Changes	
		E-II.4 RCC Cross-compilation No Longer Uses OCPI_CROSS_HOST	
		E-II.5 Updating a 1.0.x Unit Test for the 1.1 Framework	
		E-II.6 Prerequisite RPM Changes	
		E-II.7 Deprecated RCC controlOperations	
		E-II.8 64-Bit Build Host Issues ("Value too large for defined data type")	
	E-II	IMajor Known Deficiencies	
		E-III.1 Maximum Message Length in PCI-Based Platforms	
		E-III.2 MAC Address on ZedBoard	
		E-III.3 Platform Development Guide	
		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
$\mathbf{F}$	Rele	ease 1.0.1	21
	F-I	OpenCPI HDL Assembly Filename Constraint	21
	F-II	32-bit Architecture File Size Limit	21
	F-III	I Eclipse Project Description File	21
		Refreshing the ANGRYVIPER IDE	
		Non-default Xilinx Installation Locations	
		I Zero-Length Message Finite State Machines	

# Overview

This document contains corrections, changes, and enhancements made to OpenCPI since the previous release. It can never encapsulate *every* change or bug fix, but attempts to assist previous users in getting up and running as swiftly as possible. The *general* format of this document is to answer user questions:

- Section I ("Enhancements") describes "What's New?" about the current release.
- Section II ("Changes and Notes") is "What do I need to be aware of as a previous user of the Framework?"
- Section III ("Major Known Deficiencies") is for all users to answer "What bugs should I be aware of?"

The appendices contain the Release Notes from previously released versions of the Framework, roughly following the same format, e.g. C-I, being Section I of the v1.3 Appendix, is the "Enhancements" that were added to Release 1.3. It is highly recommended that a new user reviews the appendices as well; not only the main document concerning the latest release.

# I Enhancements

# I-1 New Digital Radio Controller Front-End Control Paradigm

(Technology Preview) This release includes a new OpenCPI Specification File (OCS) which represents the next-generation interface for Radio Frequency (RF) command and control. This generation improves upon the previous by removing RF vs. Base Band (BB) specificity, allowing for runtime querying of acceptable settings, and supporting multiple RF channels. Each of these marks an important step towards supporting truly hardware-agnostic RF applications.

For more information, consult Dig\_Radio\_Ctrlr.pdf.

# I-2 New Time-Based Protocol ("ComplexShortWithMetadata-prot") (Technology Preview)

One of the major improvements as of 1.5 is to have timestamped data flow from end-to-end using the "RxApp" on an E3xx example platform. To achieve this, "ComplexShortWithMetadata-prot" was created. The source to this Protocol (<core>/specs/) has various comments explaining the new opcodes and arguments as well as example usage.

# I-3 New Time-Based Assets Project ("assets\_ts") (Technology Preview)

The workers required to achieve the previously mentioned goal of timestamped data within "RxApp" were derived from those within "assets" but are now in their own Project, "assets\_ts". This Project mostly exists to work around current limitations within the Framework; whether or not it will continue to exist or if the timestamped versions will return to "assets" is still to be determined.

# I-4 New HDL Worker Port Interfaces

A new HDL Worker port interface is now available that considerably reduces code complexity when a Worker "doesn't care" about message boundaries, *e.g.* when streaming sequences of data. This interface is currently requested by noting in the OWD that it is "version=2" and this interface will become the default in OpenCPI 2.0. Additional information can be found in the *HDL Development Guide*.

#### Some Workers Migrated

Some of the HDL Workers' source have been updated to use this new "version=2" interface to exemplify its usage, while the "version 1" (pre-1.5) Worker source code has been migrated to the "inactive" Project. This should not affect any applications that previously used these Workers, except the Properties explicitly affecting buffer sizes are now silently ignored. The following Workers have been upgraded in this way:

agc\_real.hdl cic\_int.hdl mfsk\_mapper.hdl cic\_dec.hdl dc\_offset\_filter.hdl

# I-5 ocpidev Improvements

The ocpidev tool has been significantly improved, including:

- ability to show utilization of various HDL Workers and Assemblies
- show component shows information about Components, including Properties and Ports
- show worker information about Workers, including Properties and Ports

See II-6 for ocpidev command changes.

# I-6 New "Zed" RCC Platform: xilinx13\_4

With the introduction of the RCC Platform xilinx13\_4 to support the E310 in 1.4, with release 1.5 there are now RPMs available pairing the Zed with both xilinx13\_3 and xilinx13\_4. The RPMs follow the naming convention opencpi-hw-platform-zed-<RCCPlatform>. See the Zed Getting Started Guide for more information.

# I-7 gdb and rsync Provided on xilinx13\_3 and xilinx13\_4 RCC Platforms

Both of these tools are very helpful with development and an ARM-compiled version is now provided in the SD card images provided by OpenCPI. Out of the box, rsync must be run from the radio targeting the development host; more information is available in the applicable Getting Started Guides.

# II Changes and Notes

# II-1 Deprecation of the "Readable" Attribute

The "readable" Property Accessibility Attribute has been deprecated and replaced with "readback." *However*, its use case is very rare and specific; by default all Properties are "readable" in the usual context of the term. Additional information can be found in the *Component Development Guide*.

# II-2 Deprecation of Zipper RF Interface Board

The Myriad RF Zipper Interface Board has been unavailable for purchase for a considerable time. While OpenCPI still theoretically supports it, limited available quantities have resulted in its removal from the list of officially supported (and therefore tested) platforms. Support infrastructure has been moved to the "inactive" project.

# II-3 E3xx PPS Discipline

The "e3xx" Platform Worker timebase interface's PPS disciplining was previously limited to only the E310/E312's "SYNC" SMB connector (GPS PPS disciplining was not possible). The source selection is now exposed as a parameter on the Platform Worker.

# II-4 "new\_project\_source" script removed

The utility script noted in C-II.1 has been replaced by the more versatile "ocpi-copy-projects" script. This new utility is in the user's path and has a "--help" option.

# II-5 RCC Worker Parameter Macros Stricter

If an RCC Worker had been using the undocumented / internal "macro form" of a parameter, e.g. "PARAM\_biasValue()", that form will no longer work. Instead, RCC Workers must use the documented form, e.g. "BIAS\_PARAM\_BIASVALUE".

<sup>&</sup>lt;sup>1</sup>These examples are from the bias\_param.c worker, comparing 1.4 to 1.5.

# II-6 ocpidev Changes

• The show projects command no longer shows tests and primitives with low verbosity ("-v"); use high verbosity instead ("-vv")<sup>2</sup>.

# II-7 "myClock" HDL Code Deprecated / Removed

While revamping and examining the framework's ability to use multiple clocks within HDL Workers, it was found that the "myClock" capability was documented but likely never fully worked. This feature is *planned* to be restored and tested for the 1.6 release using a different XML attribute name.

#### II-8 Infrastructure OWDs Moved

Various OWDs<sup>3</sup> were incorrectly located within the "core" Project's "specs" directory, even though they are infrastructure Workers that an end user shouldn't need to be concerned with. They have been moved out to reduce confusion and clutter.

# II-9 RPM Upgrade Notes

Some previous RPM-based installations may not have proper dependencies documented for some sub-packages, e.g. version 1.4 of opencpi-hw-platform-e3xx-xilinx13\_4 requires "opencpi," not explicitly "opencpi version 1.4." This may cause version mismatches when upgrading; ensure all packages currently installed on a system are explicitly added to the yum command line when upgrading.

# II-10 HDL Wrapper Changes

The internal "wrapper" that encapsulates an HDL Worker has changed considerably (see Section I-4). This has changed the pipeline depths of the inputs and outputs of the Workers. This should not affect any users; an Application should never make assumptions concerning, or require specific relationships between, the timing of data between Workers<sup>4</sup>. However, if developers previously made implementation-specific assumptions, their Applications will now fail and will need to be fixed to properly use the Framework to transport all required data and metadata.

# III Major Known Deficiencies

# III-1 "udev" Radio Rules Sometimes Does Not Work

Starting with 1.4, some RPMs pre-install symlinks for rules in /etc/udev/rules.d/ for certain radio platforms, e.g. a rule to create a symlink from /dev/matchstiq\_z1\_0 to /dev/ttyUSBO. If the OpenCPI installation location is on a different partition than the host machine's root partition, the symlinks for these rules may be broken at boot-time because the target partition is not yet mounted when udev is reading the rules. To fix this, the command "sudo udevadm control --reload" should be executed upon a full boot. With CentOS 7, a custom systemd service can be implemented.

# III-2 Emulators Not Constrained To Specific Containers In Unit Tests

When an emulator-based test harness is built for multiple simulators (e.g. "isim" and "xsim"), running the unit test does not guarantee that all workers are running on the same container. For example, when "lime\_dac\_ts.test" is built for both isim and xsim, test execution could pass for isim, but might later fail with xsim. Review of the log file shows that the emulator worker is erroneously running on an isim container and not the expected xsim container. The recommended workaround is to only build and test for a *single* simulator at a given time, ensuring there is only one artifact that satisfies the test's requirements.

<sup>&</sup>lt;sup>2</sup>Any automated parsing of data should be using JSON interface, which also needs this additional verbosity.

<sup>&</sup>lt;sup>3</sup>The OWDs explicitly were metadata.xml, ocscp.xml, time\_client.xml, and unoc\_node.xml.

<sup>&</sup>lt;sup>4</sup>Other ways timing may be affected would include backpressure from upstream Workers, network latency between remote Containers, etc.

# III-3 Provided LiquidDSP Build May Link Incorrectly

Note: This bug only affects source-based building; RPM-based users will not encounter this issue.

The "LiquidDSP" library is provided as a prerequisite of the "assets" Project. It is currently used by one worker, "complex\_mixer.rcc", which uses it for its Numerically Controlled Oscillator (NCO). If the LiquidDSP library is built on a system that has the "FFTW" library installed, it will attempt to use it. However, any user-developed RCC Worker attempting to use LiquidDSP functions that use the FFTW back-end will fail at runtime with an undefined symbol (e.g. fftwf\_execute). The recommended workaround is to use the compiled libliquid from the RPM installation (e.g. /opt/opencpi/cdk/centos7/lib/libliquid.a or /opt/opencpi/cdk/xilinx13\_3/lib/libliquid.a) or to rebuild the prerequisites without the FFTW libraries installed.

This problem was found late within the 1.5 release cycle and will be addressed with the next major release.

# III-4 Previously Documented Deficiencies

The following deficiencies are still present in 1.5:

- 32-bit Architecture File Size Limit (cf. F-II)
- OpenCPI HDL Assembly Filename Constraint (cf. F-I)
- Maximum Message Length in PCI-Based Platforms (cf. E-III.1)
- Properties Before Raw Properties Cannot Have Parameterized Lengths (cf. D-III.7)
- MAC Address on ZedBoard (cf. E-III.2)
- PCI-Based Platforms Not Always Detected in Remote Tests (cf. D-III.5)
- Lime RX/TX Proxy Tests on CentOS6 (cf. D-III.10)
- PCI Platforms Can Only Transmit Using One Channel (cf. B-III.1)
- Connection Direction In GUI Assumes XML order (cf. A-III.2)
- Some HDL Workers Will Need To Be Updated When props\_in.raw.address Width Fixed (cf. A-III.4)

The following previously-documented deficiencies have been fixed in this release:

- ZedBoard IP Required Even In Standalone Mode (cf. A-III.1)
- OnlyPlatforms/ExcludePlatforms Does Not Work For Individual Unit Test Cases (cf. A-III.3)
- Some ocpi.assets Workers Have Flow Control Issues (cf. A-III.6)
- Default python Must Be Python2 (cf. A-III.5)

# Appendices

The Release Notes from previous releases are included here as reference for still-existing bugs, relevant upgrading notes for users of very old versions, etc.

# A Release 1.4.0

#### A-I Enhancements

## A-I.1 Support for Ettus E310 Platform

The Ettus Research USRP E310 is now supported within the OpenCPI framework. This includes the changes to the AD9361 device workers for using a CMOS interface, increasing the number of modes that the framework supports<sup>5</sup> There is currently a limitation of a single TX and RX channel being supported; see the *E3xx Getting Started Guide* for more information.

#### A-I.2 Component Unit Test Enhancements

The provided Component Unit Test infrastructure has been enhanced to automatically incorporate elements that address common issues when developing HDL workers:

- 1. Input message metadata manipulation applied to the Unit Under Test's (UUT) input port(s) helps ensure an HDL Worker can properly handle various message-protocol edge conditions, e.g. start-of-message without data until a later clock. This manipulation is not enabled by default.
- 2. Output message throttling applied to the UUT's output port(s). Not respecting "backpressure" is often the reason an HDL Worker fails on a "real" hardware platform after passing all tests within a simulation. This backpressure is now enabled in *all* test benches by default.

Exercising Workers in this manner during the simulation design phase has been shown to greatly increase the likelihood of success on physical hardware. More information can be found in the *Component Development Guide*.

# A-I.3 Multi-Slave Proxy Support

Previously, a Proxy Worker could only represent a single Worker but not a collection of Workers that had related functions, e.g. the transmit and receive paths of a single RF link. This resulted in various workarounds that are not officially supported by the Framework. For example, one user had a Proxy "peeking" into the Application to find peer Workers: this does not work with Remote Containers with the Application on another physical machine. Now a Proxy can (optionally) define more than one slave Worker with full interface compatibility with previous implementations <sup>6</sup>. More information can be found in the Component Development Guide.

#### A-I.4 Transmit Blanking / Powerdown for DACs

Both the AD9361 and LIME DACs are now blanked / powered down<sup>7</sup> when not in use. To perform this on-demand, they use a new "tx\_event" Port/Protocol, as well as properties exposed in their proxies. See the respective Worker datasheets for more details. This added capability resulted in a change to the qdac-spec that may affect current user applications. If an application used connect=qadc (connect attribute), that application will require an additional to attribute specified directing it to explicitly use the IN input port.

#### A-I.5 ocpidev Improvements

The ocpidev tool has been significantly improved, including:

- run some Applications
- run Unit Tests

 $<sup>^5\</sup>mathrm{AD9361}$  LVDS signaling has been supported since 1.3; cf. C-I.3.

<sup>&</sup>lt;sup>6</sup>The interface of using an object named "slave" remains. The type of the object is considered an implementation detail and has changed.

<sup>&</sup>lt;sup>7</sup>Implemented by TX RF carrier suppression

- show Unit Tests within a Project
- show additional Project information

See A-II.7 for ocpidev command changes.

## A-I.6 VHDL-Native Pattern and Capture HDL Workers

The pattern\_v2 and capture\_v2 Workers have been written from the ground up in VHDL to replace the machine-generated Verilog-sourced pattern and capture Workers. These latter Workers are now considered deprecated. The new Workers include fully-functional test benches and data sheets. Platform and BSP Developers will find these Workers to be very useful when debugging various issues related to low-level OpenCPI development.

## A-I.7 New Documentation RPM

In addition to the PDF-based documentation available at github.io, a new RPM is now included "opencpi-doc," which includes most of that documentation. Most of the PDFs are installed into /usr/share/doc/8, but a convenience symlink can be found at /opt/opencpi/documentation.html. This path should not change across multiple OpenCPI versions and can be passed directly to most browsers, e.g. "xdg-open /opt/opencpi/documentation.html". If you receive the RPM directly from the AV team, it may include BSP documentation that is not available on GitHub.

## A-I.8 Zynq Parts Defined

All Zynq-based Xilinx parts that are supported by the current Framework, but not necessarily used in an OpenCPI-supported platform, have been defined within the Framework build system. This means that an end user creating a BSP for a "larger fabric" Zynq-7000, e.g. xc7z100, will not need to change any Framework files and have all required changes isolated to a single Project. This does not include additional platforms that have different internal configurations, e.g. Zynq-UltraScale+ devices.

# A-II Changes and Notes

# A-II.1 I/Q Data Ordering

As noted in the *HDL Development Guide*, when a Protocol contains a Struct Argument, the first Argument Member defined in the Protocol's XML is always in the least significant bits of the resulting Port. A good example of the importance of this is the scenario where a Port's default data width is overridden (in the OWD) to present all of a Struct's Members in parallel within a single clock cycle. For example, iqstream\_protocol's default ordering is a 16-bit interleaved I/Q data: " $I_{t=0}$ ,  $Q_{t=0}$ ,  $I_{t=1}$ ,  $Q_{t=1}$ 

```
I_0 = InPort_0[15:0]; Q_0 = InPort_0[31:16]

I_1 = InPort_1[15:0]; Q_1 = InPort_1[31:16]
```

The following Application and Workers were identified as improperly handling  $iqstream\_protocol$  complex data (I/Q) presented in the manner noted above and have been corrected:

• assets/components/dsp\_comps:

```
cic_dec.hdldc_offset_filter.hdlpr_cordic.hdlcic_int.hdlfir_complex_sse.hdlrp_cordic.hdlcomplex_mixer.hdl9iq_imbalance_fixer.hdlcomplex_mixer.rcc9phase_to_amp_cordic.hdl
```

• assets/hdl/devices:

<sup>&</sup>lt;sup>8</sup>The Fedora/Red Hat standard documentation location.

 $<sup>^9\</sup>mathrm{See}$  last paragraph as well concerning Property changes.

ad9361\_dac.hdl lime\_dac.hdl lime\_dac\_ts.hdl

• assets/applications

FSK Rx\_App

It is important to note that this list includes various DACs as well as the complex\_mixer, meaning that user's RF Applications from previous versions of the Framework may need to be updated, e.g. to handle this change in the DAC's interpretation of data presented for transmission. Also related to this, the phs\_inc Property of complex\_mixer may require inversion when compared to previous versions.

# A-II.2 Upgrade Notes

If you have previous versions of the RPM-based OpenCPI RPMs installed, they must all be manually removed, including the prerequisites. There is no automatic upgrade path. Manually performing "sudo rm -rf /opt/opencpi/prerequisities" after uninstalling all previous RPMs may also be needed.

#### A-II.3 Significant SD Card Layout Changes

There have been significant changes to the layout of the Framework and its support files. These are mostly implementation details that the end user does not need to be concerned with. However, scripts and paths that are used for embedded development (both locally and using NFS mounts) have changed enough that users should wipe any SD cards they have used and follow the directions given in the respective platform's *Getting Started Guide* to create a new one.

# A-II.4 Intel Quartus and Quartus Pro Version Change

This release has been tested with Quartus Standard 17.1 which is a newly supported version of the tool. Version 15.1 should still work, but future versions will be tested with 17.1. Additionally, preliminary support for Quartus Pro 17.0.2 is also available within the Framework, but is not used by any platforms at this time.

#### A-II.5 New Input Port ZLM-Handling Primitive

For an HDL Worker to handle the *de facto* end-of-stream signaling used by the Component Unit Test infrastructure (a ZLM with OpCode 0), a convenience primitive is now available and found at projects/core/hdl/primitives/util/zlm\_detector.vhd with an example implementation shown in the capture\_v2.hdl Worker.

#### A-II.6 Change in QDAC/QDAC\_TS Component Spec

The QDACs now have two ports. The "IN" ports have not changed, but some applications may need to be updated if they did not explicitly connect to them. See A-I.4 above for more information.

# A-II.7 Change in ocpidev Default Output and Scope

Some of the output from ocpidev's show has changed to default to being more "human friendly" and reporting in a tabular fashion (--table). Many of these commands retain a --simple parameter for quick parsing. Most also support --json, which is the recommended and most stable method of parsing ocpidev output.

Some of ocpidev's show commands now have the concept of "scope" where the user is requesting a list of somethings provided by a single project, or all somethings available within all registered Projects. At this time, no commands support both of the scoping arguments --global-scope and --local-scope. However, to ensure future ocpidev enhancements remain compatible with user scripts, some commands will force the user to explicitly specify a scope if the "reasonable" not-yet-implemented default is not yet ready. For example, in a future release, "ocpidev show tests" will report all Unit Tests that are available. That report is not yet available, so the user must currently explicitly scope the request with "ocpidev show tests --local-scope". However, something like "ocpidev show registry --local-scope" would make no sense, so will never be supported.

#### A-II.8 Rounding and Truncation in qdac-spec Workers

Various DACs were found to be improperly casting *signed* data to *unsigned* during certain operations, resulting in an overflow when the maximum value was transmitted.

# A-II.9 HDL Workers Failing Unit Tests That Previously Passed

If a user experiences Unit Test failures that were not present in previous releases, the most likely cause is that "backpressure" is now automatically asserted by default; see A-I.2 for details.

#### A-II.10 New Framework Build System

The OSS OpenCPI Project has migrated the Framework build system to a new custom-made system that produces RPMs directly<sup>10</sup> and removes the need for "prerequisite" RPMs. If upgrading from a previous RPM-based installation, the prerequisite RPMs might require manual deletion. Any mention of prerequisite RPMs in the Appendices (e.g. E-II.6) below can likely be ignored.

# A-II.11 New RCC Platform Configuration

Prior to 1.4, RCC Platforms were defined in /projects/core/rcc/platforms. With 1.4, they can be in the /rcc/platforms directory of any Project. *The Platform Development Guide* defines how RCC Platforms are *now* defined and a condensed migration guide can be found at projects/core/rcc/platforms/README.migrating.

# A-III Major Known Deficiencies

# A-III.1 ZedBoard IP Required Even In Standalone Mode

Applications (including XML-only ones) fail if there is not an IP address assigned to the ZedBoard, even when in "standalone mode." If the network connection is not used, forcing a MAC (cf. Section E-III.2) and IP addresses is required. To set a temporary IP address, the command "ifconfig etho 192.168.244.244" can be used. This problem was found late within the 1.4 release cycle and should be addressed with the next major release.

#### A-III.2 Connection Direction In GUI Assumes XML order

When importing hand-written XML into the GUI, the to and from attributes are ignored on connections. This does not affect any XML generated by the GUI.

#### A-III.3 OnlyPlatforms/ExcludePlatforms Does Not Work For Individual Unit Test Cases

You can include and exclude platforms at a full-test level, but individual cases currently ignore the directives.

#### A-III.4 Some HDL Workers Will Need To Be Updated When props\_in.raw.address Width Fixed

The "raw" address scheme for HDL workers is documented as a 32-bit bus. In testing, it was found that this is currently implemented as only 16 bits. While this has *not* yet been fixed, users should review their own libraries for any Workers that make assumptions concerning the size of the bus. Any raw.address access should be written in more generic VHDL, e.g.:

```
- event_rawprops.raw.address <= x"0040"; --TXRF modules enable register
+ event_rawprops.raw.address <= (6 => '1', others => '0'); --TXRF modules enable register (0x40)
```

#### A-III.5 Default python Must Be Python2

According to the PEP-394 specification, system-level python should point to a 2.x version of the Python interpreter. Some scripts within the Framework and Unit Tests require this configuration.

 $<sup>^{10}</sup>$ If a user was building custom RPMs (from the releng directory), the process has changed considerably.

# A-III.6 Some ocpi.assets Workers Have Flow Control Issues

The Component Unit Test infrastructure has been enhanced (cf. Section A-I.2) and deficiencies within some Workers have been revealed during regression testing. The following ocpi.assets Workers are currently known to have defects which will be fixed in a future release:

bias\_ver.hdl cic\_int.hdl fir\_real\_sse.hdl

cic\_dec.hdl fir\_complex\_sse.hdl

# A-III.7 Previously Documented Deficiencies

The following deficiencies are still present in 1.4:

- 32-bit Architecture File Size Limit (cf. F-II)
- OpenCPI HDL Assembly Filename Constraint (cf. F-I)
- Maximum Message Length in PCI-Based Platforms (cf. E-III.1)
- Properties Before Raw Properties Cannot Have Parameterized Lengths (cf. D-III.7)
- MAC Address on ZedBoard (cf. E-III.2)
- PCI-Based Platforms Not Always Detected in Remote Tests (cf. D-III.5)
- Lime RX/TX Proxy Tests on CentOS6 (cf. D-III.10)
- PCI Platforms Can Only Transmit Using One Channel (cf. B-III.1)

The following previously-documented deficiencies have been fixed in this release:

- XML Parser Mixed-Case Issue (cf. D-III.8)
- Platform Development Guide (cf. E-III.3)

# B Release 1.3.1

#### **B-I** Enhancements

- All documentation has now been updated to cover 1.3 capabilities and features
- Bugfixes and enhancements for AD9361
- Workarounds for bug noted in Section B-III.1
- USB Blaster udev rules fixed
- ocpizyną tool fixed

# **B-II** Changes and Notes

None to report.

# **B-III** Major Known Deficiencies

• Note: no other deficiencies from Section C-III have been mitigated and all remain.

# B-III.1 PCI Platforms Can Only Transmit Using One Channel

The current implementation of the PCI-e Specification (ALST4 and ML605 platforms) only allows DMA transaction from the host to the platform on the first External Port defined in the Assembly or Container XML. This means the input to any Assembly/Container should be listed first. See projects/assets/hdl/assemblies/empty/cnt\_1rx\_1tx\_bypassasm\_fmcomms\_2\_3\_hpc\_LVDS\_m1605.xml as an example. This does not affect any Zynq-based platforms. This problem was found late within the 1.3 release cycle and should be addressed with the next major release.

# C Release 1.3

#### C-I Enhancements

#### C-I.1 OSS Release

ANGRYVIPER Team's build of OpenCPI is now available on GitHub under the OpenCPI Organization. The first release is in a git branch, but full integration is planned in the future. This includes all of the previously-proprietary "ocpiassets / Assets" Project, including the Board Support Package (BSP) for Epiq Solutions' Matchstiq Z1.

## C-I.2 Python and GNU Radio Integration (Technology Preview)

There are now SWIG bindings available to allow a top-level Python script to use the ACI to manipulate an Application in the same manner as from  $C++^{11}$ . One use case is a GNU Radio block that allows GNU Radio Companion to handle the entire lifecycle of an OpenCPI Application. This block can handle data flows of complex I/Q streams or any primitive data type (e.g. floats or bytes) in and out of the Application. A reference implementation of this block is provided in OpenCPI's fork of GNU Radio Companion.

This fork of GNU Radio Companion also allows for Application and HDL Assembly building, as well as deployment independent of the ANGRYVIPER GUI. Some of this capability was presented at the GNU Radio Conference GRCon17; the video is available on YouTube.

#### C-I.3 AD9361 Support

The popular Analog Devices, Inc's AD9361 RF transceiver IC is now supported via a series of Device Workers. The modularity of these workers eases AD9361 transceiver integration with future FPGA systems. Most of the major AD9361 features are supported, including RX/TX RF digitization/data streaming and RF tuning/gain control. The AD9361 Device Workers currently only fully support some operating modes, but contain infrastructure in anticipation of future expansion. These device workers utilize the vendor's No-OS software library for high-level control.

There is also "card" support for the FMCOMMS2 and FMCOMMS3 evaluation/prototyping RF transceiver FMC cards centered on the AD9361. The newly released ocpi.assets Project includes a single-channel RX narrowband I/Q stream to file (applications/rx\_app) and single-channel RX/TX FSK modem (applications/FSK) reference applications, which each support the FMCOMMS2 and FMCOMMS3 card on the zed platform.

# C-I.4 GUI Improvements

Since 1.2, the GUI has multiple improvements, some of which are:

- The ability to build OpenCPI Assets The Component and Application developer can now build without the command line. The build tool allows RCC and HDL compilation from numerous levels in a Project from individual assets to the entire Project. The tool also allows the developer to build and run Component unit tests while allowing multiple concurrent builds in separated tabbed consoles.
- New Perspective This Eclipse Perspective is the new presentation of the build tool. It consists of a number of views where three are specific to OpenCPI.
- **Project Explorer view** This view allows simple navigation to select items to build and provides a way forward to provide OpenCPI features without having to explore the file system.
- OpenCPI Operations Panel Selections can be placed in this panel and built for all available RCC and HDL Targets and/or Platforms.
- Build Status View Provides a simple graphical presentation of the launched build or test run and its status (e.g. running). The user may also re-run build, clean, or run executions from this view and bring the build console window forward.
- New HDL Platform Editor The HDL developer can now create and view HDL platform XML in a graphical presentation.

<sup>&</sup>lt;sup>11</sup>This integration is only available on CentOS 7 platforms.

## C-I.5 Project Registry

Release 1.3 introduces a new concept of "Project Registry" to organize and interrelate a set of Projects which allows Projects to be moved (cf. C-I.6) as well as present an explicit relationship between them, e.g. "this copy of ocpi.assets was built based upon that copy of ocpi.core." Registry manipulation is performed using ocpidev (cf. C-I.7).

The default configuration is that every Project on a machine shares a single Registry (located at /opt/opencpi/project-registry). A user must be in the Unix group "opencpi" to manage this global Registry.

This new capability deprecates the previously-used OCPI\_PROJECT\_PATH build-time variable as well as the scripts freeze\_project.sh and thaw\_project.sh noted in D-III.6.

## C-I.6 Project Migration

With the new Project Registry (cf. C-I.5), Projects can now be moved to new locations or archived and then restored on another machine with the use of the ocpidev unregister and ocpidev register commands. This mitigates the previously-documented deficiency found in D-III.6.

# C-I.7 ocpidev Improvements

The "ocpidev" command has been improved in various ways, including:

- bash completion for many commands (try ocpidev <tab><tab>)
- Ability to show possible HDL platforms: ocpidev show hdl platforms --table
- Ability to show possible RCC platforms: ocpidev show rcc platforms
- Ability to build unit tests
- Project Registry (C-I.5) manipulations

# C-I.8 RCC Platforms

With the new Project Registry (cf. C-I.5), RCC Platforms can now be defined exclusively within a Project outside of the CDK / Core Project. An example of this can be seen in the inactive project under rcc/platforms/macos10\_13. This improvement allows BSPs to be self-contained within a Project.

#### C-I.9 Remote Containers (Technology Preview)

The full-OSS OpenCPI code base has imported previously-written code that allows Remote Containers. This code has not yet been evaluated by the ANGRYVIPER Team.

#### C-I.10 OpenCL Containers (Technology Preview)

The full-OSS OpenCPI code base has imported previously-written code that allows OpenCL ("OCL model") Containers on CPUs and GPUs. This code has not yet been evaluated by the ANGRYVIPER Team.

#### C-II Changes and Notes

This section describes items that may cause users of previous versions to modify their code, build system, etc.

#### C-II.1 Major Project Restructuring

Starting with Release 1.3, the CDK is no longer a top-level Project. All Components that were previously found in the CDK, e.g. file\_read, have migrated to ocpi.core. The previously-documented "Base Project" has been removed; it was the RPM-specific manner of separating the CDK from the core components needed to run OpenCPI. The various items (cards, devices, specs, etc) that were previously found in the Base Project have been distributed into one of three new Projects. The previously non-OSS proprietary items have been redistributed within the new Projects as well. The Projects are:

• ocpi.core - Core items for the Framework

- ocpi.assets Items fully-supported by the ANGRYVIPER Team
- ocpi.inactive "Everything else"

These items being moved will cause Application XML to possibly fail, e.g. anything calling for the ocpi.file\_read spec now needs to look for ocpi.core.file\_read. There is a similar rename of ocpiassets  $\Rightarrow$  ocpi.assets.

There is a provided utility script (/opt/opencpi/cdk/scripts/upgradeApp\_v1\_3.py) to assist in this migration. This script will modify the package information for the specs required. There are three ways it can be called:

- If given a single argument (the Application XML file name), it will write the same name with updated\_prepended.
- If given a second argument, the modified file will be written to that file name.
- If the second argument is same, the original file will be overwritten.

This change also removes the <code>/opt/opencpi/base\_project\_source/new\_base\_project.sh</code> script found in earlier releases; its equivalent is now <code>/opt/opencpi/projects/new\_project\_source</code>, which uses the same arguments as noted in the <code>Getting Started Guide</code>.

#### C-II.2 Upgrade Notes

If you have previous versions of the RPM-based OpenCPI RPMs installed, they must all be manually removed, including the prerequisites. There is no automatic upgrade path. Manually performing "sudo rm -rf /opt/opencpi/prerequisities" after uninstalling all previous RPMs may also be needed.

# C-II.3 Prerequisite RPMs Built With Newer Language Standards

All prerequisites are now built with the C++11 or the C98 standard implemented. This will increase interoperability and avoid ambiguous situations, e.g. the size of a bool variable.

#### C-II.4 Legacy Platform Names Continue to be Deprecated

The legacy suffix "\_pf" for simulator platforms, e.g. isim\_pf, is not supported when running unit tests. Unit tests were introduced after the suffix was deprecated, so the effect on end users should be minimal.

#### C-II.5 OCPI\_XILINX\_VIVADO\_DIR Variable Changed

A bug in Release 1.2 required the variable to be set "deep", e.g. /data/Xilinx/Vivado/2017.1. You must now set it to the top-level value, e.g. /data/Xilinx. If a specific version of Vivado is required, OCPI\_XILINX\_VIVADO\_VERSION should be set, e.g. 2017.01. As a reminder, these variables only apply if you have both ISE and Vivado installed in different base directories, e.g. ISE in /opt/Xilinx vs. Vivado in /data/Xilinx.

#### C-II.6 ocpidev and Requesting RCC Platform To Match HDL Platform

When building Projects with ocpidev, the user can tell the build system to automatically select the proper RCC Platform when given an HDL Platform. This option is --rcc-hdl-platform with a mnemonic of "build this RCC Platform for that HDL Platform." Previous Releases had the flags backwards ("--build-hdl-rcc-platform"). This is incorrect and has been deprecated.

#### C-II.7 zero\_padding Component in ocpi.assets deprecated

In the FSK reference application, zero\_padding.hdl was replaced by two new Workers, zero\_pad.hdl and mfsk\_mapper.hdl. The change was made because zero\_padding.hdl performed two functions: binary FSK mapping and inserting zeros between symbols. Whenever possible, functions should be separated into their own Components for increased flexibility and reuse. The zero\_padding Component will be removed in Release 2.0.

# C-III Major Known Deficiencies

# C-III.1 Previously Documented Deficiencies

The following deficiencies are still present in 1.3:

- 32-bit Architecture File Size Limit (cf. F-II)
- OpenCPI HDL Assembly Filename Constraint (cf. F-I)
- XML Parser Mixed-Case Issue (cf. D-III.8)
- Maximum Message Length in PCI-Based Platforms (cf. E-III.1)
- Platform Development Guide (cf. E-III.3)
- Properties Before Raw Properties Cannot Have Parameterized Lengths (cf. D-III.7)
- MAC Address on ZedBoard (cf. E-III.2)
- PCI-Based Platforms Not Always Detected in Remote Tests (cf. D-III.5)
- Lime RX/TX Proxy Tests on CentOS6 (cf. D-III.10)

The following previously-documented deficiencies have been fixed in this release:

- Driver Failing to Allocate Memory on Zynq-Based Platforms (cf. D-III.1)
- Built Projects Cannot Be Moved (cf. D-III.6)
- HDL Workers Cannot Send SOM Without Valid Data (cf. D-III.2)
- File\_Read and File\_Write Cannot Handle ZLM Mid-file (cf. D-III.4)
- SDP Cannot Handle More Than One ZLM Per Application Run (cf. D-III.3)

The following previously-documented deficiencies will *not* be fixed:

• Simulation of Primitive Cores Needs Makefile Modified (cf. D-III.9): It was determined that this is not a bug. For primitive cores, if a user sets the SourceFiles variable, they must explicitly list all files, including \*\_pkg.vhd files. This is true for all platforms.

# D Release 1.2

#### **D-I** Enhancements

#### D-I.1 Vivado Support for Applicable Xilinx-Based Platforms

By far the #1 requested feature by OpenCPI users, the Framework now supports the use of Xilinx's Vivado on the appropriate Platforms. **This toolchain is now the default** where applicable (mostly Zynq-based), and it is highly recommended that users of Xilinx-based platforms review the provided *Vivado Usage Guide*.

End users should be aware (see Vivado Usage Guide for more details) that:

- If you simulate with ModelSim, you may need to upgrade. Vivado requires a minimum version of 10.5c (tested by ANGRYVIPER Team using 10.6a)
- If your design requires the use of Xilinx CORE Generator IP (coregen) items, they must be regenerated with Vivado to be *simulated* in XSIM. Your existing ngc files from ISE can continue to be used for *synthesis*, but porting to new *Vivado IP* is recommended.
- There is a new platform, zed\_ise, that is intended for testing purposes, but released with the distribution. This platform is the ZedBoard using the Xilinx ISE tool chain.

# D-I.2 New command option "ocpidev build"

To help improve the end-user experience, OpenCPI 1.2 requires less command-line usage of "make". The previously-available tool ocpidev now has a "build" verb available. More information can be found in the (OSS) Component and Application Development Guides.

#### D-I.3 GUI Now Delivered as RPM

There is now an opencpi-ide RPM included in the distribution. A separate installation of Eclipse for each end user is no longer required. Once installed, any user can launch with the ocpigui command.

#### D-I.4 Artifact Version Checking

While backwards compatibility is a major goal of OpenCPI, binary compatibility across versions is *not* guaranteed. Every artifact should always be rebuilt with the latest framework. To enforce this requirement, the framework will check all artifact metadata at deployment time to verify the version used to build. Version 1.1 inserted the proper metadata, but the comparison is new in 1.2, allowing 1.2 to recognize and reject 1.1 artifacts. Artifacts rejected for no other reason will issue a warning message at all debugging levels. This behavior can be overridden by setting the environment variable OCPI\_ALLOW\_VERSION\_MISMATCH to "1"; this is not recommended.

## D-I.5 Miscellaneous Improvements

A quick list of improvements not documented above include:

- Cross-platform ACI builds using ocpidev-generated applications previously failed
- Picoflexor T6A Software updated to vendor's Drop 5.5.2
- ocpiassets project can now be imported into GUI
- Proxies can now use string properties<sup>12</sup>

#### **D-II** Changes and Notes

This section describes items that may cause users of previous versions to modify their code, build system, etc.

# D-II.1 rx-spec and tx-spec Support Property Interdependence

Certain front-ends have different ranges based other properties, e.g. the current sample rate, requiring some properties that were previously "Initial" (immutable) to have their restrictions relaxed. This compatibility break should only affect platform developers, unless applications were incorrectly caching these values. All interfaces above that level should be unaffected.

 $<sup>^{12}</sup>$ This is noted here because it is one of the first user reported bugs.

## **D-II.2** Vivado Support

Please see D-I.1 for modifications that may need to be performed.

# D-III Major Known Deficiencies

#### D-III.1 Driver Failing to Allocate Memory on Zynq-Based Platforms

In some situations after repeated multi-model (RCC and HDL) application runs on Zynq-based platforms (e.g. ZedBoard), the kernel driver will fail to allocate contiguous memory for DMA data transfers. On x86-based platforms, memory for this use is allocated at boot time before memory fragmentation. Currently, no memory is being allocated at boot time for the Zynq-based platforms. Single ocpirun or ACI application runs from the command line do not present any errors. When running an app in a long loop, such as in the unit test framework, or an application that writes a large amount of data (approx. 1GB) to file, this error may occur.

#### D-III.2 HDL Workers Cannot Send SOM Without Valid Data

Although the HDL Component documentation claims the Framework's internal protocols support a separate Start-of-Message independent of valid data designations, this sequence causes the Component's output port to ignore any remaining data. This was found late within the 1.2 release cycle and should be addressed with the next release.

# D-III.3 SDP Cannot Handle More Than One ZLM Per Application Run

The SDP transport will not propagate a second ZLM, so at this time the *only* ZLM should be an implied end-of-application transmission. This problem does not exist when communicating between RCC-only Workers. Related to, but independent of D-III.4. (See also F-VI.)

#### D-III.4 File\_Read and File\_Write Cannot Handle ZLM Mid-file

file\_read (HDL implementation) and file\_write (RCC and HDL implementations) will stop if a Zero-Length-Message (ZLM) is found when operating in "message mode" regardless of the location within the file. Related to, but independent of D-III.3. (See also F-VI.)

#### D-III.5 PCI-Based Platforms Not Always Detected in Remote Tests

Using OCPI\_REMOTE\_TEST\_SYSTEMS, JTAG connection problems have been observed, possibly related to system reboots. They seem to be resolved after disconnecting and reconnecting the USB cable.

#### D-III.6 Built Projects Cannot Be Moved

When a Project is built, the dependencies of each artifact and other support files are captured. Some of these contain absolute paths pointing to where the Project is currently located. The distribution includes a pair of *unsupported* scripts that *may* allow movement of Projects. They can be found in /opt/opencpi/cdk/scripts/ and are named freeze\_project.sh and thaw\_project.sh.

## D-III.7 Properties Before Raw Properties Cannot Have Parameterized Lengths

"Raw properties" start at a certain property with the properties before that being "non-raw" properties. Currently, none of these "before" properties can have their length be set by an expression dependent on another parameter property.

#### D-III.8 XML Parser Mixed-Case Issue

The XML parser does not always recognize tags if differently-cased versions of the same tag are in the same XML file, e.g. an OAS having both <Instance .../> and <instance .../> XML tags will fail. Users of the GUI should not be affected.

# D-III.9 Simulation of Primitive Cores Needs Makefile Modified

When designing a Primitive vendor-specific core that is intended for simulation, the required \*\_pkg file containing the core's stub must be explicitly listed first in the Makefile's SourceFiles variable.

# D-III.10 Lime RX/TX Proxy Tests on CentOS6

The proxy tests for the Lime transceiver use a feature of C++11 that is not supported by the compiler in CentOS 6. The workaround is to use similar code to the following in the various places to\_string() was used:

```
- std::string ClkInStr;
- ClkInStr = to_string(2 * sample_rate * 1e6).c_str();
+ std::ostringstream ostr_clkin;
+ ostr_clkin << (2 * sample_rate * 1e6);
+ std::string ClkInStr(ostr_clkin.str());</pre>
```

# D-III.11 Previously Documented Deficiencies

The following deficiencies are still present in 1.2:

- 32-bit Architecture File Size Limit (cf. F-II)
- OpenCPI HDL Assembly Filename Constraint (cf. F-I)
- MAC Address on ZedBoard (cf. E-III.2)
- Maximum Message Length in PCI-Based Platforms (cf. E-III.1)
- Platform Development Guide (cf. E-III.3)

# D-IV Addenda to Previous Release Notes

- The default CWD\_MAX\_LENGTH noted in E-I.3 is now set to 256.
- The Liquid RPMs referenced in E-II.6 are now required to build the ocpiassets project (complex\_mixer. rcc). They are still considered optional when installing.

# E Release 1.1

#### E-I Enhancements

A quick list of improvements include:

• Simulatable Data Plane: Allows HW and SW co-simulation to test integration between heterogeneous Workers

- Scalable Data Plane: Allows Platform Workers to more efficiently use wider data paths on future platforms, e.g. a 128-bit bus instead of 32-bit<sup>13</sup>
- New automatic test harness creation, including limited remote platform support 14
- Automatic bus width adaption between HDL Workers
- Additional Assets components to help design and debug Applications
- HDL Simulator on-the-fly launching<sup>15</sup>
- Extended GUI capabilities
- Official CentOS 7 driver support
- Split platform names more explicitly between hardware and software platform types
- Many fields in XML that require numerical values can now have mathematical calculations
- Added platform support (Picoflexor RCC-Only)

## E-I.1 Debug Symbols for Framework Now Available

An RPM containing most debug symbols for the Framework (opencpi-debuginfo-\*.x86\_64.rpm) is now provided. This greatly enhances the debugging of RCC Workers using industry-standard debuggers such as gdb and ddd.

#### E-I.2 Kernel Driver Memory Arguments

In previous versions, the "memmap" argument was given to the Linux kernel command line. This can conflict with other software that may also require reserved memory. If the user requires the reservation of more than one memory area using the memmap option, the OpenCPI driver will:

- Assume the first memmap is for its use
- Explicitly use the range/subrange marked with an additional opencpi\_memmap. The original memmap must still be provided for the kernel to make the reservation.

See /opt/opencpi/driver/README for more information, including usage examples and configuration.

#### E-I.3 HDL File\_Read and File\_Write CWD

The HDL Workers implementing the File\_Read and File\_Write specs distributed in 1.0 failed if used in a directory that exceeded 100 characters deep. There is an additional parameter CWD\_MAX\_LENGTH on these Workers that can be increased to allow deeper directories when needed.

# E-II Changes and Notes

This section describes items that may cause users of previous versions to modify their code, build system, etc.

<sup>&</sup>lt;sup>13</sup>Currently limited to some Zynq-based platforms.

<sup>&</sup>lt;sup>14</sup>Most ocpiassets have been moved to the new test system to provide examples.

 $<sup>^{15}\</sup>mathrm{See}$  Section E-II.1 for more information.

#### E-II.1 Simulators Renamed and Work Out-of-the-Box

The simulator platform names have been renamed to remove the "\_pf" suffix, e.g. isim. The isim<sup>16</sup> and modelsim simulation platforms can now be targeted once the appropriate environment variables are set, e.g. OCPI\_MODELSIM\_DIR. With ocpirun able to launch simulations, the usage of "ocpihdl simulate" is now deprecated and does nothing.

An example:

#### \$ ocpirun -C

Available containers:

#	Model	Platform	OS	OS-Version	Arch	Name
0	hdl	isim				lsim:isim
1	hdl	modelsim				lsim:modelsim
2	rcc	centos7	linux	c7	x86_64	rcc0

## E-II.2 HDL Width Adapters Not Required

One of the advantages of the new Scalable Data Plane is the Framework's automatic insertion of "width adapters" whenever needed between Workers in an Assembly. This means the user can remove any wsi\_16\_to\_32, wsi\_32\_to\_16, or wsi\_width\_adapter Components that are instantiated in their Assemblies or Applications. It is harmless to leave them in existing designs, but future Applications should not instantiate them.

## E-II.3 Platform Name Changes

To allow for more hardware and software separation in the future, there is now more distinction used in platform naming. Previously, the keyword "zed" was used to describe both software (the Xilinx-based Linux kernel) and hardware (the ZedBoard). This ambiguity led to confusion for some users and implied a nonexistent reliance on the ZedBoard. Starting with OpenCPI 1.1, the software platform for most Zynq-based hardware is labeled "xilinx13\_3", analogous to "centos7". The "13\_3" is shorthand for Xilinx's Linux release from the Third Quarter (Q3) of 2013. This means that previous code that used an OCPI\_TARGET\_PLATFORM of zed must now be changed to xilinx13\_3.

#### E-II.4 RCC Cross-compilation No Longer Uses OCPI\_CROSS\_HOST

Previous OpenCPI releases used OCPI\_CROSS\_HOST to define RCC cross-compilation. This required the usage of less-than-memorable values such as arm-xilinx-linux-gnueabi. The new manner is to use OCPI\_TARGET\_PLATFORM, RccPlatforms, or RccHdlPlatforms, which allow more intuitive and consistent values (See Section E-II.3). For example, the example above could be replaced with "OCPI\_TARGET\_PLATFORM=xilinx13\_3", "RccPlatforms=xilinx13\_3", or "RccHdlPlatforms=zed".

The RccPlatforms and RccHdlPlatforms variables allow the targeting of multiple platforms with a single make call. While either format can be used for Workers, ACI Applications can only be built for a single target platform using the OCPI\_TARGET\_PLATFORM variable.

# E-II.5 Updating a 1.0.x Unit Test for the 1.1 Framework

Some unit tests for Components were released with the 1.0.x version of ocpiassets that relied upon simulator availability or certain platform names reported by ocpirun (see Sections E-II.1 and E-II.3). If any users have developed their own unit tests based on these, some updates may be required for them to work using the new release.

All of the provided unit tests have been updated to work with the new release and can be used for reference. If the previous unit test is using ocpirun, the Makefile needs to be updated to add the following to any lines that are forming the execution string:

#### -P \$@=\$P

This is forcing the platform of your unit test to be set explicitly with ocpirun's -P option.

If the unit test is using an ACI Application to run the unit test, the platform needs to be set similarly within the C++ source. The Platform will be passed from the Makefile to the ACI Application as a command-line argument

<sup>&</sup>lt;sup>16</sup>Only version 14.7 without rebuilding the Base Project.

by adding \$P to the end of any execution strings. The source code needs to be updated to use this new argument by adding the following to the C++ application, while changing "XXX" to your Worker's name and "2" to the correct argument number based on your current inputs:

```
std::string pf("XXX=");
pf += argv[2];
OA::PValue params[] = {
    ...
OA::PVString("platform", pf.c_str()),
    ...
OA::PVEnd};
...
OA::Application app(appNameXml, params);
```

This patch is adding the platform that is passed in (via argv[2]) to the params array that is used to constrain the application's search space.

The user could do a full conversion to the new testing framework released with 1.1, but this is expected to be more work.

#### E-II.6 Prerequisite RPM Changes

The Open Source XZ Utils has replaced the LZMA Utils. This has caused the ANGRYVIPER-provided RPM to change names. Additionally, new RPMs are now provided for other prerequisite packages; consult the *Installation Guide* for a list. An upgrade to the new RPMs *should* cause previous versions to be removed, but the recommended procedure is to uninstall all 1.0.x RPMs before installing 1.1.

For the first time, OpenCPI is providing a pre-packaged third-party library that is not directly required by the Framework: liquid-dsp. This is provided to assist end users in the creation of DSP-heavy RCC Workers that execute on all currently-supported platforms without requiring any additional configuration for cross-compilation. It is treated like any other prerequisite library; usage information can be found in the *OpenCPI RCC Development Guide*.

#### E-II.7 Deprecated RCC controlOperations

The RCC controlOperations afterConfigure and beforeQuery have been deprecated and removed from the IDE. They were never called by the Framework and the C++ interface provides the finer-granularity XXX\_read() and XXX\_written() notification methods.

#### E-II.8 64-Bit Build Host Issues ("Value too large for defined data type")

Some 32-bit cross-compilers exhibit somewhat-rare problems on 64-bit host machines using file systems that allow 64-bit inodes, e.g. XFS. A new RPM, ocpi-rereq-build\_support-inode64, provides a workaround. Additional information can be found in the ANGRYVIPER-provided Picoflexor T6A documentation.

# E-III Major Known Deficiencies

This is a list of major known deficiencies at the release of 1.1 that were not previously documented in Section F. This is *not* an exhaustive list.

#### E-III.1 Maximum Message Length in PCI-Based Platforms

PCI-based platforms, e.g. ML605 and ALST4, are limited to a 32KB buffer. By default, that buffer is split into two, resulting in two 16KB buffers. The maximum message length, in bytes, is then 16KB-16<sup>17</sup>. RCC Workers will see any data beyond the limit as zero-filled.

<sup>&</sup>lt;sup>17</sup>16 bytes required for metadata

# E-III.2 MAC Address on ZedBoard

The currently used Linux release ("xilinx13\_3") cannot properly set the MAC address on the ZedBoard. This should only affect users who have more than one ZedBoard on a single network. Consult the ZedBoard Getting Started Guide for a workaround.

# E-III.3 Platform Development Guide

While all documentation is constantly under improvement, the *Platform Development Guide* in particular is currently undergoing major changes, in part due to the SDP improvements. If an end user intends to create a Board Support Package (BSP) for a new target platform, they should contact the ANGRYVIPER Team to ensure the latest Guide is used.

# F Release 1.0.1

These are "Release Notes" from Version 1.0.1 that are still relevant as of Version 1.1.

# F-I OpenCPI HDL Assembly Filename Constraint

Due to a limitation with the ISE Simulator (isim), the filename of any HDL Assembly must be all lowercase letters. A capital letter anywhere in the filename will result in an error.

#### F-II 32-bit Architecture File Size Limit

On some software platforms, there will be an error when writing files greater than 2<sup>31</sup> bytes (about 2.2 GB), especially if using NFS. This includes the ARM 32-bit architecture on Zyng-based platforms.

# F-III Eclipse Project Description File

A necessary file known as the project description file (.project) is generated when creating a Project in the ANGRYVIPER IDE. This file is required by Eclipse and is used to describe the project in its workspace. Removal of this file will cause an error.

# F-IV Refreshing the ANGRYVIPER IDE

Whenever files are being created or removed via command-line for an Project, the Project within the IDE needs to be refreshed. Examples include executing make clean, make tests, make rcc, etc. Many of the make commands will create or remove files in the Project, so it is important to refresh the Project within the IDE to reflect the changes.

#### F-V Non-default Xilinx Installation Locations

OpenCPI assumes Xilinx's installation location is /opt/. If the Xilinx tools were installed in another location, the cross compiling environment variable can not be inferred correctly. To resolve this issue, refer to the /opt/opencpi/cdk/env/xilinx.sh.example file and the *Installation Guide*.

# F-VI Zero-Length Message Finite State Machines

Some workers make use of a finite state machine to monitor a zero-length message (ZLM) from an upstream worker. This implementation was designed specifically with unit tests in mind so that simulations could be ended with an end-of-file (EOF) condition from the File Read Worker rather than waiting for a fixed amount of time. Simulation times vary across machines and Workers, so predicting how much time a Worker might need on various machines is not deterministic. In the future, the handling of zero-length message may change, but the current finite state machines for handling them are provided to complete the unit tests of the workers.