

Y axis in1 in2 in3 in4 Universal G-code Sender
 A₃ A₂ A₁ A₀ (ULN 2003)

X-axis in1 in2 in3 in4
 2 3 4 5

Z-axis in1 in2 in3 in4
 8 9 12 13

Machine Tab → setup Wizard
 Calibrate

Adjust Steps Per mm

100

100

50

Main GUI

Stepsize XY : 0.991

Z : 0.991

Feedrate : 15, 113

JS cut (all units in mm)

Tools

units ÷ mm

Diameter: 0.3 mm

Material

units ÷ mm

Thickness: 0.5

Gcode Conversion

Return to go at end ✓

inkscape settings

File → Document Properties

Custom Size Width : 7mm

Height : 7mm