Shepard Test Stand - Bug # 155: Research Whether or Not the 30 Foot Safety Radius For E Motors is Necessary

 Status:
 New
 Priority:
 High

 Author:
 Jeremy Wright
 Category:

 Created:
 08/01/2013
 Assignee:
 Jeremy Wright

 Updated:
 08/01/2013
 Due date:

Subject: Research Whether or Not the 30 Foot Safety Radius For E Motors is Necessary

Description

There has been discussion that the 30 foot safety radius for the E motors may be more about the increased risk of horizontal movement of a rocket with an E motor than the explosive force that can be generated by one. Research needs to be done, including contacting Estes and the NAR (National Association of Rocketry), to find out exactly why the radius for an E was chosen.

History

10/27/2022 1/1