

OPERATOR INTELLIGENCE

Your machines can't see what your best operator sees.

Six slides on turning what the floor knows into
measured, repeatable improvement.

01 • Capture

The signal that matters most is walking the floor.

Sensors log temperature, speed, output. They miss the context: the workaround, the near miss, the “it always does that on the night shift”. Your operators are the sensor for everything the machine can’t register.

02 • Connect

Machine data says what. Operators say why.

Put both on one timeline and the pattern shows up: the stop, and the reason behind it. That is where an improvement stops being a guess and becomes something you can prove.

03 • Execute

**One verified
improvement, repeated.**

€ 50–100k

Per line, per year, on deliberately conservative assumptions. Most plants run several lines across several sites, and the same method repeats on each. Illustrative, not a promise.

The path

Analyze. Prove. Scale.

Start on one line. Analyze what the floor already knows, prove a single improvement against the numbers, then scale the method to the next line and the next site. You know your payback before the proof starts.

See it on your own floor.

A short walk-through on your lines, with your numbers.
No rip-and-replace, no new hardware on day one.

oppr.ai