Report Generated by Test Manager

Title: Branch: 28-hexarotor-UTs-optimWIP

Author: Previous Commit Hash: 568728229669cb

0019de50f947fc78007f5c2cc9

Date: 22-Oct-2025 18:58:45

Test Environment

Platform: PCWIN64 MATLAB: (R2024a)

Summary - failed test results only

Name	Outcome	Duration (Seconds)
Results: 2025-Oct-22 18:58:04	10 🗷 2 🛭	37.714
hexarotor	4 🛭 1 😵	11.579
□ <u>Vehicle Tests</u>	4 🛭 1 😵	11.578
hexMotorModel	8	0.897
sensors sensors	3 🗷 1 🛭	9.789
Sensor Tests	3 2 1 8	9.79
sensors sensors	8	4.481
■ Iteration1	8	4.48

Results: 2025-Oct-22 18:58:04

Result Type: Result Set Parent: None

Start Time: 22-Oct-2025 18:58:06 End Time: 22-Oct-2025 18:58:44

Outcome: Total: 12, Passed: 10, Failed: 2

Back to Report Summary

hexarotor

Test Result Information

Result Type: Test File Result

Parent: <u>Results: 2025-Oct-22 18:58:04</u>

Start Time: 22-Oct-2025 18:58:06 End Time: 22-Oct-2025 18:58:18

Outcome: Total: 5, Passed: 4, Failed: 1

Test Suite Information

Name: hexarotor

Back to Report Summary

Vehicle Tests

Test Result Information

Result Type: Test Suite Result

Parent: <u>hexarotor</u>

Start Time: 22-Oct-2025 18:58:06 End Time: 22-Oct-2025 18:58:18

Outcome: Total: 5, Passed: 4, Failed: 1

Test Suite Information

Name: Vehicle Tests

Back to Report Summary

hexMotorModel

Test Result Information

Result Type: Test Case Result Parent: Vehicle Tests

Start Time: 22-Oct-2025 18:58:16 End Time: 22-Oct-2025 18:58:16

Outcome: Failed

Cause of Failure: Errors running test case

Test Case Information

Name: hexMotorModel Type: Baseline Test

Simulation

System Under Test Information

Model: hexMotorModel

Harness: hexMotorModelTestHarness

Harness Owner: hexMotorModel

Release: Current Simulation Mode: normal

Override SIL or PIL Mode: 0

Configuration Set: standardSILConfiguration

Test Sequence Block: hexMotorModelTestHarness/Test Sequence

Test Sequence Scenario: Scenario_1

Start Time: 0 Stop Time: 0

Simulation Logs:

No data is logged for the model 'hexMotorModelTestHarness'.

Simulation Error:

An error occurred ('Simulink:blocks:BlockConfiguredToExpectBus') when calling 'sim':

The Signal Conversion block 'hexMotorModelTestHarness/Input Conversion Subsystem/SigConv_6' cannot operate on a non-bus signal when it has been configured to expect a bus signal. Either create a bus signal by using a Bus Creator block or other bus capable block upstream, or set the Output parameter of the block to 'Signal copy' for non-bus signals.

Back to Report Summary

Test Logs:

No baseline criteria evaluation performed as no baseline data is available for this test.

Back to Report Summary

sensors

Test Result Information

Result Type: Test File Result

Parent: Results: 2025-Oct-22 18:58:04

Start Time: 22-Oct-2025 18:58:18 End Time: 22-Oct-2025 18:58:28

Outcome: Total: 4, Passed: 3, Failed: 1

Test Suite Information

Name: sensors

Back to Report Summary

Sensor Tests

Test Result Information

Result Type: Test Suite Result

Parent: <u>sensors</u>

Start Time: 22-Oct-2025 18:58:18 End Time: 22-Oct-2025 18:58:28

Outcome: Total: 4, Passed: 3, Failed: 1

Test Suite Information

Name: Sensor Tests

Back to Report Summary

sensors

Test Result Information

Result Type: Test Case Result Parent: Sensor Tests

Start Time: 22-Oct-2025 18:58:24 End Time: 22-Oct-2025 18:58:28

Outcome: Failed

Cause of Failure: Test failed as iteration failed

Test Case Information

Name: sensors

Type: Baseline Test

Iteration1

Test Result Information

Result Type: Test Iteration Result

Parent: <u>sensors</u>

Start Time: 22-Oct-2025 18:58:24

End Time: 22-Oct-2025 18:58:28

Outcome: Failed

Cause of Failure: Errors running test case

Test Case Information

Name: Iteration1
Type: Baseline Test

Iteration Settings

Test Overrides

Parameter Name	Value
TestSequenceScena	Scenario_1
rio	

Simulation

System Under Test Information

Model: sensors

Harness: sensorsTestHarness

Harness Owner: sensors
Release: Current
Simulation Mode: normal

Override SIL or PIL Mode: 0

Configuration Set: standardSILConfiguration

Test Sequence Block: sensorsTestHarness/Test Sequence

Test Sequence Scenario: Scenario_1

Start Time: 0 Stop Time: 0

Simulation Logs:

No data is logged for the model 'sensorsTestHarness'.

Simulation Error:

An error occurred ('Stateflow:translate:SFcnErrorStatus') when calling 'sim':

Errors occurred during parsing of 'Initialize'.

Back to Report Summary

Test Logs:

No baseline criteria evaluation performed as no baseline data is available for this test.

Back to Report Summary